389 Congress Street, 04101 Location of Construction:			Owner Address: MAY 3 200	Phone:					
Commercial St	Casco Bay Ga	Tage Assoc	Po Fox 7525 Dts	I HOME.					
Business Name:	Contractor Name		Contractor Address: PORTIAND Phone						
	Cianbro Corp.		328 W. Commercial Street Po	-7 11 10 []					
Lessee/Buyer's Name	Phone:		Permit Type:	Zone:					
			Alterations - Commercial	WPD					
Past Use:	Proposed Use:		Permit Fee: Cost of Worl	k: CEO District:					
Vacant	Office Space		\$0.00	0.00					
premius spA	u		FIRE DEPT: Approved Denied	Use Group: Type:					
Proposed Project Description:				- 1 00 /					
Tenant Fit Up for Office Space	e	<u></u>	Signature: PEDESTRIAN ACTIVITIES DIST	Signatur (P.A.D.)					
			Action: Approved App	roved w/Conditions Denied					
			Signature:	Date:					
Permit Taken By: jodinea	Date Applied For: 05/06/2002		Zoning Approva	l					
1. This permit application do	oes not preclude the	Special Zone or Review	Zoning Appeal	Historic Preservation					
Applicant(s) from meeting Federal Rules.	•	Shoreland Wetland Column Wetland Column Flood Zone	Variance	Not in District or Landmark					
Building permits do not in septic or electrical work.	clude plumbing,	Wetland County	Miscellaneous	Does Not Require Review					
3. Building permits are void within six (6) months of the	ne date of issuance.		☐ Conditional Use	Requires Review					
False information may inv permit and stop all work	alidate a building	Subdivision	Interpretation	Approved					
		Site Plan	Approved	Approved w/Conditions					
		Mai Minor MM M	Denied	Denied					
		Date: 3/14	Date:	Date:					
		,							
		CERTIFICATIO	N						
urisdiction. In addition, if a pe	wner to make this appli- rmit for work described	cation as his authorized a l in the application is issu	agent and I agree to conform to ued. I certify that the code office	by the owner of record and that of all applicable laws of this cial's authorized representative ion of the code(s) applicable to					
SIGNATURE OF APPLICANT		ADDRESS	DATE	PHONE					

DATE

PHONE

Application:	(CAlumber:	2.0489	4		one de transcription de la company	
age between de	Zoning	Siens /	pproved with Condition	ons Resissor	Marge Schmuck	(al
ommentes 4	0 Commercial St.			Approval Date	05/14/2002	
				Sign Of Pate	05/10/2002	
Z		Con Marge	Schmuckal	05/14/2002		
						7
				The state of the s		
This permit is	being approved on	the basis of pla	ns submitted. Any de	eviations shall require a	separate approval	
This permit is before starting	being approved on that work.			eviations shall require a	separate approval	
This permit is before starting	being approved on			eviations shall require a	separate approval	
This permit is before starting	being approved on that work.			eviations shall require a	separate approval	
This permit is before starting	being approved on that work.			eviations shall require a	separate approval	
This permit is before starting	being approved on that work.			eviations shall require a	separate approval	
This permit is before starting	being approved on that work.		gnage.			

02-0489

All Purpose Building Permit Application

If you or the property owner owes real estate or personal property taxes or user charges on any property within the City, payment arrangements must be made before permits of any kind are accepted.

<u> </u>				
Location/Address of Construction: 40	Comm	excial St		
Total Square Footage of Proposed Structu	ıre	Square Footage of Lot		
Existing 27,000		NA		
Tax Assessor's Chart, Block & Lot Chart# 444 (Block# A Lot# 5	Owner:	of Portland		Telephone:
Lessee/Buyer's Name (If Applicable)	telephone Scott B = 328 W.	name, address & atty-Ciauloro Corp. commercial st. l. ME 04102	W	e: \$ CITY
Current use: Vaccent		•		PRIJECT
If the location is currently vacant, what wo	as prior use:	Office		
Approximately how long has it been vacc	ınt: <u>6 /</u>	Months		
Proposed use: Office Project description: TENANT	FIT	UP-		
Contractor's name, address & telephone:				
Who should we contact when the permit Mailing address:	is ready: <u>S</u> abour	cott Beatty 553	·2	717
We will contact you by phone when the preview the requirements before starting and a \$100.00 fee if any work starts before	ny work, with	n a Plan Reviewer. A stop w	oick ork	up the permit and order will be issued
IF THE REQUIRED INFORMATION IS NOT INCL	LIDED IN THE	SURMISSIONS THE PERMIT WI	II R	E AUTOMATICALLY

IF THE REQUIRED INFORMATION IS NOT INCLUDED IN THE SUBMISSIONS THE PERMIT WILL BE AUTOMATICALLY DENIED AT THE DISCRETION OF THE BUILDING/PLANNING DEPARTMENT, WE MAY REQUIRE ADDITIONAL INFORMATION IN ORDER TO APROVE THIS PERMIT.

I hereby certify that I am the Owner of record of the named property, or that the owner of record authorizes the proposed work and that I have been authorized by the owner to make this application as his/her authorized agent. I agree to conform to all applicable laws of this jurisdiction. In addition, if a permit for work described in this application is issued, I certify that the Code Official's authorized representative shall have the authority to enter all areas covered by this permit at any reasonable hour to enforce the provisions of the codes applicable to this permit.

Signature of applicant:	Lott & Beats	A Date: 5/1/02	
	Y		


This is NOT a permit, you may not commence ANY work until the permit is insued.


If you are in a Historic District you may be subject to additional permitting and fees with the Planning Department on the 4th floor of City Hall.



L		OTAL SF = 27000, Common=13%-3500sf, City=9%-2200sf, Cianbro=78%-21,300 RENT CREDITS CI				CIANBRO				
			QT		TOT COST	*	VALUE	-	VALUE	Comments
49		ELEVATOR SILL ANGLES	2	EA	\$1,184	100%	\$1,184	T		Landings will require steel sill angles to ensure a level platform during elevator offloading.
50		PIT LADDER	1	EA	\$496	100%	\$496	6 0%		Elevator pit will receive a new steel ladder per code requirements
51	BI	PIT WATERPROOFING	1	BA	\$2,300	100%	\$2,300	0 0%		Apply cementitious waterproof coating at existing elevator pit as required
52	С	ELEVATOR RAIL SUPPORTS	2	EA	\$4,345	100%	\$4,345	5 0%		Existing shaft is larger than required for the new elevator, so new support steel across the opening so new support steel will be utilized for anchoring of the elevator
53	c	ELEVATOR HOIST BEAM	1	EA	\$1,515	100%	\$1,515	5 0%	\$0	
54	le l	ELEVATOR MACHINE RM	650		42 000					Recondition existing bathroom beside elevator into an elevator machine room per
55	ļ	DEMO IN ELEVATOR ROOM		LS	\$1,300	100%	\$1,300	 	1	12. Remove elevator steel structural supports and equipment to accommodate new
56	С	ELEVATOR DEMO		EA	\$5,000	100%	\$1,370		\$0	1
57	c	WALLS AT ELEV DOORS		EA						New passenger elevator will require smaller doors. The existing be will infilled areas
		MECHANICAL	ئىسىد ئىسىد	EA	\$400	100%	\$400	0%	\$0	W accommodate the new elevator goos frames.
58		FIRE PROTECTION	1	LS	\$49,950	100%	\$49,950	0%	\$0	
59	ві	HVAC - OFFICE	9	EA	\$116,500	100%	\$116,500	0%	\$0	Five existing roof top cooling units and four (4) existing evaporative cooling units servicing the Office area will be disconnected and removed. Nine (9) new Carrier packaged gas/electric air conditioning units will be installed at the roof vvaranouse area will have gas piping run to support two temporary gas fired heaters
60	SH	HVAC - WAREHOUSE	2	EA	\$18,550	100%	\$18,550	0%	\$0	
	1440	BLECTRICAL			HINESET	1.00	unggara, in	olescommune.	Y -	
61	BI	Roof repair misc elect		LS	\$368	100%	\$368	0%		Misc roof electrical disconnects for electrical equipment
								1		
62	BI	Elect for roof HVAC units	1	LS	\$2,137	100%	\$2,137	0%	\$0	Disconnect roof HVAC units. Repower new roof HVAC units.
63		Domo, phone manage			1 . 1					Disconnect and Demo roof run shore power conduits and cables
64		Demo shore power Demo existing elevator and feed		LS	\$5,614	100%	\$5,614	0%	\$0	from source to shore power before it goes under dock.
65		New elevator power feed		LS	\$2,802 \$5,032	100%	\$2,802	0%		Demo existing Elevator power back to source.
66		New elevator fire alarm		LS	\$1,096	100%	\$5,032 \$1,096	0%		Install new elevator power feed.
67	C	New elevator tel lines		EA	\$398	100%	\$398	0%		Install new elevator fire detection Install new elevator phone lines
68	SK	Data lines - 10 fiber per 8 location		LS	\$3,982	22%	\$876	78%	:	Reconnect/terminate and test fiber to data closets on second floor, and to remote locations at remote dock. 10 fibers at each location.
69	BI	Clean light fixtures on first floor	70	EA	\$1,044	100%	\$1,044	0%	śo	Clean all light fixtures on the first floor, no repair or relamping included. Assume cleaning will meet osha requirements for light
										Clean and re-lamp existing light fixtures on the second floor to meet osha lighting requirements. Old lamps will be
70		Clean / relamp fixtures on 2nd floor	375	EA	\$9,103	100%	\$9,103	0%	\$0	turned over to the city.
71	SH	Light fixtures repair & replace	300	EA	\$19,672	40%	\$7,869	60%	\$11,803	Fix or replace broken fixtures on second and first floors.
72		Add battery packs 120/12v	14	EA	\$3,348	100%	\$3,348	0%	so	Add additional battery packs as required to illuminate exit routes
73	С	Add exit signs 120v	7	EA	\$1,255	100%	\$1,255	0%		Add exit signs as required for exit routes.
74	_	Move existing battery packs	7	_	\$1,287	100%	\$1,287	04	\$0	Move existing battery packs to illuminate exit routes
75	۲	Move exit signs	5	EA	\$746	100%	\$746	04	\$0	Move existing exit signs to illuminate exit routes
76		Modify existing fire alarm panel	1		\$6,348	100%	\$6,348	0%		Modify existing new fire alarm panel to connect / test additional points.
77 0	پ	Fire alarm horn/lt	15	EA	\$6,358	100%	\$6,358	0%	\$0	Add additional fire horn light units
78	С	Fire alarm pull stations	6	ıs	\$2,543	100%	\$2,543	0 %		Add additional fire alarm pull stations on the second floor.
79	SH .	Add 120v power panel on 2nd flr	1	s	\$3,782	22%	\$832	78%	\$2,950	Add an additional panel to handle additional 120v receptacles on the second floor.
					\$636,939		\$538,109		\$98,830	
A		GENERAL CONDITIONS	1		400					
В		PERSONEL OH COSTS		+	\$22,387	85%	\$18,917	15%	\$3,466	Design costs,plans, clean up, trash removal, permits
c		CREW SUPPORT COSTS		+	\$12,574	85%	\$34,256 \$10,625	15%		COST OF SUPERVISORY PERSONEL
D		QUIPMENT		+	\$3,221	85%	\$2,721	15%		TOOLS, PER DIEM, SAFETY & INSURANCE COSTS CONSTRUCTION EQUIPMENT, FORKLIFTS ETC.
E		CORPORATE OVERHEAD		╛	\$53,675	85%	\$45,355	15%		COST OF EXISTANCE
+		TOTAL COST OF RENOVATIONS		7	4000					
		TODE OF KENOVALIONS			\$769,334		\$649,983		\$119,325	

Ľ		THYST PROJECT - OFFICE R								T
1	ME									18-Apr-(
H	+	101AL SE = 27000, Common=138-3500st. City-98-	CAL SF = 27000, Common=134-3500sf, City-94-2200sf, Ciambro-784-21,300 RENT CREDITS CIAMBRO OTY TOT COST % VALUE % VALUE							
					101 0081	+-	VALUE	+*	VALUE	Comments One sign for city. New signage to identify Clandro work areas including the Guard
1	SH			6 EA	\$3,048	164	\$48	84%	\$2,560	House, main building and directional signs for other work areas
		DEMOLITION			100					SURFACE OF SECURISION SECURISION
2	ві	REMOVE SHORE POWER CONDUITS ON ROOF	1	1 Ls	\$571	100%	\$57	L 0%	60	Remove t existing electrical conduits previously used for shore power at roof edge which conflicts with the installation of the new roof system
Γ.				+	1	1	337.	-	***	Remove all hollow core wood doors, frames and associated hardware as the existing
3	C	REMOVE HOLLOW CORE DOORS		4 EA	\$228	100%	\$22	0%	\$0	doors do not meet code requirements
4	SH	MISCELLANEOUS DEMO		0 EA	61 140	200				Miscellaneous demoition as required for penetrations, electrical and mechanical
5	SH			O LF	\$1,142	90%	\$25	78%	\$891	Communication to the state of t
6	SH	PARTIAL LIGHT REMOVAL		0 EA	\$571	22%			\$171	- December
				+	1	† 	7100	70.	2443	Remove existing telephone, voice and data, fire alarm and electrical lines above
7	C	TERMINATE ELECTRICAL		1 LS	\$7,138	100%	\$7,138	0%	\$0	ceiling that are not functioning
B 9	BI			0 LS	\$0	100%	\$0		\$0	
ŕ	 -	CARPET	900	0 SY	\$4,283	100%	\$4,283	0%	\$0	
10	ВІ	REMOVE ROOF UNITS		9 EA	\$571	100%	\$571	. 0%	\$0	Remove existing roof top units and exhaust fans to accommodate new heating system
				1				 		Remove existing temporary wood office spaces at Warehouse area which conflict
12	T	REMOVE WOOD OFFICES 1ST		1 EA	\$1,142	0%	\$0	100%	\$1,142	with warehouse operations
	BI	REMOVE SKYLIGHT PLUMBING DEMO	1	1 EA	\$457	100%	\$457	0%	\$0	Remove existing glass skylight which appears to leak and is not in service below
-		THE PERCONSTRUCTION OF	<u> </u>	2 EA	\$685	100%	\$685	0%	\$0	Remove plumbing fixtures and piping including existing showers, sinks, tollets, etc.
14	SH	TRASH CHUTE	:	1 EA	\$1,236	21%	\$260	79%	\$976	Install trash chutes to remove debris from second floor to dumpsters located below
15	SH	TRASH CARTS	7	2 EA	\$117	21%	\$25		\$92	Provide trash carts to assist with removal of debris
16	SH	MISCELLANEOUS MAT								Provide miscellaneous materials such as scaffolding to support the trash chutes,
17			3.50		\$2,826	21%	\$593	79%	\$2,232	ventilation to zerate the space during demolition, etc
		WARHOUSE		LF	\$1,000	100%	\$1,000	0%	\$0	Apply pavement markings to delineate Claribro space from City areas
		· · · · · · · · · · · · · · · · · · ·	7		11200		AFG-			Barricades to protect cruiseship passengers from warehouse intersection - City
18	-	TRAFFIC BARRICADES	10	EA	\$3,784	50%	\$1,892	50%	\$1,892	would like to keep theirs when complete
19		DOCK PLATE	1	LEA	\$1,171	0%	\$0	100%	\$1,171	For warehouse opperations
20 21		ROLLING STAIRS WEIGHT SCALE		EA	\$1,671	0%	\$0	100%	\$1,671	For warehouse opperations
22		SAFETY MIRRORS		BA	\$3,614	04	\$0	100%	\$3,614	For Warehouse opperations
		STERL		EA	\$428	0%	\$0	100%	\$428	For warehouse opperations
23	BI	MISC SUPPORTS	4	EA	\$1,642	100%	\$1,642	0%	\$0	Miscelaneous supports for stairs, ceilings and wats
24	BI	MISC ROOF SUPPORTS	4	EA	\$2,713	100%	\$2,713	0%	\$0	Steel support for roof top units
		CARPENTRY	1,411			100	FISHER.	1884		COART SPECIAL CONTRACTOR CONTRACT
25	۲.	ADA ACCESS	Ī							Wood infill framing for existing 12-0 x20-0 overhead door to meet elevator code
26		DOOR BUCKS		LF	\$857	100%	\$857	0%	\$0	requirements
27		MISC BLOCKING		LF	\$731 \$710	100%	\$731 \$710	0%	\$0	Wood door nailers to allow anchoring of new hollow metal door frames
28	т	CABINETRY							ė n i	
			10	LF	\$714	0%		100%	\$0 \$714	Miscellaneous wood blocking for cabinets, temporary supports, railings, etc. New cabinets and countertops for coffee break stations
		MOISTURE PROTECTION	10	LF	\$714		\$710 \$0	100%	\$0 \$714	misceraneous wood blocking for cabinets, temporary supports, raillings, etc. New cabinets and counterlops for coffee break stations
29		MOISTURE PROTECTION	10	LF	\$714 -				\$714	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7* of polylsocyanurate insulation for
_	ві	BPDM ROOFING - OFFICE			en mar ia.	0%	\$0 **** ********************************	100%	\$71 4	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7° of polylsocyanurate insulation for a R-20 rating and apply a fully achieval EPDM roof membrane at existing Office.
	ві		27000		\$714 \$80,100				\$714 \$706 \$0	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylsocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warrarty.
30	ві	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF		SF	en mar ia.	0%	\$0 **** ********************************	100%	\$714	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7° of polylsocyanurate insulation for a R-20 rating and apply a fully achieval EPDM roof membrane at existing Office.
30 31	ві	EPDM ROOFING - OFFICE	27000	SF SF	\$80,100	0%	\$0 \$80,100	100% Minitian	\$714 \$0 \$0 \$0	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylisocyanurate insulation for a re-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing leaks Flashing for columns projecting through roof.
	BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF	27000 84150 72	SF SF EA	\$80,100 \$75,000 \$4,111	100%	\$80,100 \$75,000 \$4,111	100% ***********************************	\$714 \$0 \$0 \$0	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylsocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warrardy. Existing Warehouse lower roof will have a patching contingency allowance to repair existing leaks Plashing for columns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof stress.
31	BI BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF	27000 84150 72	SF SF EA	\$80,100 \$75,000 \$4,111 \$2,928	100% 100% 100% 100%	\$80,100 \$75,000 \$4,111 \$2,928	0% 0% 0%	\$714 \$0 \$0 \$0 \$0	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylsocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing leaks Flashing for columns projecting through roof. Provide miscelaneous roof askings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system
31	BI BI BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING	27000 84150 72 1	SF SF EA	\$80,100 \$75,000 \$4,111	100%	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600	0% 0% 0% 0%	\$714 \$0 \$0 \$0 \$0 \$0 \$0	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylsocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing leaks Flashing for columns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof elevation.
31 32 33	BI BI BI BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS	27000 84150 72 1 8	SF SF EA EA	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600	100% 100% 100% 100% 100%	\$80,100 \$75,000 \$4,111 \$2,928	0% 0% 0%	\$714 \$0 \$0 \$0 \$0 \$0 \$0	New cabinets and countertops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylsocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing leaks Flashing for columns projecting through roof. Provide miscelaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof elevation. Patch roof deck at existing skylight and apply roof membrane.
31 32 33 34	BI BI BI BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK	27000 84150 72 1 8	SF SF EA EA EA	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092	100% 100% 100% 100% 100%	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092	0% 0% 0% 0% 0% 0%	\$714 \$0 \$0 \$0 \$0 \$0 \$0	New cabinets and countertops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylsocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patiching contingericy allowance to repair existing leaks Flashing for columns projecting through roof. Provide miscelaneous roof askings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof elevation.
31 32 33 34 35	BI BI BI BI BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE	27000 84150 72 1 8 3 1	SF SF EA EA EA	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428	100% 100% 100% 100% 100% 100% 100%	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428	0% 0% 0% 0% 0%	\$714 \$0 \$0 \$0 \$0 \$0 \$0 \$0	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylsocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency attowance to repair existing leaks Flashing for columns projecting through roof. Flashing for columns projecting through roof, provide miscalaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to mest the new roof elevation. Patch roof deck at existing skylight and apply roof membrane. Provide new metal siding to match existing material at infilled overhead door.
31 32 33 34 35	BI BI BI BI BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS	27000 84150 72 1 8 3 1	SF SF EA EA EA LS	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428	100% 100% 100% 100% 100% 100%	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428	0% 0% 0% 0% 0% 0%	\$714 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylsocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warrantly. Existing Warehouse lower roof will have a patching contingency allowance to repair existing leaks Flashing for columns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof elevation. Provide new metal siding to match existing material at infilled overhead door. Replace existing door hardware to meet code and add 4ea common area doors
31 32 33 34 35	BI BI BI BI BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE	27000 84150 72 1 8 3 1 1	SF SF EA EA EA LS	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000	100% 100% 100% 100% 100% 100% 100%	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428	0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 %	\$714 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylsocyanurate insulation for a R-20 rating and apply a filty adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing leaks Flashing for columns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to mest the new roof elevation Patch roof deck at existing skylight and apply roof membrane Provide new metal stding to match existing material at infilled overhead door Replace existing door hardware to meet code and add 4ea
31 32 33 34 35 36 37	BI BI BI BI BI BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS FATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS FINISHES	27000 84150 72 1 8 3 1 1	SF SF EA EA EA LS	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428	100% 100% 100% 100% 100% 100%	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428	0% 0% 0% 0% 0% 0%	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7° of polylsocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warrandy. Existing Warehouse lower roof will have a patching contingency allowance to repair existing the contingency allowance to repair existing the contingency allowance to repair existing for columns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof elevation. Patch roof deck at existing skylight and apply roof membrane. Provide new metal stoing to match existing material at infined overhead door. Replace existing door hardware to meet code and add 4ea common area doors. Maintenance and repairs for 6 Over Head doors.
31 32 33 34 35	BI BI BI BI BI BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS	27000 84150 72 1 8 3 1 1	SF SF EA EA EA EA EA EA EA	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000	100% 100% 100% 100% 100% 100%	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428	0% 0% 0% 0% 0% 0%	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylsocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing leaks Flashing for columns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof elevation Patch roof deck at existing skylight and apply roof membrane Provide new metal siding to match existing material at inflined overhead door Replace existing door hardware to meet code and add 4ea common area doors Maintenance and repairs for 6 Over Head doors Maintenance and repairs for 6 Over Head doors
31 32 33 34 35 36 37	BI BI BI BI BI BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS FINISHES GYPSUM DRYWALL	27000 84150 72 1 8 3 1 62 6	SF SF EA EA EA LS	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000	100% 100% 100% 100% 100% 100% 100% 100%	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000	0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 %	\$714 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7° of polylsocyanurate insulation for a first order of the polylsocyanurate insulation for a first order of a first order of the polylsocyanurate insulation for a first order or
31 32 33 34 35 36 37	BI BI BI BI BI BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS FINISHES	27000 84150 72 1 8 3 1	SF SF EA EA EA LS	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000	100% 100% 100% 100% 100% 100% 100%	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000	0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 %	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7° of polylsocyanurate insulation for a Repove excess gravel surface coating, apply 2.7° of polylsocyanurate insulation for a Re-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warrandy. Existing Warehouse lower roof will have a patching contingency allowance to repair existing the contingency allowance to repair existing the proof of the contingency allowance to repair existing for columns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof elevation patch roof deck at existing skylight and apply roof membrane Provide new metal sloing to match existing material at infilled overhead door Replace existing door hardware to meet code and add 4ea common area doors Maintenance and repairs for 6 Over Head doors Maintenance and repairs for 6 Over Head doors Install new interior wall partitions consisting of 3-5/8° thick steel stude and a layer of 5/8° type X gypsum drywall on both sides to accommodate the new wall layout Patch existing gypsum drywall was partitions adjacent to disturbed work areas with old compound and/or drywall was partitions adjacent to disturbed work areas with old compound and/or drywall was partitions adjacent to disturbed work areas with old compound and/or drywall was partitions and the state of the s
31 32 33 34 335 336 337 338 338	BI BI BI BI BI BI BI BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS FINISHES GYPSUM DRYWALL PATCH EXISTING WALLS ACOUSTICAL CEILINGS	27000 84150 72 1 8 3 1 1 62 6	SF SF EA EA EA LS	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000	100% 100% 100% 100% 100% 100% 100% 100%	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000	0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 %	\$714 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7° of polylsocyanurate insulation for a first order of the polylsocyanurate insulation for a first order of a first order of the polylsocyanurate insulation for a first order or
31 32 33 34 335 336 337 338 339	BI B	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS PINISHES GYPSUM DRYWALL PATCH EXISTING WALLS ACOUSTICAL CEILINGS CARPETING	27000 84150 72 1 8 3 1 1 62 6 1080 500 27000	SF EA EA EA LS EA EA	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,780 \$325	100% 100% 100% 100% 100% 100% 100% 100%	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000	0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	New cabinets and countertops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylscoyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patiching contingency allowance to repair existing leaks Flashing for columns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof elevation patich roof deck at existing skylight and apply roof membrane Provide new metal siding to match existing material at infilled overhead door Replace existing door hardware to meet code and add 4ea common area doors Maintenance and repairs for 6 over Head doors metal new interior wall partitions consisting of 3-0/8" thick steel studs and a layer of 5/8" type X gypsum drywall on both sides to accommodate the new wall layout ratio accompound and/or drywall was partitions adjacent to disturbed work areas with only compound and/or drywall was partitions adjacent to disturbed work areas with only country and provide replacement tiles
31 32 33 34 335 336 337 338 338	BI B	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS FINISHES GYPSUM DRYWALL PATCH EXISTING WALLS ACOUSTICAL CEILINGS	27000 84150 72 1 8 3 1 1 62 6 1080 500 27000 2889	SF SF EA EA EA LS EA EA SF SF	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,780 \$325	100* 100* 100* 100* 100* 100* 100* 100*	\$1,130 \$1,100 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$13,000 \$3,402 \$325 \$4,139	04 04 04 04 04 04 04 04 04	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	New cabinets and countertops for coffee break stations Remove excess gravel surface coating, apply 2.7° of polylsocyanurate insulation for a fire 20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing Warehouse lower roof will have a patching contingency allowance to repair existing Warehouse lower roof will have a patching contingency allowance to repair existing for collumns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof edges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof elevation Patch roof deck at existing skylight and apply roof membrane Provide new metal sliding to match existing material at infined overhead door Replace existing door hardware to meet code and add 4ea common area doors Maintenance and repairs for 6 Over Head doors Mai
31 32 33 34 35 36 37 38 38 39 10 11	BI BI BI BI BI BI BI BI BI T	EFDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS FINISHES GYPSUM DRYWALL PATCH EXISTING WALLS ACOUSTICAL CEILINGS CARPETING CARPET VINYL BASE	27000 84150 72 1 8 3 1 1 62 6 1080 500 27000 2889 4500	SF SF EA EA EA LS EA SF SF SF SY LF	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,780 \$325 \$19,710 \$25,163 \$4,500	100% 100% 100% 100% 100% 100% 100% 100%	\$11,130 \$3,402 \$4,139 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,402 \$325 \$4,139 \$5,284 \$945	04 04 04 04 04 04 04 04 04 794	\$714 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$15,571 \$19,879 \$3,555	New cabinets and countertops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylisocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing leaks Plashing for collumns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof elevation Patch roof deck at existing skylight and apply roof membrane Provide new metal siding to match existing material at infined overhead door Replace existing door hardware to meet code and add 4ea common area doors Maintenance and repairs for 6 Over Head doors Install new Interior wall partitions consisting of 3-5/8" thick steel stude and a layer of 5/8" type X gypsum drywall on both sides to accommodate the new wall layout patch existing grayeum drywall wallboard on the sides to accommodate the new wall layout point compound and/or drywall wallboard free placement tiles. Remove existing ceiling tiles and 6" fiberplass insulation above ceiling, provide minor pitel reworking, support and provide replacement tiles.
31 32 33 34 335 336 337 338 339	BI BI BI BI BI BI BI BI BI T	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS PINISHES GYPSUM DRYWALL PATCH EXISTING WALLS ACOUSTICAL CEILINGS CARPETING	27000 84150 72 1 8 3 1 1 62 6 1080 500 27000 2889	SF SF EA EA EA LS EA SF SF SF SY LF	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,780 \$325 \$19,710 \$25,163	100% 100% 100% 100% 100% 100% 100% 100%	\$1,100 \$1,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,402 \$325 \$4,139 \$5,284	04 04 04 04 04 04 04 04 04 04 04 04 04	\$714 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	New cabinets and countertops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylsocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing leaks Flashing for columns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof elevation. Patch roof deck at existing skylight and apply roof membrane Provide new metal siding to match existing material at infilled overhead door. Replace existing door hardware to meet code and add 4ea common area doors Maintenance and repairs for 6 Over Head doors Maintenance and repairs for 6 Over Head doors As a substing system drywall on both sides to accommodate the new wall layout for the compound and/or drywall wallboard. Remove existing ceiling tiles and 6" fiberglass linsulation above ceiling, provide minor pid reworking, support and provide replacement bles Provide direct gue carpeting at all areas except pathroom locations Provide viny wall base at all intentor wall partitions Provide viny replacement tile to infill missing and damaged tile areas and provide niscellaneous floor patching as required to allow proper carpet installation
31 32 33 33 34 35 36 37 38 38 39 110 111 112 113 113	BI BI BI BI BI BI BI BI BI T T BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS FINISHES GYPSUM DRYWALL PATCH EXISTING WALLS ACOUSTICAL CEILINGS CARPETING CARPET VINYL BASE FLOOR PATCHING	27000 84150 72 1 8 3 1 1 62 6 1080 500 27000 2889 4500	SF SF EA EA EA LS EA SF SF SF SY LF	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,780 \$325 \$19,710 \$25,163 \$4,500	100% 100% 100% 100% 100% 100% 100% 100%	\$11,130 \$3,402 \$4,139 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,402 \$325 \$4,139 \$5,284 \$945	04 04 04 04 04 04 04 04 04 794	\$714 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	New cabinets and countertops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polyisocyanurate insulation for a Remove excess gravel surface coating, apply 2.7" of polyisocyanurate insulation for a Re-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing warehouse lower roof will have a patching contingency allowance to repair existing for columns projecting through roof. Provide miscelanaeous roof flashings at mechanical equipment curbs and roof edges, etc. to complete the EPDM system Rework existing for drains above office to meet the new roof elevation Patch roof deck at existing skylight and apply roof membrane Provide new metal siding to match existing material at infilled overhead door Replace existing door hardware to meet code and add 4ea common area doors Maintenance and repairs for 6 Over Head doors Maintenance and repairs for 6 Over Head doors Patch existing gypsum drywal war partitions adjacent to disturbed work areas with oint compound and/or drywall war partitions adjacent to disturbed work areas with oint compound and/or drywall war partitions adjacent to disturbed work areas with oint compound and/or drywall war partitions adjacent to disturbed work areas with oint compound and/or drywall war partitions and a flashing and atmospherity at at areas except bathroom locations Provide direct give carpeting at at areas except bathroom locations Provide direct give carpeting at at areas except bathroom locations Provide of the drywall war partitions are except bathroom locations Provide in the virging and develope areas and provide inscellaneous floor patching as required to allow proper carpet installation
31 32 33 34 35 36 37 38 38 39 10 11	BI BI BI BI BI BI BI BI BI T T BI	EFDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS FINISHES GYPSUM DRYWALL PATCH EXISTING WALLS ACOUSTICAL CEILINGS CARPETING CARPET VINYL BASE	27000 84150 72 1 8 3 1 1 62 6 1080 500 27000 2889 4500	SF EA EA EA LS SF SF SF SF SY LF	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,780 \$325 \$19,710 \$25,163 \$4,500	100% 100% 100% 100% 100% 100% 100% 100%	\$11,130 \$3,402 \$4,139 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,402 \$325 \$4,139 \$5,284 \$945	04 04 04 04 04 04 04 04 04 794	\$714 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$15,571 \$19,879 \$3,555 \$0	New cabinets and countertops for confee break stations Remove excess gravel surface coating, apply 2.7" of polylisocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing leaks Plashing for collumns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof elevation Patch roof deck at existing skylight and apply roof membrane Provide new metal siding to match existing material at infilled overhead door Replace existing door hardware to meet code and add 4ea common area doors Maintenance and repairs for 6 Over Head doors Maintenance and repairs for 6 Over Head doors Patch adding anyound repairs for 6 over Head doors Patch adding gypsum drywal on both sides to accommodate the new wall layout reach adding gypsum drywal wall partitions adjacent to disturbed work areas with oint compound and/or drywal wall partitions adjacent to disturbed work areas with oint compound and/or drywal wall partitions adjacent to disturbed work areas with oint compound and/or drywal wall base at all interior will partitions. Provide direct glue carpeting at all areas except batthroom locations provide replacement tiles to infill missing and damaged tile areas and provide riscellaneous floor patching as required to allow proper carpet installation. Patch and several adding as required to allow proper carpet installation allow on with high build acrylic floor coating at Office areas.
31 32 33 34 35 36 37 36 37 38 38 39 10 11 12 11 12 11 13 11	BI BI BI BI BI BI BI T T BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS FINISHES GYPSUM DRYWALL PATCH EXISTING WALLS ACOUSTICAL CEILINGS CARPETING CARPET VINYL BASE FLOOR PATCHING	27000 84150 72 1 8 3 1 1 62 6 6 27000 2889 4500 350	SF EA EA LS SF SF SY LF SF	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,780 \$3,780 \$325 \$19,710 \$25,163 \$4,500 \$3,500	100* 100* 100* 100* 100* 100* 100* 100*	\$11,130 \$3,402 \$4,139 \$1,600 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,402 \$325 \$4,139 \$5,284 \$945 \$3,500	04 04 04 04 04 04 04 04 04 04 04 794 794 794	\$714 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	New cabinets and countertops for coffee break stations Remove excess gravel surface coating, apply 2.7° of polylisocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warrarty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing leaks Flashing for columns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof elevation patch roof deck at existing skyight and apply roof membrane Provide new metal siding to match existing material at infilled overhead door Replace existing door hardware to meet code and add 4ea common area doors Maintenance and repairs for 6 over Head doors Maintenance and repairs wall partitions adjacent to disturbed work areas with old compound and/or drywall wallboard Temove existing ceiling ties and of fleergass insulation above ceiling, provide minor grid reworking, support and provide replacement tiles Provide new Whyt wat base at at interior wall partitions Provide new Whyt wat base at at interior wall partitions Provide new Whyt wat base at at interior wall partitions Maintenance and part partitions and paint existing restroom locus with high build acrylic floor coating at Office areas. Maintenance and repairs at all warehouse
31 32 33 33 34 35 36 37 38 38 39 110 111 112 113 113	BI BI BI BI BI BI BI T T BI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS FINISHES GYPSUM DRYWALL PATCH EXISTING WALLS ACOUSTICAL CEILINGS CARPETING CARPET VINYL BASE FLOOR PATCHING PAINTING CLEAN & PAINT WAREHOUSE RMS	27000 84150 72 1 88 3 1 62 6 1080 500 27000 2889 4500 350 60000 15000	SF EA EA LS SF SF SY LF SF	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,780 \$325 \$19,710 \$25,163 \$4,500 \$3,500 \$19,200 \$7,500	100% 100% 100% 100% 100% 100% 100% 100% 100% 100% 100% 100% 100% 100%	\$11,130 \$3,402 \$4,139 \$1,600 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,402 \$325 \$4,139 \$5,284 \$945 \$3,500	04 04 04 04 04 04 04 04 04 04 04 04 04 0	\$714 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	New cabinets and countertops for coffee break stations Remove excess gravel surface coating, apply 2.7° of polylisocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warrarty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing leaks Flashing for columns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof elevation patch roof deck at existing skyight and apply roof membrane Provide new metal siding to match existing material at infilled overhead door Replace existing door hardware to meet code and add 4ea common area doors Maintenance and repairs for 6 over Head doors Maintenance and repairs wall partitions adjacent to disturbed work areas with old compound and/or drywall wallboard Temove existing ceiling ties and of fleergass insulation above ceiling, provide minor grid reworking, support and provide replacement tiles Provide new Whyt wat base at at interior wall partitions Provide new Whyt wat base at at interior wall partitions Provide new Whyt wat base at at interior wall partitions Maintenance and part partitions and paint existing restroom locus with high build acrylic floor coating at Office areas. Maintenance and repairs at all warehouse
31 32 33 33 34 35 36 37 38 38 39 10 11 12 55 2	BI BI BI BI BI BI BI T T F	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS FINISHES GYPSUM DRYWALL PATCH EXISTING WALLS ACOUSTICAL CEILINGS CARPETING CARPET VINYL BASE FLOOR PATCHING PAINTING CLEAN & PAINT WAREHOUSE RMS SPECIALTIES	27000 84150 72 1 8 3 1 1 62 6 6 27000 2889 4500 350	SF EA EA LS SF SF SY LF SF	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,780 \$3,780 \$325 \$19,710 \$25,163 \$4,500 \$3,500	100* 100* 100* 100* 100* 100* 100* 100*	\$11,130 \$3,402 \$4,139 \$1,600 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,402 \$325 \$4,139 \$5,284 \$945 \$3,500	04 04 04 04 04 04 04 04 04 04 04 794 794 794	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	New cabinets and countertops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylisocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warrarty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing to the property of the patching of the property o
31 32 33 34 35 36 37 36 37 38 38 39 10 11 12 11 12 11 13 11	BI BI BI BI BI BI BI BI BI F	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS FINISHES GYPSUM DRYWALL PATCH EXISTING WALLS ACOUSTICAL CEILINGS CARPETING CARPET VINYL BASE FLOOR PATCHING PAINTING CLEAN & PAINT WAREHOUSE RMS SPECIALTIES MISC MIRRORS & FIRE EXT.	27000 84150 72 1 88 3 1 62 6 1080 500 27000 2889 4500 350 60000 15000	SF EA EA EA LS EA EA SF SF SF SF SF SF SF	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,780 \$325 \$19,710 \$25,163 \$4,500 \$3,500 \$19,200 \$7,500	100* 100* 100* 100* 100* 100* 100* 100*	\$11,130 \$3,402 \$4,139 \$1,600 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,402 \$325 \$4,139 \$5,284 \$945 \$3,500	04 04 04 04 04 04 04 04 04 04 04 794 794 794	\$714 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7" of polylsocyanurate insulation for a Report of gravel surface coating, apply 2.7" of polylsocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patiching contingency allowance to repair existing leaks Flashing for columns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof elevation Patich roof deck at existing skylight and apply roof membrane Provide new metal siding to match existing material at infilled overhead door Replace existing door hardware to meet code and add 4ea common area doors Maintenance and repairs for 6 over Head doors Maintenance and repairs for 6 over Head doors metal new interior wall partitions consisting of 3-5/8" thick steel studs and a layer of 5/8" type X gypsum drywall on both sides to accommodate the new wall layout Temove existing ceiling tiles and 6" hierglass insulation above ceiling, provide minor grid reworking, support and provide replacement tiles Provide new viny wall base at at interior wall partitions Provide new viny wall base at at interior wall partitions Provide new viny wall base at a tile for mile missing and damaged tile areas and provide resocial and our for patiching as required to allow proper carpet installation Paint all existing and new wall surfaces with two coats of acrylic eggshel finish, paint all existing and removary offices and coffice areas. Asan and paint existing temoorary offices and comfirence areas at Warehouse.
31 32 33 33 34 35 36 37 38 38 39 10 11 12 55 2	BI BI BI BI BI BI BI BI BI F	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS FINISHES GYPSUM DRYWALL PATCH EXISTING WALLS ACOUSTICAL CEILINGS CARPETING CARPET VINYL BASE FLOOR PATCHING PAINTING CLEAN & PAINT WAREHOUSE RMS SPECIALTIES	27000 84150 72 1 8 3 1 1 62 6 1080 500 27000 2889 4500 350 60000	SF EA EA EA LS EA EA SF SF SF SF SF SF SF	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,780 \$325 \$19,710 \$25,163 \$4,500 \$3,500 \$19,200 \$7,500	100% 100% 100% 100% 100% 100% 100% 100%	\$11,130 \$3,402 \$4,139 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,402 \$325 \$4,139 \$5,284 \$945 \$3,500	04 04 04 04 04 04 04 04 04 104 794 794 794	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7° of polylsocyanurate insulation for a first part of the polylsocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing the part of th
31 32 33 33 34 35 36 37 38 38 39 10 11 12 55 2	BI BI BI BI BI BI BI T T	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS FINISHES GYPSUM DRYWALL PATCH EXISTING WALLS ACOUSTICAL CEILINGS CARPETING CARPET VINYL BASE FLOOR PATCHING PAINTING CLEAN & PAINT WAREHOUSE RMS SPECIALTIES MISC MIRRORS & FIRE EXT.	27000 84150 72 1 8 3 1 62 6 1080 500 27000 2889 4500 350 60000 15000	SF EA EA LS SF	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$325 \$19,710 \$25,163 \$4,500 \$3,500 \$19,200 \$7,500	100% 100% 100% 100% 100% 100% 100% 100%	\$1,130 \$3,402 \$3,500 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,402 \$3,402 \$4,139 \$5,284 \$945 \$3,500	04 04 04 04 04 04 04 04 04 04 04 04 04 0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7° of polylsocyanurate insulation for a five coating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing leaks Flashing for columns projecting through roof. Provide miscellaneous roof flashings at mechanical equipment curbs and roof adges, etc. to complete the EPDM system Rework existing roof drains above office to meet the new roof sievation Patch roof deck at existing skylight and apply roof membrane Provide new metal stding to match existing material at inflied overhead door Replace existing door hardware to meet code and add 4ea common area doors Maintenance and repairs for 6 Over Head doors Maintenance and repairs for 6 over Hea
31 32 33 34 35 36 37 38 38 39 10 11 12 55 66	BI BI BI BI BI BI BI BI FI	EPDM ROOFING - OFFICE PATCH WAREHOUSE ROOF FLASH COLUMNS ON ROOF MISC. FLASHING REWORK ROOF DRAINS PATCH ROOF DECK ADA ACCESS REQUIREMENTS DOORS & HARDWARE HOLLOW METAL DOORS REPAIR OVER HEAD DOORS FINISHES GYPSUM DRYWALL PATCH EXISTING WALLS ACOUSTICAL CEILINGS CARPETING CARPET VINYL BASE FLOOR PATCHING PAINTING CLEAN & PAINT WAREHOUSE RMS SPECIALTIES MISC MIRRORS & FIRE EXT. ELEVATORS	27000 84150 72 1 8 3 1 1 62 6 1080 500 27000 2889 4500 350 60000	SF SF EA LS SF	\$80,100 \$75,000 \$4,111 \$2,928 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,780 \$325 \$19,710 \$25,163 \$4,500 \$3,500 \$19,200 \$7,500	100% 100% 100% 100% 100% 100% 100% 100%	\$11,130 \$3,402 \$4,139 \$1,600 \$2,092 \$428 \$11,130 \$3,000 \$3,402 \$325 \$4,139 \$5,284 \$945 \$3,500	04 04 04 04 04 04 04 04 04 104 794 794 794	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$378 \$378 \$378 \$3,555 \$0 \$15,571 \$19,879 \$3,555 \$0 \$0 \$15,571 \$19,879 \$3,555	New cabinets and counterlops for coffee break stations Remove excess gravel surface coating, apply 2.7° of polylsocyanurate insulation for a first part of the polylsocyanurate insulation for a R-20 rating and apply a fully adhered EPDM roof membrane at existing Office area. Roof to have 10 year warranty. Existing Warehouse lower roof will have a patching contingency allowance to repair existing the part of th






SYSTEM CLASS

ADD SPRINKLER PROTECTION BELOW SUSPENDED CEILING THIS SYSTEM IS DESIGNED TO MEET NEPA #13 FOR LIGHT HAZARD PIPE SCHEDULE. THE EXISTING UPRIGHT SPRINKLERS TO REMAIN IN PLACE FOR PROTECTION OF THE WOOD ROOF DECK

LEGEND:

EXISTING DRY PENDENT HEADS



GENERAL NOTES:

ALL DIMENSIONS ARE CENTER TO CENTER U/N ALL PIPE TO BE BLACK SCH 40 THREADED OR SCH. 10 ROLL GROOVED ALL SCREWED FITTINGS TO BE STD. WT. C., BLACK U/N ALL GROOVED FITTINGS TO BE VICTAULIC FIRELOCK U/N ALL HANGERS TO BE BLACK STEEL U/N

DEAN & ALLYN, INC.


FIRE PROTECTION - SPECIAL HAZARD PO BOX 709, CRAY, MANE 04039 (207)657-5646 FAX: (207)657-5647

	DANA A. STEVAN NICET IV - 406			
 BATE	SURVEYED BY	HAK	4/25/02	TITLE
L	DRAWN BY	HAK	4/25/02	Ì
	CHECKED BY	DAS	4/25/02	ĺ

LE	THE	CIANBRO	COF	RPORATIO	5
	Α	METHYST	PRO	JECT	
	40	COMMERC	IAL	STREET	

100 100 100 connect size C0204328

v :	0-	1		1	APPROVED BY	PATE	SURVEYED BY	HAK	4/25/	E TITLE					
		_]					DRAWN BY	HAK	4/25/1	12	THE	CIANBRO	CC)RPOF	₹ДТ
				1					4/25/		Α	METHYST	PR	OJF C	T
		_					AT DEAN & ALLYN	. INC		7	40	COMMERC	ואור	STD	,
		_ i		<u>L</u>			SCALE 1/8"-: -0"	-		7					
		1	AG!21V3R	1,544.0			SHEET NO. 1 DF	1		-		PORTLAN	D N	νΑ!ΝΕ	-




i.

LIGHT FIXTURE SCHEDULE										
TYPE	DESCRIPTION	⊌FR.	LAMPS	MOUNTING	нот					
œ	THREAMOPLASTIC LED EXIT SHAN WITH UNIVERSAL MOUNT, PROVIDE WITH EMERGENCY BATTERY LIMIT.	DUALLITE	UED	AS SHOWN ON DRAWING	_					

NOTES:

1. SEZ SHEET E-001 FOR LEGENO AND GENERAL NOTES

3. EMERGENCY EXIT SIGNS SHIELL BE POWERED FROM LOCAL LIGHTING CRICUIT.




199UED FOR PERMITTING 4-9-02 ARCHITECTURE ENGINEERING PLANMING SWRT 144 Fow Strand/P.O. Imm 418 Partients, Motor 01104 sel. (287) 772-386 fee. (287) 772-380 THE CIANBRO CORPORATION

AMETHYST PROJECT

40 COMMERCIAL STREET PORTLAND, MANE SECOND FLOOR FIRE ALARM PLAN

SECOND FLOOR PLAN



FIRE ALARM FACP FIRE ALARM CONTROL PANEL FIRE ALAPM MASTER BOX FIRE ALARM WANUAL PULL STATION IFD FIRE ALAPM SPEAKER/STROBE UM FIRE MARM AUDIBLE/VISIBLE NOTIFICATION APPLIANCE (GENERAL EVACUATION FIRE ALARM ALIDBLE/MISIBLE
MOTHICATION APPLIANCE
CLEAN ROOM MOTHICATION (LOCAL) FINE ALARM VISIBLE ONLY NOTIFICATION APPLIANCE:

110) — CANDELA INTENSTY-15/75 JAKESS OTHERWISE MOTEO

C — CFF HOLD MICHINETE PHOTOELECTRIC SMOKE DETECTOR, CEILING MOUNTED CLEAR ROOM SMOKE DETECTOR

ORC-12 MIDICATES EQUIPMENT INTERLOCKED WITH THE SMOKE DETECTOR (H) COMBINATION PATE-OF-RISE/FIXED TEMPERATURE REAT DETECTOR, COLUNG MOUNTED DUCT SMOKE DETECTOR, PHOTOELECTRIC WITH AUXILIARY CONTACT FS SPRINGER SYSTEM FLOW SWITCH DHI FIRE ALARM SYSTEM WAZMETIC DOOR HOLDER MTERLOCK RELAY RTT GUCT SMOKE DETECTOR REMOTE TEST MOKATOR SECURITY SYSTEMS 2-WAY CELLING MOUNTED INTERCOM SPEAKER CELLING MOUNTED PAGING SPEAKER (4) WALL MOUNTED PAGING HORN C CELLING OR WALL MOUNTED FIXED CAMERA (5) CELING OR WALL MOUNTED PTZ CAMERA PAGE PAGING CONTROL EQUIPMENT DOOR DOOR CONTROL TRIBUNAT (DC) MONITORED DOOR POSITION SWITCH AND CONTROLLED DOOR HARDWAR MONITORED DOOR POSITION SWITCH
STANDARD INTERCOM STATION WALL MOUNTED CURRESS BUTTON GRAPHIC CONTROL PANEL TOUCH SCREEN WORKSTATION [TV] OCTV CONTROL OR DISPLAY FOLKPHING ZONE PERMETER CONTROL EQUIPMENT DURY DURESS CONTROL EQUIPMENT DURESS ALARM RECEIVER OFFICER CONTROLLED COLLECT-ONLY PUBLIC TELEPHONE DEL OFFICER CONTROLLED FIRE SPRINKLER (DELUGE) HEAD MI HE DUAL TECHNOLOGY VOLUMETRIC SENSOR DR LOCAL DOOR RELEASE BUTTON WAT OFFICER CONTROLLED SHOWER WATER SUPPLY CARE OFFICER CONTROLLED LIGHTING AND ELECTRICAL OUTLETS DOOR CONTACT

CR CARC READER KP KEY PAD CCTVICI CLOSED CIRCUIT TELEVISION CAMERU ES ELECTRIC STRIKE

ONE LINE DIAGRAM MEDIUM VOLTAGE DRAWOUT CIRCUIT BREAKT LOW VOLTAGE DRAWOUT CIRCLET BREAKER

AF - AMP FRAME
AT AT - AMP TRIP

ED 60 - ELECTICALLY OPERATED FUSED LOAD BREAK SWITCH MEDIUM VOLTAGE MOTOR STARTER MAGNETIC MOTOR STARTER, NEMERAL ROUGHTS NEMA SIZE FARE UNLESS OTHERWISE NOTED.

FOR PLUL WOLLDOR REVERSING ROUT TRANSFORMEN 25 - TWO SPECIAL START OF THE PROPERTY OF THE PROP CAPACITOR VFD VARIABLE FREQUENCY DRIVE POWER TRANSFORMER

A UNION THE SELF COOLED

FA — FAN COOLED

FA — FAN COOLED

FA — FAN COOLED SHIPLDED TRANSFORMER POTENTIAL TRANSFORMER

WARD/120 — RATIO

NUMBER REQUIRED CURRENT TRANSFORMER

400/5 — RATIO

MUMBER REQUIRED GROUND FALLT CURRENT TRANSCIONS (5) MOTOR, NUMBER INDICATES HORSEPOWE (4) **(A)** DIGITAL POWER METER METER TRANSFER SWITCH
AS - AMMETER SWITCH
VS - VOLTMETER SWITCH AS TRANSIENT VOLTAGE SURGE SL •• → LICHTING ARRESTOR -- KEY INTERLOCK FUSE F DRAWOUT DEVICE

AMERICATIONS

AMERICAN
APPER ARTER PROSPED GLOOR
AFT ARDE PRESSED FLOOR
AFT ARDE PRESSED FLOOR
AFT ARDE PRESSED FLOOR
AFT ARDE PRESSED FLOOR
AFT ARDER PRESSED FLOOR
AND AMERICAN THE CALLEY
BOOK AMERICAN THE CALLEY
BOOK AMERICAN THE CALLEY
BOOK AMERICAN THE CALLEY
CONTROL PROSPED
CONTRO

0 SSUED FOR PERMITTING
PEX: PEXEMPTON 4-9
PEX: PEXEMPTON 4-9
PEX: PEXEMPTON 4-9-02

CENERAL NOTES

. ALL WORN SHALL BE PETFORMED IN ACCORDANCE WITH MFD #10, MIDDING ELECTRON. CODE (NEC). 2002 EDITION. LOUISE OF MEMORIES DOTTO HE WAS MOTHER AND MOTHERATION DEVICES SHALL BE MOUNTED BY AFT TO THE SOTTOM OF THE COVICE SHALL BE MOUNTED BY AFT TO THE SOURCE MOUNT FOR ALL ARMS PULL STATIONS 48 NOISES AFT TO THE O'D BOXES, ALARMS PULL STATIONS 48 NOISES AFT TO THE O'D BOXES.

ALL PENETRADORS THROUGH FLOORS, RATED WALLS AND PARTITIONS SHALL BE SEALED WITH A UL APPROVED FIRE SEALANT MATERIAL TO MAINTAIN THE RATING OF THE SEPAR

ALL ENCLOSURES, CONDUIT BODIES AND THEIR COVERS CONTAMING FIRE ALARM SYSTEM CONDUCTORS SHALL BE PAIN

GENERAL NOTE

ALL CREAK NOTES, SYMBOL USTS, AND DETAILS ARE TO BE CONSIDERED AS APPLICABLE TO ALL ELECTRICAL DRAWN FOR THIS PROJECT. SYMBOLS MID ABBREVIATIONS SHOWN ON THIS SEET ARE FOR REFERENCE ONLY AND DO NOT INDICATE THEIR INCORPORATION IN THE DESIGN.

AMETHYST PROJECT
PROJECT: 40 COMMERCIAL STREET POPULAND, JAMME
LEGEND &
CENERAL NOTES
SHEET INLE:
SOCIE
1/05/11-07 TOJE
SOCIE
1/05/11-07 TOJE

ARCHITECTURE ENGINEERING PLANNING

ed. (2007) 772-3644 fac. (2007) 772-1070 THE CIANBRO CORPORATION

