

(3-15-56)

3/20/56 - all items have been connected
& Ok to issue Order (Temp. Management
finished. J.M.M

7/14/56 Insp Garage close in w/Christ.
- will add some building plates for electrical protection.
- 1st step rise too high
Ok to proceed w/ stock on common wall. J.M.

7/31/56 - all above (7/14) have been connected no
new issues seen. Ok for permanent if O when you
regards give us as need. J.M.M

11/4/05 Spoke to Dana Dresser who says surveyor will be
out to day - went over what is needed for winding of surveyors
letter. To come in and look good. Once pour footings &
wall can be poured after surveyors letter received.

11/7/05 US plumbing due

11/30/05 - Backfill ok - Still waiting for Surveyors
Letter (C)

03/10/06 - Left a message for Dana Dresser telling
him we will not be out for an inspection until we
have the required letter from Surveyor Carty giving the
setbacks are in compliance w/ zoning "from M"

03/15/06 - Received Surveyor letter from
Titscomb Assoc. Inc.
John M

03/15/06 - Gent steps

① Rail system not to end of run ② Rail ht at
Steps 32". ③ no handrails.

② Basement Steps 19 1/2" de ~~ft~~ heads all less than 10" net
Risers over 8" - ③ no Handrails - open railings and
then "bottom of steps." ~~like a fire place~~ ^{like a fireplace}

③ 5105 STAIRS Open risers. Rail system not end

of steps - No hand rails

④ Drywall or ceilings 1st floor not to be drywall

⑤ Sink in 1st floor needs permanent back splash work.