

MUNDY SCUTH

SHAW-WALKER
#8503-1B

REQUEST FOR SERVICE

PORTLAND HEALTH DEPARTMENT

DATE RECEIVED	8/9/82	BY	Good	DISTRICT	H. C. Council
REQUEST BY	NAME	State Rep. Edith Scanlon for M. WING			
	ADDRESS	Tenant Organization (775-1494)			
OWNER	NAME				
	ADDRESS				
CONDITIONS	ADDRESS	Munjoy So. Townhouses			
Complete inspection for violations, sliding doors & windows that do not open, rotten floors, wiring overloaded, etc. (also)					
(Mrs. Scanlon would like follow-up report)					
COMMENTS	8-18-82 MET AT PROPERTY WITH TENANT SP KESMAN C. SHEPPARD WHO SAID HE WOULD COME TO OUR OFFICE WITH A LIST OF TENANTS SPECIAL INSTRUCTIONS WISHING TO MAKE COMPLAINTS. BMA/SBRO				
DIVISION	SANITATION		HOUSING		NURSING
PRIORITY	ROUTINE		SPECIAL		BY
	URGENT		REPORT TO		DATE

REQUEST FOR SERVICE

PORTLAND HEALTH DEPARTMENT

DATE RECEIVED	4 4-11-72	BY	Gayle	DISTRICT	McLean
REQUEST BY	NAME	Carlton Tripp			774-187
	ADDRESS	Munjoy South Apt. 25			
OWNER	NAME				775-11 6
	ADDRESS				
CONDITIONS	ADDRESS	Munjoy South Apt. 25			
Rust problems with hot water					
COMMENTS	NOT JUSTIFIED				4-12-72
SPECIAL INSTRUCTIONS					
DIVISION	SANITATION		☒	HOUSING	NURSING
PRIORITY	ROUTINE		SPECIAL		BY
	URGENT		REPORT TO		DATE

REQUEST FOR SERVICE

PORTLAND HEALTH DEPARTMENT

DATE RECEIVED	8-27-71	BY	MARK	DISTRICT	McInnes
REQUEST BY	NAME	Mr. John Alilward			
	ADDRESS	Apt. 50 Munjoy South			
OWNER	NAME				
	ADDRESS				
CONDITIONS	ADDRESS	Munjoy South - (Apt. 50) roof leaks first floor boards are rot & warped			
COMMENTS					
SPECIAL INSTRUCTIONS	Candice L. 10-7-71				
DIVISION	SANITATION	HOUSING	NURSING		
PRIORITY	ROUTINE	SPECIAL	BY		
	URGENT	REPORT TO	DATE		

PORTLAND HEALTH DEPARTMENT

DATE RECEIVED	4-7-71	BY	Dint	DISTRICT	112545
REQUEST BY	NAME	Mr. Kuleszar 773-9794			
	ADDRESS	139 Munjoy South			
OWNER	NAME				
	ADDRESS				
CONDITIONS	ADDRESS	139 Munjoy South			
Mintenake man 775-1146					
Lack of hot water!!					
COMMENTS					
SPECIAL INSTRUCTIONS	Check Street File first				
DIVISION	SANITATION		HOUSING		NURSING
PRIORITY	ROUTINE		SPECIAL		BY
	URGENT		REPORT TO		DATE

SERVICE		PORTLAND HEALTH DEPARTMENT	
DATE RECEIVED	2-17-81	BY	Joyel
REQUEST BY	NAME	Ruth Him - 7741659	
	ADDRESS		
OWNER	NAME	Mungoy Assoc. - Managers - 775-1146	
	ADDRESS	Zachand	
CONDITIONS	ADDRESS	50 Mungoy St.	
No hot water - 5 days			
COMMENTS	Phoned mgmt - they will correct		
SPECIAL INSTRUCTIONS			
DIVISION	SANITATION	HOUSING	NURSING
PRIORITY	ROUTINE	SPECIAL	BY
	URGENT	REPORT TO	DATE

REQUEST FOR SERVICE

PORTLAND HEALTH DEPARTMENT

DATE RECEIVED	12-26-80	BY	L.D.N.	DISTRICT	
REQUEST BY	NAME	Mary Ann Woods			
	ADDRESS	Murray South			
OWNER	NAME	Murray South Town House			
	ADDRESS	725 12 46			
CONDITIONS	ADDRESS	#13			
		First floor apartments cold APT #13			
		APT #81			
COMMENTS					
SPECIAL INSTRUCTIONS					
DIVISION	SANITATION		HOUSING		NURSING
PRIORITY	ROUTINE		SPECIAL	BY	
	URGENT		REPORT TO	DATE	

REQUEST FOR SERVICE

PORTLAND HEALTH DEPARTMENT

DATE RECEIVED	5-4-79	BY	✓	DISTRICT	Kern
REQUEST BY	NAME	Mrs. Pratt			
	ADDRESS	125 Munjoy South			
OWNER	NAME	Joy C. Pratt			
	ADDRESS	140 Munjoy South			
CONDITIONS	ADDRESS	#125			
Paint peeling off -					
C.M.J. @ 5/4/79					
COMMENTS	Latey Paint on shutters - some faded areas but no peeling. @				
SPE	INSTRUCTIONS				
DIVISION	SANITATION		HOUSING		NURSING
PRIORITY	ROUTINE		SPECIAL		BY
	URGENT		REPORT TO		DATE

REQUEST FOR SERVICE

PORTLAND HEALTH DEPARTMENT

DATE RECEIVED	9/26/79		BY	Diller		DISTRICT	
REQUEST BY	NAME	Mrs Richard White					
	ADDRESS	11 Murphy South 773-9528					
OWNER	NAME	Mrs Davis					
	ADDRESS	Murphy South 775-1146					
CONDITIONS	ADDRESS	11 Murphy South					
No Heat							
COMMENTS	Phoned magnet & advised them of heat requirements. M. J. J. 9-20						
SPECIAL INSTRUCTIONS							
DIVISION	SANITATION		HOUSING		NURSING		
PRIORITY	ROUTINE		SPECIAL		BY		
	URGENT		REPORT TO		DATE		

City of Portland

Health Department

Housing Inspection Division

STRUCTURE INSPECTION SCHEDULE

1. Insp. Name CARROLL, K

2) Insp. Date	3) Insp. Type	4) Proj. Code	5) Assr's: Chart	6) Bl.	7) Lot	8) Census: Tract	9) Blk.	10) Insp.	11) Form No.		
10/31/77	NCP	EE	17	C	7			17	139		
12) House No.	13) Sec. H. No.	14) Suffix	15) Direct.	16) Street Name				17) St. Design.			
140				MUNJOY				SOUTH			
18) Owner or Agent: <u>MUNJOY ASSOCIATES</u>								19) Status	20) Bldg's Rat.		
21) Address: <u>144 ISLAND BROOK ROAD</u>								AC	01		
22) City and State: <u>BRIDGEPORT, CONN</u>								Zip Code: <u>06606</u>			
23) D. Units	24) Occ. D. U. s	25) Ra. Units	26) Occ R U s	27) No. Occupants	28) Com'l U.	29) Bldg. Type	30) St. Des.	31) Const. Mat	32) O. Bs		
140	140				NO	SDE	2 1/2	NO	NO		
33) C. H.	34) Photo	35) Zoned For	36) Actual Land Use	37) D. D.	38) Lks. Ad. Bth. Fac.	39) Disp	40) Closing Date				
Yes	NO	R	R		Yes (NC)						
Viol. No.	Remedy	Cond.	Violation Description			Fl. No.	Room Type	Area Type	Resp. Party	Code Sect. Viol.	Viol. Rem. Date
			STANDARD 1ST w/ Recommendations								
			LO/Peeling PAINT								
			C/A EX								
			TRIM/WALLS								
CC: To											
MRS Thomas Joyce, MGR											
MUNJOY South Townhouse APARTMENTS											
140 MUNJOY SOUTH											
PORTLAND, MAINE											

1G-B OK MUNDOY SOUTH Date 10-2-64
 Photos ☐ yes ☒ no
 Proj. No. ☐ C.I. ☐ Ass'ts ☐ Zone ☐ Zone Viol
 Stories ☒ 1 ☐ 2 ☐ 3 ☐ 4 ☐ 5 ☐ 6 ☐ 7 ☐ 8 ☐ 9 ☐ 10 ☐ 11 ☐ 12 ☐ 13 ☐ 14 ☐ 15 ☐ 16 ☐ 17 ☐ 18 ☐ 19 ☐ 20 ☐ 21 ☐ 22 ☐ 23 ☐ 24 ☐ 25 ☐ 26 ☐ 27 ☐ 28 ☐ 29 ☐ 30 ☐ 31 ☐ 32 ☐ 33 ☐ 34 ☐ 35 ☐ 36 ☐ 37 ☐ 38 ☐ 39 ☐ 40 ☐ 41 ☐ 42 ☐ 43 ☐ 44 ☐ 45 ☐ 46 ☐ 47 ☐ 48 ☐ 49 ☐ 50 ☐ 51 ☐ 52 ☐ 53 ☐ 54 ☐ 55 ☐ 56 ☐ 57 ☐ 58 ☐ 59 ☐ 60 ☐ 61 ☐ 62 ☐ 63 ☐ 64 ☐ 65 ☐ 66 ☐ 67 ☐ 68 ☐ 69 ☐ 70 ☐ 71 ☐ 72 ☐ 73 ☐ 74 ☐ 75 ☐ 76 ☐ 77 ☐ 78 ☐ 79 ☐ 80 ☐ 81 ☐ 82 ☐ 83 ☐ 84 ☐ 85 ☐ 86 ☐ 87 ☐ 88 ☐ 89 ☐ 90 ☐ 91 ☐ 92 ☐ 93 ☐ 94 ☐ 95 ☐ 96 ☐ 97 ☐ 98 ☐ 99 ☐ 100 ☐ 101 ☐ 102 ☐ 103 ☐ 104 ☐ 105 ☐ 106 ☐ 107 ☐ 108 ☐ 109 ☐ 110 ☐ 111 ☐ 112 ☐ 113 ☐ 114 ☐ 115 ☐ 116 ☐ 117 ☐ 118 ☐ 119 ☐ 120 ☐ 121 ☐ 122 ☐ 123 ☐ 124 ☐ 125 ☐ 126 ☐ 127 ☐ 128 ☐ 129 ☐ 130 ☐ 131 ☐ 132 ☐ 133 ☐ 134 ☐ 135 ☐ 136 ☐ 137 ☐ 138 ☐ 139 ☐ 140 ☐ 141 ☐ 142 ☐ 143 ☐ 144 ☐ 145 ☐ 146 ☐ 147 ☐ 148 ☐ 149 ☐ 150 ☐ 151 ☐ 152 ☐ 153 ☐ 154 ☐ 155 ☐ 156 ☐ 157 ☐ 158 ☐ 159 ☐ 160 ☐ 161 ☐ 162 ☐ 163 ☐ 164 ☐ 165 ☐ 166 ☐ 167 ☐ 168 ☐ 169 ☐ 170 ☐ 171 ☐ 172 ☐ 173 ☐ 174 ☐ 175 ☐ 176 ☐ 177 ☐ 178 ☐ 179 ☐ 180 ☐ 181 ☐ 182 ☐ 183 ☐ 184 ☐ 185 ☐ 186 ☐ 187 ☐ 188 ☐ 189 ☐ 190 ☐ 191 ☐ 192 ☐ 193 ☐ 194 ☐ 195 ☐ 196 ☐ 197 ☐ 198 ☐ 199 ☐ 200 ☐ 201 ☐ 202 ☐ 203 ☐ 204 ☐ 205 ☐ 206 ☐ 207 ☐ 208 ☐ 209 ☐ 210 ☐ 211 ☐ 212 ☐ 213 ☐ 214 ☐ 215 ☐ 216 ☐ 217 ☐ 218 ☐ 219 ☐ 220 ☐ 221 ☐ 222 ☐ 223 ☐ 224 ☐ 225 ☐ 226 ☐ 227 ☐ 228 ☐ 229 ☐ 230 ☐ 231 ☐ 232 ☐ 233 ☐ 234 ☐ 235 ☐ 236 ☐ 237 ☐ 238 ☐ 239 ☐ 240 ☐ 241 ☐ 242 ☐ 243 ☐ 244 ☐ 245 ☐ 246 ☐ 247 ☐ 248 ☐ 249 ☐ 250 ☐ 251 ☐ 252 ☐ 253 ☐ 254 ☐ 255 ☐ 256 ☐ 257 ☐ 258 ☐ 259 ☐ 260 ☐ 261 ☐ 262 ☐ 263 ☐ 264 ☐ 265 ☐ 266 ☐ 267 ☐ 268 ☐ 269 ☐ 270 ☐ 271 ☐ 272 ☐ 273 ☐ 274 ☐ 275 ☐ 276 ☐ 277 ☐ 278 ☐ 279 ☐ 280 ☐ 281 ☐ 282 ☐ 283 ☐ 284 ☐ 285 ☐ 286 ☐ 287 ☐ 288 ☐ 289 ☐ 290 ☐ 291 ☐ 292 ☐ 293 ☐ 294 ☐ 295 ☐ 296 ☐ 297 ☐ 298 ☐ 299 ☐ 300 ☐ 301 ☐ 302 ☐ 303 ☐ 304 ☐ 305 ☐ 306 ☐ 307 ☐ 308 ☐ 309 ☐ 310 ☐ 311 ☐ 312 ☐ 313 ☐ 314 ☐ 315 ☐ 316 ☐ 317 ☐ 318 ☐ 319 ☐ 320 ☐ 321 ☐ 322 ☐ 323 ☐ 324 ☐ 325 ☐ 326 ☐ 327 ☐ 328 ☐ 329 ☐ 330 ☐ 331 ☐ 332 ☐ 333 ☐ 334 ☐ 335 ☐ 336 ☐ 337 ☐ 338 ☐ 339 ☐ 340 ☐ 341 ☐ 342 ☐ 343 ☐ 344 ☐ 345 ☐ 346 ☐ 347 ☐ 348 ☐ 349 ☐ 350 ☐ 351 ☐ 352 ☐ 353 ☐ 354 ☐ 355 ☐ 356 ☐ 357 ☐ 358 ☐ 359 ☐ 360 ☐ 361 ☐ 362 ☐ 363 ☐ 364 ☐ 365 ☐ 366 ☐ 367 ☐ 368 ☐ 369 ☐ 370 ☐ 371 ☐ 372 ☐ 373 ☐ 374 ☐ 375 ☐ 376 ☐ 377 ☐ 378 ☐ 379 ☐ 380 ☐ 381 ☐ 382 ☐ 383 ☐ 384 ☐ 385 ☐ 386 ☐ 387 ☐ 388 ☐ 389 ☐ 390 ☐ 391 ☐ 392 ☐ 393 ☐ 394 ☐ 395 ☐ 396 ☐ 397 ☐ 398 ☐ 399 ☐ 400 ☐ 401 ☐ 402 ☐ 403 ☐ 404 ☐ 405 ☐ 406 ☐ 407 ☐ 408 ☐ 409 ☐ 410 ☐ 411 ☐ 412 ☐ 413 ☐ 414 ☐ 415 ☐ 416 ☐ 417 ☐ 418 ☐ 419 ☐ 420 ☐ 421 ☐ 422 ☐ 423 ☐ 424 ☐ 425 ☐ 426 ☐ 427 ☐ 428 ☐ 429 ☐ 430 ☐ 431 ☐ 432 ☐ 433 ☐ 434 ☐ 435 ☐ 436 ☐ 437 ☐ 438 ☐ 439 ☐ 440 ☐ 441 ☐ 442 ☐ 443 ☐ 444 ☐ 445 ☐ 446 ☐ 447 ☐ 448 ☐ 449 ☐ 450 ☐ 451 ☐ 452 ☐ 453 ☐ 454 ☐ 455 ☐ 456 ☐ 457 ☐ 458 ☐ 459 ☐ 460 ☐ 461 ☐ 462 ☐ 463 ☐ 464 ☐ 465 ☐ 466 ☐ 467 ☐ 468 ☐ 469 ☐ 470 ☐ 471 ☐ 472 ☐ 473 ☐ 474 ☐ 475 ☐ 476 ☐ 477 ☐ 478 ☐ 479 ☐ 480 ☐ 481 ☐ 482 ☐ 483 ☐ 484 ☐ 485 ☐ 486 ☐ 487 ☐ 488 ☐ 489 ☐ 490 ☐ 491 ☐ 492 ☐ 493 ☐ 494 ☐ 495 ☐ 496 ☐ 497 ☐ 498 ☐ 499 ☐ 500 ☐ 501 ☐ 502 ☐ 503 ☐ 504 ☐ 505 ☐ 506 ☐ 507 ☐ 508 ☐ 509 ☐ 510 ☐ 511 ☐ 512 ☐ 513 ☐ 514 ☐ 515 ☐ 516 ☐ 517 ☐ 518 ☐ 519 ☐ 520 ☐ 521 ☐ 522 ☐ 523 ☐ 524 ☐ 525 ☐ 526 ☐ 527 ☐ 528 ☐ 529 ☐ 530 ☐ 531 ☐ 532 ☐ 533 ☐ 534 ☐ 535 ☐ 536 ☐ 537 ☐ 538 ☐ 539 ☐ 540 ☐ 541 ☐ 542 ☐ 543 ☐ 544 ☐ 545 ☐ 546 ☐ 547 ☐ 548 ☐ 549 ☐ 550 ☐ 551 ☐ 552 ☐ 553 ☐ 554 ☐ 555 ☐ 556 ☐ 557 ☐ 558 ☐ 559 ☐ 560 ☐ 561 ☐ 562 ☐ 563 ☐ 564 ☐ 565 ☐ 566 ☐ 567 ☐ 568 ☐ 569 ☐ 570 ☐ 571 ☐ 572 ☐ 573 ☐ 574 ☐ 575 ☐ 576 ☐ 577 ☐ 578 ☐ 579 ☐ 580 ☐ 581 ☐ 582 ☐ 583 ☐ 584 ☐ 585 ☐ 586 ☐ 587 ☐ 588 ☐ 589 ☐ 590 ☐ 591 ☐ 592 ☐ 593 ☐ 594 ☐ 595 ☐ 596 ☐ 597 ☐ 598 ☐ 599 ☐ 600 ☐ 601 ☐ 602 ☐ 603 ☐ 604 ☐ 605 ☐ 606 ☐ 607 ☐ 608 ☐ 609 ☐ 610 ☐ 611 ☐ 612 ☐ 613 ☐ 614 ☐ 615 ☐ 616 ☐ 617 ☐ 618 ☐ 619 ☐ 620 ☐ 621 ☐ 622 ☐ 623 ☐ 624 ☐ 625 ☐ 626 ☐ 627 ☐ 628 ☐ 629 ☐ 630 ☐ 631 ☐ 632 ☐ 633 ☐ 634 ☐ 635 ☐ 636 ☐ 637 ☐ 638 ☐ 639 ☐ 640 ☐ 641 ☐ 642 ☐ 643 ☐ 644 ☐ 645 ☐ 646 ☐ 647 ☐ 648 ☐ 649 ☐ 650 ☐ 651 ☐ 652 ☐ 653 ☐ 654 ☐ 655 ☐ 656 ☐ 657 ☐ 658 ☐ 659 ☐ 660 ☐ 661 ☐ 662 ☐ 663 ☐ 664 ☐ 665 ☐ 666 ☐ 667 ☐ 668 ☐ 669 ☐ 670 ☐ 671 ☐ 672 ☐ 673 ☐ 674 ☐ 675 ☐ 676 ☐ 677 ☐ 678 ☐ 679 ☐ 680 ☐ 681 ☐ 682 ☐ 683 ☐ 684 ☐ 685 ☐ 686 ☐ 687 ☐ 688 ☐ 689 ☐ 690 ☐ 691 ☐ 692 ☐ 693 ☐ 694 ☐ 695 ☐ 696 ☐ 697 ☐ 698 ☐ 699 ☐ 700 ☐ 701 ☐ 702 ☐ 703 ☐ 704 ☐ 705 ☐ 706 ☐ 707 ☐ 708 ☐ 709 ☐ 710 ☐ 711 ☐ 712 ☐ 713 ☐ 714 ☐ 715 ☐ 716 ☐ 717 ☐ 718 ☐ 719 ☐ 720 ☐ 721 ☐ 722 ☐ 723 ☐ 724 ☐ 725 ☐ 726 ☐ 727 ☐ 728 ☐ 729 ☐ 730 ☐ 731 ☐ 732 ☐ 733 ☐ 734 ☐ 735 ☐ 736 ☐ 737 ☐ 738 ☐ 739 ☐ 740 ☐ 741 ☐ 742 ☐ 743 ☐ 744 ☐ 745 ☐ 746 ☐ 747 ☐ 748 ☐ 749 ☐ 750 ☐ 751 ☐ 752 ☐ 753 ☐ 754 ☐ 755 ☐ 756 ☐ 757 ☐ 758 ☐ 759 ☐ 760 ☐ 761 ☐ 762 ☐ 763 ☐ 764 ☐ 765 ☐ 766 ☐ 767 ☐ 768 ☐ 769 ☐ 770 ☐ 771 ☐ 772 ☐ 773 ☐ 774 ☐ 775 ☐ 776 ☐ 777 ☐ 778 ☐ 779 ☐ 780 ☐ 781 ☐ 782 ☐ 783 ☐ 784 ☐ 785 ☐ 786 ☐ 787 ☐ 788 ☐ 789 ☐ 790 ☐ 791 ☐ 792 ☐ 793 ☐ 794 ☐ 795 ☐ 796 ☐ 797 ☐ 798 ☐ 799 ☐ 800 ☐ 801 ☐ 802 ☐ 803 ☐ 804 ☐ 805 ☐ 806 ☐ 807 ☐ 808 ☐ 809 ☐ 810 ☐ 811 ☐ 812 ☐ 813 ☐ 814 ☐ 815 ☐ 816 ☐ 817 ☐ 818 ☐ 819 ☐ 820 ☐ 821 ☐ 822 ☐ 823 ☐ 824 ☐ 825 ☐ 826 ☐ 827 ☐ 828 ☐ 829 ☐ 830 ☐ 831 ☐ 832 ☐ 833 ☐ 834 ☐ 835 ☐ 836 ☐ 837 ☐ 838 ☐ 839 ☐ 840 ☐ 841 ☐ 842 ☐ 843 ☐ 844 ☐ 845 ☐ 846 ☐ 847 ☐ 848 ☐ 849 ☐ 850 ☐ 851 ☐ 852 ☐ 853 ☐ 854 ☐ 855 ☐ 856 ☐ 857 ☐ 858 ☐ 859 ☐ 860 ☐ 861 ☐ 862 ☐ 863 ☐ 864 ☐ 865 ☐ 866 ☐ 867 ☐ 868 ☐ 869 ☐ 870 ☐ 871 ☐ 872 ☐ 873 ☐ 874 ☐ 875 ☐ 876 ☐ 877 ☐ 878 ☐ 879 ☐ 880 ☐ 881 ☐ 882 ☐ 883 ☐ 884 ☐ 885 ☐ 886 ☐ 887 ☐ 888 ☐ 889 ☐ 890 ☐ 891 ☐ 892 ☐ 893 ☐ 894 ☐ 895 ☐ 896 ☐ 897 ☐ 898 ☐ 899 ☐ 900 ☐ 901 ☐ 902 ☐ 903 ☐ 904 ☐ 905 ☐ 906 ☐ 907 ☐ 908 ☐ 909 ☐ 910 ☐ 911 ☐ 912 ☐ 913 ☐ 914 ☐ 915 ☐ 916 ☐ 917 ☐ 918 ☐ 919 ☐ 920 ☐ 921 ☐ 922 ☐ 923 ☐ 924 ☐ 925 ☐ 926 ☐ 927 ☐ 928 ☐ 929 ☐ 930 ☐ 931 ☐ 932 ☐ 933 ☐ 934 ☐ 935 ☐ 936 ☐ 937 ☐ 938 ☐ 939 ☐ 940 ☐ 941 ☐ 942 ☐ 943 ☐ 944 ☐ 945 ☐ 946 ☐ 947 ☐ 948 ☐ 949 ☐ 950 ☐ 951 ☐ 952 ☐ 953 ☐ 954 ☐ 955 ☐ 956 ☐ 957 ☐ 958 ☐ 959 ☐ 960 ☐ 961 ☐ 962 ☐ 963 ☐ 964 ☐ 965 ☐ 966 ☐ 967 ☐ 968 ☐ 969 ☐ 970 ☐ 971 ☐ 972 ☐ 973 ☐ 974 ☐ 975 ☐ 976 ☐ 977 ☐ 978 ☐ 979 ☐ 980 ☐ 981 ☐ 982 ☐ 983 ☐ 984 ☐ 985 ☐ 986 ☐ 987 ☐ 988 ☐ 989 ☐ 990 ☐ 991 ☐ 992 ☐ 993 ☐ 994 ☐ 995 ☐ 996 ☐ 997 ☐ 998 ☐ 999 ☐ 1000 ☐ 1001 ☐ 1002 ☐ 1003 ☐ 1004 ☐ 1005 ☐ 1006 ☐ 1007 ☐ 1008 ☐ 1009 ☐ 1010 ☐ 1011 ☐ 1012 ☐ 1013 ☐ 1014 ☐ 1015 ☐ 1016 ☐ 1017 ☐ 1018 ☐ 1019 ☐ 1020 ☐ 1021 ☐ 1022 ☐ 1023 ☐ 1024 ☐ 1025 ☐ 1026 ☐ 1027 ☐ 1028 ☐ 1029 ☐ 1030 ☐ 1031 ☐ 1032 ☐ 1033 ☐ 1034 ☐ 1035 ☐ 1036 ☐ 1037 ☐ 1038 ☐ 1039 ☐ 1040 ☐ 1041 ☐ 1042 ☐ 1043 ☐ 1044 ☐ 1045 ☐ 1046 ☐ 1047 ☐ 1048 ☐ 1049 ☐ 1050 ☐ 1051 ☐ 1052 ☐ 1053 ☐ 1054 ☐ 1055 ☐ 1056 ☐ 1057 ☐ 1058 ☐ 1059 ☐ 1060 ☐ 1061 ☐ 1062 ☐ 1063 ☐ 1064 ☐ 1065 ☐ 1066 ☐ 1067 ☐ 1068 ☐ 1069 ☐ 1070 ☐ 1071 ☐ 1072 ☐ 1073 ☐ 1074 ☐ 1075 ☐ 1076 ☐ 1077 ☐ 1078 ☐ 1079 ☐ 1080 ☐ 1081 ☐ 1082 ☐ 1083 ☐ 1084 ☐ 1085 ☐ 1086 ☐ 1087 ☐ 1088 ☐ 1089 ☐ 1090 ☐ 1091 ☐ 1092 ☐ 1093 ☐ 1094 ☐ 1095 ☐ 1096 ☐ 1097 ☐ 1098 ☐ 1099 ☐ 1100 ☐ 1101 ☐ 1102 ☐ 1103 ☐ 1104 ☐ 1105 ☐ 1106 ☐ 1107 ☐ 1108 ☐ 1109 ☐ 1110 ☐ 1111 ☐ 1112 ☐ 1113 ☐ 1114 ☐ 1115 ☐ 1116 ☐ 1117 ☐ 1118 ☐ 1119 ☐ 1120 ☐ 1121 ☐ 1122 ☐ 1123 ☐ 1124 ☐ 1125 ☐ 1126 ☐ 1127 ☐ 1128 ☐ 1129 ☐ 1130 ☐ 1131 ☐ 1132 ☐ 1133 ☐ 1134 ☐ 1135 ☐ 1136 ☐ 1137 ☐ 1138 ☐ 1139 ☐ 1140 ☐ 1141 ☐ 1142 ☐ 1143 ☐ 1144 ☐ 1145 ☐ 1146 ☐ 1147 ☐ 1148 ☐ 1149 ☐ 1150 ☐ 1151 ☐ 1152 ☐ 1153 ☐ 1154 ☐ 1155 ☐ 1156 ☐ 1157 ☐ 1158 ☐ 1159 ☐ 1160 ☐ 1161 ☐ 1162 ☐ 1163 ☐ 1164 ☐ 1165 ☐ 1166 ☐ 1167 ☐ 1168 ☐ 1169 ☐ 1170 ☐ 1171 ☐ 1172 ☐ 1173 ☐ 1174 ☐ 1175 ☐ 1176 ☐ 1177 ☐ 1178 ☐ 1179 ☐ 1180 ☐ 1181 ☐ 1182 ☐ 1183 ☐ 1184 ☐ 1185 ☐ 1186 ☐ 1187 ☐ 1188 ☐ 1189 ☐ 1190 ☐ 1191 ☐ 1192 ☐ 1193 ☐ 1194 ☐ 1195 ☐ 1196 ☐ 1197 ☐ 1198 ☐ 1199 ☐ 1200 ☐ 1201 ☐ 1202 ☐ 1203 ☐ 1204 ☐ 1205 ☐ 1206 ☐ 1207 ☐ 1208 ☐ 1209 ☐ 1210 ☐ 1211 ☐ 1212 ☐ 1213 ☐ 1214 ☐ 1215 ☐ 1216

Photos ☐ Yes ☒ No
Proj. No.

Date 10-2-61

CROSSING	LOCATION <u>82 MULDER</u>	COMP.
SAFETY	D.W. LOC.	FILED
	OCCUPY	
	OWNER	
	AGENT	
	ADDRESS	YTS

DWELLING UNIT SCHEDULE

Occupants		Rent		Occupancy		Facilities						Violations				
		MO. RENT				RMS	PER.	AL.	D	LG	HEAT	BATH	FLSH	K.SK	H.W.	CK'S
1. <u>HELMY NELSON</u>		<u>1</u>	<u>2</u>	<u>5</u>	<u>1</u>	<u>6</u>	<u>1</u>	<u>5</u>	<u>1</u>	<u>5</u>	<u>1</u>	<u>5</u>	<u>1</u>	<u>5</u>	<u>1</u>	<u>5</u>
2.																
3.																
4.																

	KITCHEN	BATH	TOILET	DINING	LIVING	BED	BED	BED	BED	Other	TOTAL
OVERCROWDING 85' - 7'	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>		
50 SLEEP'G											
VENTILATION 1/12 - 1/2											
LIGHTING											
DET'N											
WALLS											
CEILINGS											
WINDOWS											
DOORS											
FLOORS											

Remarks

Portland
Health Dept.
CS-7

Inspector F. J. [Signature]

KITCHEN SINK & WATER

☐ SINK	
☐ SUPPLY & WASTE	
☐ PLUG, GEN'L	
☐ HEATING	
☐ STUCKS, PLUGS, VENTS	
☐ IS VENTED, REP'D	
☐ BATHING FACILITIES	
☐ SHARED MAX. 4DU	
☐ U. 1 PER 15	
☐ MIN. 7" STOD MT.	
☐ VENT'LN	
☐ JPER ACCESS	
☐ PLUGS	
☐ VENT'LN	

TOILET FACILITIES

☐ SHARED MAX. 2 DU	
☐ LONG U. IN & LAV 1 PER 10	
☐ VENT'LN	
☐ PROPER ACCESS	
☐ PLUGS	
☐ VENT'LN	


INFESTATION

☐ RATS ☐ R. ☐ O. ☐ E	
☐ OTHER (SPECIFY)	
☐ EGRESS	
☐ DUAL ☐ YES ☐ NO	
☐ OBST'N	



CITY OF PORTLAND

JOSEPH E. GRAY, JR.
DIRECTOR OF
NEIGHBORHOOD CONSERVATION



May 2, 1979

Gene Davis

Munjoy Associates
c/o Mr. Donald Tarinelli
144 Island Brook Road
Bridgeport, Conn. 06606

cc: Ms. Thomas Joyce
Munjoy South Townhouse Apts.
140 Munjoy South
Portland, Maine 04101

Dear Sirs: Re: Munjoy South Townhouses, Portland, Maine NCP-EE 17-G-7

We recently received a complaint and an inspection was made by Housing Inspector Carroll, of the proper town by you at Munjoy South Townhouses, Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following sub-standard housing conditions:

- 6/29 1. D.U. #2 BATHROOM SINK - repair leak in supply line. 6c
- 6/29 2. D.U. #2 CELLAR - repair inoperative automatic fire door. 9c
- 6/29 3. D.U. #12 BATHROOM & KITCHEN WALL & FLOOR - repair loose & missing tiles. 3b
- 6/29 4. D.U. #12 REAR BEDROOM WINDOW - replace broken glass. 3c
- 6/29 5. D.U. #12 BATHROOM CEILING - determine the reason and remedy the condition causing leakage. 3b
- 6/29 6. D.U. #13 LIVING ROOM WINDOWS - replace broken glass. 3c
- 6/29 7. D.U. #13 BATHROOM SHOWER - determine the reason and remedy the condition causing leakage. 6c
- 6/29 8. D.U. #53 BATHROOM CEILING - remove loose and peeling paint. 3b
- 6/29 9. D.U. #53 KITCHEN FLOOR - replace broken tile. 3b
- 7/11 10. D.U. #49, #55, #64, #95, #121, #128, #129, #132 - repair or replace loose and broken attic louver vent slats. 3a, 3b
- 6/29 11. D.U. #65 REAR EXTERIOR STAIRS - replace tiles & string. 3d
- 6/29 12. D.U. #95 REAR EXTERIOR WALL - repair broken light fixture. 8e

The above mentioned conditions are in violation of Chapter 307 of the Municipal Code of the City of Portland, Maine, and must be corrected on or before June 2, 1979.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

Inspector *Kenneth Carroll*
K. Carroll

By *Lyle D. Noyes*
Lyle D. Noyes,
Chief of Housing Inspections

#72
106 VW

REFERRAL MEMORANDUM

To: L. D. Hayes, Chief of Housing Inspections
From: K. W. Canale, Inspector

HOUSING INSPECTIONS DIVISION
DEPARTMENT OF NEIGHBORHOOD
CONSERVATION

Date: 4-30-79

Subject: Munjoy South Townhouse Apartments

Conditions or Defects: Results of complaint investigation on above property.

I have finished my inspection of the 13 apartments listed in the written complaint and a general exterior survey of the entire Munjoy South housing development with the following results.

1. Dwelling units inspected (#2, 7, 12, 13, 53, 75)
2. Dwelling units (#73 & #80) Tenants claimed problems were taken care of promptly when they notified the landlord.
3. Dwelling units (#55, 77, 99, 115 & 125) No access after several attempts - I called on each of these apts. at least 3 different times and left notices each time. None of these tenants have contacted me to arrange for inspections.

The end result was verification of 12 housing code violations total. I am sending the owner & manager of the development a 30 day letter of notification to correct the 12 violations.

K. W. Canale

The responsible department or division is requested to reply on this form and return the form to the Housing Inspections Division, Room _____

Reply:

Date:

Instructions: Inspectors will complete this form in triplicate retaining one copy for the tickler file and two copies to the street file. The original will be sent to the responsible division or city department.

✓ May 2, 1979

Munjoy Associates
c/o Mr. Donald Tarinelli
144 Island Brook Road
Bridgeport, Conn. 06606

cc: Ms. Thomas Joyce
Munjoy South Townhouse Apts.
140 Munjoy South
Portland, Maine 04101

Dear Sirs: Re: Munjoy South Townhouses, Portland, Maine NCP-EE 17-G-7

We recently received a complaint and an inspection was made by Housing Inspector Carroll, of the property owned by you at Munjoy South Townhouses, Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following sub-standard housing conditions:

1. D.U. #2 - BATHROOM SINK- repair leak in supply line. 6c
2. D.U. #2 - CELLAR- repair inoperative automatic fire door. 9c
3. D.U. #12- BATHROOM & KITCHEN - WALL & FLOOR- repair loose & missing tiles. 3b
4. D.U. #12- REAR BEDROOM WINDOW - replace broken glass. 3c
5. D.U. #12- BATHROOM CEILING-determine the reason and remedy the condition causing leakage. 3b
6. D.U. #13- LIVING ROOM WINDOWS- replace broken glass. 3c
7. D.U. #13- BATHROOM SHOWER - determine the reason and remedy the condition causing leakage. 6c
8. D.U. #53- BATHROOM CEILING - remove loose and peeling paint. 3b
9. D.U. #53- KITCHEN FLOOR - replace broken tile. 3b
10. D.U. #49, #55, #64, #96, #121, #128, #129, #132- repair or replace loose and broken attic louvers vent slats. 3a, 3b
11. D.U. #64- REAR EXTERIOR STAIRS - replace tiles. 3d
12. D.U. #95- REAR EXTERIOR WALL - repair broken light fixture. 8e

The above mentioned conditions are in violation of Chapter 307 of the Municipal Code of the City of Portland, Maine, and must be corrected on or before June 2, 1979.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.


Inspector

K. Carroll
K. Carroll

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

By

Lyle D. Noyes
Lyle D. Noyes,
Chief of Housing Inspections



May 1, 1979

Munjoy Associates
c/o Donald Tarnielli
144 Island Brook Road
Bridgeport, Conn. 06606

cc. Mrs. Thomas Joyce, Mgr.
Munjoy South Townhouse Apts.
140 Munjoy South
Portland, Maine 04114

Dear Sirs: Re: 98 Munjoy South, Portland, Maine JCP-East End 17-G-7

We recently received a complaint and an inspection was made by Housing Inspector Addato of the property owned by you at 98 Munjoy South, Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following sub-standard housing conditions:

- 4/12 1. ~~LAUNDRY ROOM CEILING~~ determine the reason and remedy the condition causing leakage. 31
- 4/12 2. ~~WASH TUB~~ determine the reason and remedy the condition causing leakage around the tub. 6d
- 4/12 3. ~~LAUNDRY ROOM~~ replace missing plaster in the ceiling. 3b
- 4/12 4. ~~REAR PORCH~~ repair or replace rear porch. 3d

The above mentioned conditions are in violation of Chapter 307 of the Municipal Code of the City of Portland, Maine, and must be corrected on or before June 1, 1979.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

By _____
Lyle D. Boyes,
Chief of Housing Inspections

Inspector _____
A. Addato

VW

May 1, 1979

Munjoy Associates
c/o Donald Tarinelli
144 Island Brook Road
Bridgeport, Conn. 06606

cc. Mrs. Thomas Joyce, Mgr.
Munjoy South Townhouse Apts.
140 Munjoy South
Portland, Maine 04101

Dear Sirs: Re: 98 Munjoy South, Portland, Maine NCP-East End 17-G-7

We recently received a complaint and an inspection was made by Housing Inspector Addato of the property owned by you at 98 Munjoy South, Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following sub-standard housing conditions:

- | | |
|--|----|
| 1. LAUNDRY ROOM CEILING- determine the reason and remedy the condition causing leakage. | 3b |
| 2. BATHROOM TUB- determine the reason and remedy the condition causing leakage around the tub. | 6d |
| 3. LAUNDRY ROOM - replace missing plaster in the ceiling. | 3b |
| 4. REAR PORCH - repair or replace rear porch. | 3d |

The above mentioned conditions are in violation of Chapter 307 of the Municipal Code of the City of Portland, Maine, and must be corrected on or before June 1, 1979.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

By Lyle B. Moyes
Lyle B. Moyes,
Chief of Housing Inspections

Inspector A. Addato
A. Addato

vw

PS Form 3811, Apr 1977

● SENDER Complete items 1, 2 and 3. Add your address in the space on reverse. RETURN TO

1 The following service is requested (check one).
☐ Show to whom and date delivered
☐ Show to whom, date, and address of delivery
☐ RESTRICTED DELIVERY
☐ RESTRICTED DELIVERY
 Show to whom and date delivered
☐ RESTRICTED DELIVERY
 Show to whom, date, and address of delivery. \$
 (CONSULT POSTMASTER FOR FEES)

2 ARTICLE ADDRESSED TO
 Munjoy Associates
 c/o Donald J. Farrell
 144 Island Brook Rd.
 Bridgeport, Conn. 06606

3 ARTICLE DESCRIPTION
 REGISTERED NO CERTIFIED NO INSURED NO
 520306

(Always obtain signature of addressee or agent)
 I have received the article described above
☒ Addressee ☐ Authorized agent

4 DATE OF DELIVERY
 5-8-79

5 ADDRESS (Complete only if requested)
 POSTMARK

6. UNABLE TO DELIVER BECAUSE
 CLERK'S INITIALS

RETURN RECEIPT, REGISTERED, INSURED AND CERTIFIED MAIL

☆ GPO 1977-0-249 595

April 20, '79

Mr. Kyle Royce,

I am a Manjoy South
Tenant, and I would
like to have my
apartment inspected.

My home phone # is 773 1699
-work # is 775 6571, please
call to set appointment
for inspection.

Thank you,

Wynne McLaughlin

f

MUNJOY SOUTH TENANTS

Suggestion Sheet

1:30

Fri

Name: Suzanne McNaughtlin

Address: 98 Munjoy South

Tenant Since: Feb 1978

Housing Code Violations (if any):

- ① hole in ceiling from leaking pipes, leaking in and near electrical wires, ② Back steps very dangerous, ③ hot water heat ④ trouble with electric box.

Concerns about the proposed rent increase:
(ie what services have been neglected?)

Snow plowing (winter)
Keeping up the grounds (summer)

General Concerns about Munjoy South:

AGENDA

I. Introduction

A. Reasons for this meeting

1. rent increase, snow removal, maintenance, exterior painting, ect.

II. Rent Increase

A. Concerns of individuals

B. Fill out suggestion sheet

III. Future Plans

A. Discussion of a Tenants' Union

1. Set up meeting of those most interested

B. Discussion of Munjoy Hill Neighborhood Organization

1. Good Neighborh distribution (first of every month)
2. M.H.N.O. 1st Annual Meeting and election of officers (Board of Directors) - Wednesday, April 18 at 7:30 pm at Cummings Center
3. Candidates' Night - City Council and School Committee Thursday, April 26 at 7:00 pm at Marada Adams School

✓ November 14, 1977

Munjoy Associates
c/o Mr. Donald Tarinelli
144 Island Brook Road
Bridgeport, Conn. 06606

Dear Mr. Tarinelli:

Re: #1 thru #140 Munjoy South - 17-G-7
NCP-East End
Neighborhood Conservation

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general conditions of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems.

EXTERIOR TRIM AND WALLS - overall - loose and peeling paint.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

By _____
Lyle D. Noyes,
Chief of Housing Inspections

Inspector K. Carroll

cc: Mrs. Thomas Joyce, Manager
Munjoy South Townhouse Apartments
140 Munjoy South, Portland, Maine

CITY OF PORTLAND - HEALTH DEPARTMENT
LEAD POISONING and LEAD BASE PAINT DETECTION PROGRAM

Address: 108 Munjoy South Date: 1-9-75
 D.U. Location: 1 and 2 fl. Owner: Munjoy Associates
 Occupant: Mr. Charles Huntington Owner's Address: 510 Penn Center Plaza
 Children: 5 Ages: 6,5,4,3 and 2 Philadelphia, Penn. 19103
 Referred By: PHN. Chittick Project Area: General
 Building Type: Townhouses Building Condition: Good No. D.U.: 1
 Patient's Name: Charles

DIGITAL ANALYZER (LEAD DETECTOR) READINGS Mg/cm²

INTERIOR ROOMS:	Kitchen	Bath	Living	Dining	Bd#1	Bd#2	Bd#3	Bd#4	Other
W. Sills	ALL READINGS NEGATIVE.								
Doors									
walls									
M.Board									
Cabinets									
Furniture									
Other									
COMMON AREAS:	Hall	Stair	F.Porch	R.Porch	Entry	Other	Other	Other	Other
Steps									
Rails									
Doors									
Walls									
Other									

THE AREAS ABOVE CONTAIN A HIGH CONCENTRATION OF LEAD BASED PAINT (OVER 2.0 mg/cm²). THESE AREAS MUST BE DETOXIFIED.

Comments: No lead content.. Patient previously lived at 18 Sheridan Street - probable source of lead.

IF YOU HAVE ANY QUESTIONS REGARDING THIS MATTER, PLEASE DO NOT HESITATE TO CALL THE OFFICE.

Housing Inspector: D. Gendreau

Health Dept. - Housing Division - 775-5451
Ext. 448

PORTLAND HEALTH DEPARTMENT - NURSING DIVISION - HOUSING INSPECTIONS DIVISION - LABORATORY

CITY OF PORTLAND - HEALTH DEPARTMENT
LEAD POISONING and LEAD BASE PAINT DETECTION PROGRAM

Address: 108 Munjoy South Date: 1-9-75
D.U. Location: 1 and 2 fl. Owner: Munjoy Associates
Occupant: Mr. Charles Huntington Owner's Address: 510 Penn Center Plaza
Children: 5 Ages: 6,5,4,3 and 2 Project Area: General
Referred By: PHN. Chittick Patient's Name: Charles
Building Type: Townhouses Building Condition: Good No. D.U.: 1

DIGITAL ANALYZER (LEAD DETECTOR) READINGS Mg/cm²

INTERIOR ROOMS:	Kitchen	Bath	Living	Dining	Bd#1	Bd#2	Bd#3	Bd#4	Other
W. Sills	ALL READINGS NEGATIVE.								
Doors									
Walls									
M.Board									
Cabinets									
Furniture									
Other									
COMMON AREAS:	Hall	Stair	F.Porch	R.Porch	Entry	Other	Other	Other	Other
Steps									
Rails									
Doors									
Walls									
Other									

THE AREAS ABOVE CONTAIN A HIGH CONCENTRATION OF LEAD BASED PAINT (OVER 2.0 mg/cm²). THESE AREAS MUST BE DETOXIFIED.

Comments: No lead content. Patient previously lived at 18 Sheridan Street - probable source of lead.

IF YOU HAVE ANY QUESTIONS REGARDING THIS MATTER, PLEASE DO NOT HESITATE TO CALL THIS OFFICE.

Housing Inspector: Donald A. Gendreau

D. Gendreau

Health Dept. - Housing Division - 775-5451
Ext. 448

PORTLAND HEALTH DEPARTMENT - NURSING DIVISION - HOUSING INSPECTIONS DIVISION - LABORATORY

**CITY OF PORTLAND - HEALTH DEPARTMENT
LEAD POISONING and LEAD BASE PAINT DETECTION PROGRAM**

Address: 108 Munjoy South Date: 1-9-75
 D.U. Location: 1 and 2 fl. Owner: Munjoy Associates
 Occupant: Mr. Charles Huntington Owner's Address: 510 Penn Center Plaza
 Children: 5 Ages: 6,5,4,3 and 2 Philadelphia, Penn. 19103
 Referred By: PHN. Chittick Project Area: General
 Building Type: Townhouses Building Condition: Good Patient's Name: Charles
 No. D.U.: 1

DIGITAL ANALYZER (LEAD DETECTOR) READINGS Mg/cm²

INTERIOR ROOMS:	Kitchen	Bath	Living	Dining	Bd#1	Bd#2	Bd#3	Bd#4	Other
W. Sills	ALL READINGS NEGATIVE.								
Doors									
Walls									
H. Board									
Cabinets									
Furniture									
Other									
COMMON AREAS:	Hall	Stair	F. Porch	R. Porch	Entry	Other	Other	Other	Other
Steps									
Rails									
Doors									
Walls									
Other									

THE AREAS ABOVE CONTAIN A HIGH CONCENTRATION OF LEAD BASED PAINT (OVER 2.0 mg/cm²). THESE AREAS MUST BE DETOXIFIED.

Comments: No lead content. Patient previously lived at 18 Sheridan Street - probable source of lead.

IF YOU HAVE ANY QUESTIONS REGARDING THIS MATTER, PLEASE DO NOT HESITATE TO CALL THIS OFFICE.

Housing Inspector: D. Gendreau Health Dept. - Housing Division - 775-5451
Ext. 448

PORTLAND HEALTH DEPARTMENT - NURSING DIVISION - HOUSING INSPECTIONS DIVISION - LABORATORY



CITY OF PORTLAND

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT
INSPECTION SERVICES DIVISION
August 24, 1989

Munjoy South Townhouses
P O. Box 3612
Portland, Maine 04101

Re: 2 Munjoy South

Dear Sir:

We recently received a complaint and an inspection was made by Code Enforcement Officer Joe Torres of the property owned by you at 2 Munjoy South, Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following substandard housing conditions:

Interior


- 1.) Floor 1 - Kitchen light - switch cover missing


The above mentioned conditions are in violation of Article V of the Municipal Code of the City of Portland, Maine, and must be corrected on or before September 3, 1989.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours,
Joseph E. Gray, Jr., Director of
Planning & Urban Development

By


P. Samuel Hoffer
Chief of Inspection Services


Joe Torres, Housing Inspector

ON SCHEDULE

TRACY CONBACH

Property Address: 2 Munday So.

Owner or Agent MUNDOY South TOWN HOUSES
Address

AC- BDX 3612 0410

[illegible]



APPLICATION FOR PERMIT
DEPARTMENT OF BUILDING INSPECTIONS SERVICES
ELECTRICAL INSTALLATIONS

Date March 5, 19 87
Receipt and Permit number D 09129

To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine:

The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications:

LOCATION OF WORK: 38 Munjoy South
OWNER'S NAME: Munjoy Associates ADDRESS: Munjoy South FEES

OUTLETS: Receptacles _____ Switches _____ Plugmold _____ ft. TOTAL _____

FIXTURES: (number of) Incandescent _____ Fluorescent _____ (not strip) TOTAL _____
Strip Fluorescent _____ ft. _____

SERVICE: _____ Underground _____ Temporary _____ TOTAL amperes _____

METERS: _____ or of) _____

MOTORS: (number of) Fractional _____
1 HP or over _____

RESIDENTIAL HEATING: Oil or Gas (number of units) _____
Electric (number of rooms) _____

COMMERCIAL OR INDUSTRIAL HEATING: Oil or Gas (by a main boiler) _____
Oil or Gas (by separate units) _____
Electric Under 20 kws _____ Over 20 kws _____

APPLIANCES: (number of) Ranges _____ Water Heaters _____
Cook Tops _____ Disposals _____
Wall Ovens _____ Dishwashers _____
Dryers _____ Compactors _____
Fans _____ Others (denote) _____

TOTAL _____

MISCELLANEOUS: (number of) Branch Panels _____

Transformers _____

Air Conditioners Central Unit _____
Separate Units (windows) _____

Signs 20 sq. ft. and under _____
Over 20 sq. ft. _____

Swimming Pools Above Ground _____
In Ground _____

Fire/Burglar Alarms Residential _____
Commercial _____

Heavy Duty Outlets, 220 Volt (such as welders) 30 amps and under _____
over 30 amps _____

Circuits, Fairs, etc. _____

Alterations to wires _____ 2.00

Repairs after fire _____

Emergency Lights, battery _____

Emergency Generators _____

FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT INSTALLATION FEE DUE: _____
FOR REMOVAL OF A "STOP ORDER" (304-16.b) DOUBLE FEE DUE: _____
TOTAL AMOUNT DUE: min 5.00

INSPECTION: Will be ready on ready, 19 87; or Will Call _____

CONTRACTOR'S NAME: Roberts Elec

ADDRESS: 116 Munjoy South

TEL: 773-8053

MASTER LICENSE NO.: 4230 SIGNATURE OF CONTRACTOR: Robert Roberts

LIMITED LICENSE NO.: _____

INSPECTOR'S COPY — WRITE

Permit Number 6-17-1

20

8120010

W. J. Waring

5721

05.

— 177 —

Permit Application Register Page No. 111

Service called in _____

Closing-in 3, 6/87 by Russ

PROGRESS INSPECTIONS: 3/6/87, _____, _____

[illegible]