

Such

Full out \* 920R - Half out \* 9202R - The ... ou. ? 92.J 'R - Firth out \* 92059

April 3, 1980

Foley Brothers 52 Pleasant St. Portland, Me.

Ref: 119-121 Brackett St.

sir:

Your building permit application to construct a dormer and change of use from five to four families at the above named location, is horeby denied for the following reasons:

- 1. Plans submitted are incomplete
- 2. Estimated contractural cost must be verified.
- 3. Work has commenced without banefit of required permits.

Yours truly,

Walter W. Hilton Building Inspector

WWH:k

## APPLICATION FOR PERMIT

B.O.C.A. USE GROUP

B.O.C.A. TYPE OF CONSTRUCTION

DOCATION

PORTLAND, MAINE, XREE. April. 3., 1980

DOCATION

PORTLAND, MAINE, XREE. April. 3., 1980

ZONING LOCATION_/X	PORTLAND,	, MAINE, XAER - ADIZZ
To the DIRECTOR OF BUILDING & I The undersigned hereby applies for a ure, equipment or change use in accord Coning Ordinance of the City of Portlan	INSPECTION SERVICES  I permit to erect, alter, repance with the Laws of the and with plans and specifica	S, PORTLAND, MAINE pair, demolish, move or install the following building, structure of Maine, the Portland B.O.C.A Building Code and the following specifications, if any, submitted herewith and the following specifica-
iuns:  1.0 CATION  1.19-121 Bracke  1. Owner's name and address  2. Lessee's name and address  3. Contractor's name and address  4. Architect  Proposed use of building dwelling  Last use same  Material  Other buildings on same lot  Estimated contractural cost \$ 3,00  FIELD INSPECTOR—'vir.	Ley Bros, 52 Plesses Specification of the state of the st	Fire District #1 [], #2 []  Telephone B603-883-9971  Telephone 772-8573  No. of sheets  No. families 4  Telephone 772-8573  To sheets of plans 4  Telephone 772-8573  Telephone 772-8573  To sheets No. of sheets 15,00  The side 15,00  Telephone 772-8573  T
Demolitions		SOUTH STREET, PORTLAND, ME. 04111
Other APPLICANT: Sengrate	permits are required by th	ne installers and subcontractors of heating, plumbing, electri-
al and mechanicals.		
PERM	IIT IS TO BE ISSUED TO	0 1 2 2 3 5 4
		Other:
Is connection to be made to public se	wer?	Is any electrical work involved in this work?  If not, what is proposed for sewage?  Form notice sent?
Height average grade to top of plate  Size, front depth  Material of foundation  Kind of roof R	No. stories Thickness, t	solid or filled land? earth or rock?
		Bridging in every floor and flat roof span over 8 feet. d, 3rd, roof
	200	a 3rd, 1001
	n.	310, 1001
Maximum span: 1st flo	walls, thickness of walls?	height?
	T12 A A	CADAGE
1 4-3		modeted number commercial cars to be accommodated
No. cars now accommodated on sai	other than minor repairs	to cars habitually stored in the proposed building?
	DATE	MISCELLANEOUS
APPROVALS BY: BUILDING INSPECTION—PLA ZONING: A.A.A.A.A.A.A.A.A.A.A.A.A.A.A.A.A.A.A.	N EXAMINER	Will work require disturbing of any tree on a public street?
BUILDING CODE:		Will there he in charge of the above notice a person
Fire Dept.:		to see that the State and City requirements pertaining thereto are observed?
Health Dept.:		سد بر متیم سر ۱
Others:	//	Mark B. Joley Phone # same
Signa	ture of Applicant	low Brosthers
Туро	Name of above FO.	ley Brosthers 1 2 3 4 1

FIELD INSPECTOR'S COPY

dis.	-, 73-338/	PERMIT TO INSTALL PLUMBING  Address 119-121 Brackett St PERMIT NUI  Installation For: multiple  Owner of Bldg: Gail B. Bouchard- c/o Mar	k Foley
N.	Issued	Owner's Address 9 South St. Date:	3-31-80
A.	Portland Plumbing Inspector		FEE
•	By ERNOLD R. GOODWIN	NEW REPL A SINKS	8 00
	Eng First Inst.	The state of the s	8,00
	App. That Larry	4 LAVATORIS 1980 MAY 2.1 193	
	App. First Institute	- avy grups	4 <del>30</del>
	App. Rhal Insp.	SHOWERS	
	and Final Insp.	A DRAINS FLOOR SURFACE	4 00
	The state of the	A HOT WATER TANKS	_ <del></del>
	Date 5 50%	TANKLESS WATER HEATERS	-5
	Ву	GARBAGE DIST COTTES	
	Typo of Bldg.	SEPTIC TANKS  1 HOUSE SEWERS	50
	[7] Commercial	5 - 1 HOUSE SEWERS	7:70
	Residential	1980 ROOF LEADERS AUTOMATIC WASFIES	
	Single	DISHWASHERS	
1	Multi Family	OTHER	
يجمهد	New Construction	base	3.00
	Remodeling		30050:
		ТОТА	L BRANCE
		and Inspection Services Dept. Plumbing Inspection	35.50

.3.

ń



## APPLICATION FOR PERMIT

## DEPARTMENT OF BUILDING INSPECTIONS SERVICES ELECTRICAL INSTALLATIONS

March 10

Date XXMXXXXX

Receipt and Permit number \_\_A 45596 To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine: The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications: LOCATION OF WORK: 121 Brackett Street OWNER'S NAME: MIEN FOLLY ADDRESS: 52 Pleasant St. Course FEESO408 2
OUTLETS: Cail B. Bouchard RFD 3 Torbes have South Upingthen FEESO408 2 Receptacles Switches Plugmold ft. TOTAL 31-60 FIXTURES: (number of) Overhead XX Underground Temporary TOTAL amperes 400 / MOTORS: (number of) Fractional\_\_\_\_ 1 HP or over \_ COMMERCIAL OR INDUSTRIAL HEATING:
Oil or Gas (by a main boller) Oil or Gas (by a main boiler) \_\_\_\_\_ ...... Oil or Gas (by separate units)\_\_\_ Electric Under 20 kws \_\_\_\_\_Over 20 kws \_\_\_ APPLIANCES: (number of) Water Heaters Ranges Disposals Cook Tops Dishwashers Wall Ovens Compactors Dryers Others (denote) Fans TOTAL MISCELLANEOUS: (number of) Branch Panels \_\_\_\_\_ \_\_\_\_\_\_ Air Conditioners Central Unit \_\_\_\_\_. Separate Units (windows)

Signs 20 sq. ft. and under ..... Swimming Pools Above Ground In Ground Fire/Burglar Aiarms Residential Commercial \_\_\_\_ Heavy Duty Outlets, 220 Volt (such as welders) 30 amps and under \_\_\_\_\_.... over 30 anips\_ Circus, Fairs, etc. Alterations to wires Repairs after fire Emergency Lights, battery\_\_\_\_ Emergency Generators \_\_\_\_\_ INSTALLATION FEE DUE: FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT ..... DOUBLE FIE DUE: FOR REMOVAL OF A "STOP ORDER" (304-16.b) 44.00 TOTAL AMOUNT DUE: 1st floor apt. ready tomorrow INSPECTION: Will be ready on \_\_\_\_\_\_\_, 19\_\_; or Will Call CONTRACTOR'S NAME: \_\_\_\_\_\_\_Breggia Electric 15 East Kidder St. ADDRESS: TEL. SIGNATURE OF COMPRACTOR: MASTER LICENSE NO.: LIMITED LICENSE NO .:

INSPECTOR'S COPY -- WHITE
OFFICE COPY -- CANARY
CONTRACTOR'S COPY -- GREEN

INSPECTIONS: Service by	P B F C C F
Service called in	ELE Permit N Location Cowner Owner of i Date of i Final Ins By Insper
Closing-in 3-11-80 by hely	ELECTRI Permit Numbe Location Cowner Date of Permit Pfinal Inspectio By Inspector By Inspector
PROGRESS INSPECTIONS: 3-27-80, 7-28-fg	ELECTRICAL Permit Number Location
4-10-80, 7-30-80	Permit Number 4533  Location 121822  Location 121822  Owner 12182  Date of Permit 3-10  Final Inspection 7-32  By Inspector 222  Permit Application Register Page
CODE 4-23-87	INSTALL VISTORIAL VISIT PROPERTY PROPER
COMPLIANCE 57-58-50	# Plant Barry
1 37 749	Z' (25) 1 1/2/01/5 (1) =
COMPLETED 6-10-80	LATIONS - SOLUTIONS - SOLUTION
DATE 7-31-60	8 0 ° 6 i
DATE: REMARKS:	
3-11-50 First floor Char	-
3-27-80 Hay of 1st floor + all 6) 2-ud	Ploor closed in
with a distribution of the	
4-10-80 Panels wired worns.	- seul
not all writing drope.	

f managed !!

March 18, 1980

Noral Realty Trust 4 Rand Road Cape Elizabeth, Me. 04107

Re: 119 Brackett St.

As notified to you in a previous letter, a permit is required for the work being done at the above address. Our files indicate that no permit has been applied for and work has been illegally continuing.

Also according to Mr. Goodwin, the local Plumbing Inspector, no plumbing permits have been taken out as required by law.

It is necessary to come in within 10 days of the receipt of this letter to apply for a building permit. If at the end of that time no permit has been applied for, legal action will bw pursued. Please be notified that there is up to \$1000. fine per day of violation.

Work is to cease until all proper permits have been applied for and issued.

Yours truly,

Margo Schmuckal Building Inspector

\_\_\_\_



### APPLICATION FOR PERMIT

### DEPARTMENT OF BUILDING INSPECTIONS SERVICES ELECTRICAL INSTALLATIONS

Dec. 5

	Receipt and Permit number A 397
To the CHIEF ELECTRICAL INSPECTOR Portland,	Maine:
The undersigned hereby applies for a permit to make	co electrical installations in accordance with the laws of
LOCATION OF WORK: 1942 ME Brackett S	Electrical Code and the following specifications:
OWNER'S NAME: Mark Foley	ADDRESS: 52 Placeant St
	FEES
OUTLETS:	
Recept cles Switches Plugmo	ld ft. TOTAL
FIXIURES: ('iumper of)	
Incancescent Flourescent (no	t strip) TOTAL
SERVICES:	······································
Overload X Underground Manage	orary TOTAL amperes
METERS (number of) 4	rary TOTAL amperes 400 6.00
MOTORS (number of)	<u> </u>
He or over	
RESIDENTIAL HEATING:	
Electric (number of rooms)	
COMMERCIAL OR INDUSTRIAL HEATING:	
Oil or Gas (by a main boiler)	
(4) or Gas (by separate units)	
Over 20 kw	3
APPLIANCES: (number of)	
Ranges	Water Heaters
Cook Tops	Disposals
	Dishwashers
	Compactors
Fans	Others (denote)
TOTAL MISCELLANEOUS: (number of)	
Branch Bands	
Branch Panels	
Transformers Air Conditioners Central Unit	
Separate Unite (windows)	
Signs 20 sq. ft. and under	
Over 20 sq. ft.	***************************************
Swimming Pools Above Ground	
in Ground	
Fire/Burglar Alarms Pesidential	***************************************
Commercial	
Heavy Duty Outlets, 220 Volt (such as welders)	30 amps and under
	over 30 amps
Circus, Fairs, etc.	***************************************
Alterations to wires	***************************************
Repairs after fire	***************************************
Emergency Lights, battery	***************************************
Emergency Generators	
FOR ADDITIONAL MODE NOT ON OPICIAL THE	INSTALLATION FEE DUE:
FOR REMOVAL OF A "STOP OPDER" (304 161)	MIT DOUBLE FEE DUE:
FOR REMOVAL OF A "STOP ORDER" (304-16.b)	
	TOTAL AMOUNT DUE:
INSPECTION:	
10 ( 00	Will Call
CONTRACTOR'S NAME: Breggia Electric	WIII Call
ADDRESS: 15 East Kidde	n St
TEL.:	J. N. U. a
MASTER LICENSE NO.: 393.	SIGNATURE OF CONTRACTOR:
LIMITED LICENSE NO	The Sunday of th
And the second s	- san fullyser-

INSPECTOR'S COPY --- WHITE OFFICE COP" --- CANARY

CONTRACTOR'S COPY --- GREEN

December 6, 1979

Noral Realty Trust 4 Rand Road Cape Elizabeth, Maine 04107

Re: 119 Brackett Street

Dear Six:

It has been noted that alterations have begun on the building at the above location. Our files indicate that no building permits have been applied for as required by City Ordinance.

It will be necessary to come in immediately to apply for a permit


If you have any questions regarding this matter, please don't hesitate to contact this office.

Very truly yours,

Marge Schmuckal Building Inspector

MS/x

1



PERMIT 8660	PERMIT TO INSTALL PLUMBING	
TOUGH OUGH	Address: 919 60	3997
Video and	Installation For:	Si H
1695 A - 11 - C O		
CRILAND PLUMBING	Owner of Bldg.: The Leavened In see	<b>3</b> 17
INSPECTOR A	Owner's Address: IGU -11:1/	
By (1) (1) ale		
APPROVED FIRST INSPECTION	Plumber: Date:	4-11-1
	NEW REP'L INOPOSED INSTALLATIONS	NUMBER! FE
Dalo aks. 12-60	SINKS	
/	LAVATORIES	
BY JOSEPH P. WELCH	7 TOILES	5 %.0
APPROVED FINAL INSPECTION	BATH TUBS	0-60
	3 SHOWERS V	2 1
Dato May 10-60	DRAINS	7.6
• // ·	HOT WATER TANKS	
BY JOSEPH P. WELCH		·
TYPE OF BUILDING	TANKLESS WATER PEATERS	
COMMERCIAL	GARBAGE GRINDERS	
☐ RESIDENTIAL	SEPTIC TANKS	
SINGLE	HOUSE SEWERS	
MULTI FAMILY	ROOF LEADERS (conn. to house drain)	
NEW CONSTRUCTION		
REMODELING		6 dille

Mary .



### SI M. DEFENSION APPLICATION I

AND

Class of Building or Type of Structure Third Class	JAN 25 1500
Portland Mains	CITY of PULTL
The undersigned here by applies for a permit to erect alter repair demolish install the following in accordance with the Law f the State of Maine, the Euilding Code and Zoning Ordinance of the specifications, if any, submitted herewith and the following specifications:  Location 119 Brackett St. Within Fire Limits?  Owner's name and address Leonard Morse, R.F. D 1 Gray Road Cumb is ad C Lessee's name and address owner  Lessee's name and address owner	building structure equipme city of Portland, plans an yes Diet No
Lessee's name and address Me	tr. Telephone
Contractor's name and address owner  Architect Specifications	Telephone
Proposed use of building po	. relephone - //ou
WEST TIMES TO THE USE	No familian 6
No. stories 3	No. familles (a
Other buildings on same lot	Roofing
Estimated cost \$ 100.00	•
General Description of New Work	Fee \$ .50
To partition off ton (2)	
To partition off for (3) rew bathrooms on first floor.  2x3 studs16" o.c. covered with sheetrock on both sides.  To be verted as approved by Health Dept.	
6. Co-to the same 1/22/12	Vinca .
Hills 7 4 6 reguling and man	And the property of
from 3 sed flower.	1 8
6. 6- to the solution 122/12	ماسه واستعماله
It is understood that there is	•
It is understood that this permit does not include installation of heating apparatus which is to be taken the name of the heating contractor. PERMIT TO BE ISSUED TO CHART	n out separately by and in
Is any plumbing involved in this work?  Is connection to be made to public sewer?  Has septic tank notice been sent?  Height average grade to top of plate  Size, front  depth  No. stories  Details of New Work  Is any electrical work involved in this more involved in this proposed for sewage?  Form notice sent?  Height average grade to highest point of size, front  Size, front  Material of found to	
Size, front	rth or rock?
Material of underpinning	******
Rich per foot	55
No. of chimneys	
Size Girder	fuel
Attituding thickness of outside sheathing of exterior and the shea	centers
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof st	
Joists and rafters: 1st floor	oan over 8 feet.
On centers: 1st floor	roof
Maximum span: 1st floor, 2nd, 3rd,  If one story buildin , th masonry walls, thickness of walls?,	roof
If one story buildin, th masonry walls, thickness of walls?	1001 """" " 1001
No. cars now occurred to the Garage	4g11tf
the title now accommodated on same lot	00 2000mm - 1- 4 - 1
maditually stored in the proposer	build no?
Miscellancous	
Will work require disturbing of any tree on a	uhlia utrasa i
Will there be in char, the above week	
	ertaining thereto are
observed? Yes Leonard Morse	5 moreto are
by:	
INSPECTION COPY Signature of owner	`\

t:m

Final Inspn.
Final Inspn.
Cert of Occupancy is
Staking Out Notice
Form Check Notice NOTESfrome 6150 Oil r bublings c : Switeles ? bolfod down . (1) Should have Firedorr With the hour till, at 2 nd floor connection 1-60 Closoq nothing Further done 13- 60 Closed 6-1-60 Somewha done balt tich i sa sa e. :7: AACO HOLLIGHAMI Water I Y I The Table

CITY OF PORTLAND

Department of Building Inspection

Permit #	

With reference to your building under construction at

a Certificate of Occupancy from this Department is required BEFORE THIS BUILDING IS OCCUPIED.

The Building Code provides that notice shall be given to this office of readiness for final inspection, and that final inspection shall be made within two full working days of such notice.

Please cooperate with this office by giving notice so that there may be sufficient time for final inspection and issuing the Certificate of Occupancy before you plan to occupy the building. It is not necessary that the building be completely finished before final inspection, as we are not interested in the painting, papering, etc. In event, your building is intended to accommodate a number of families, or is a mercantile building with several different tenants, we shall be pleased to make final inspection and issue the certificate covering a part of the building if more convenient for you.

Very truly yours,

Warren by

Inspector of Buildings

McD/H

#P- 119-121 Brackett St.

Feb. 1, 1960

Nr. Leonard Morse RFO 1, Gray Road Cumberland Center

Dear Mr. Morse:

Upon making an inspection under the building permit for which you applied on Jan. 29th, our Field Inspector noted a structural condition in the basement which is called to your attention with the thought that it will be well to care for the matter now, rather than let it go to such a point where this department would find it necessary to issue orders for safety.

He noted that the main carrying girder at the rear of the chimney has no column for support under the end near the chimney. It is suggested that you provide a suitable steel column fastened to the girder and supported upon a suitable foundation at the level of the cellar floor.

Very truly yours,

Warren McDonald Acting Deputy Insptr. of Bldgs.

WMcI):m

MAINE PRINTING CO. COST, AND

CITY OF PORTLAND HEALTH DEPARTMENT HOUSING DIVISION



Loc. 119-121 MixCh CT 87. Loc w/i S WING. Bldg Fire Elec. Other Issued March 23, 1960 Expires April 23, 1960

Kr. Koland Despositors 160 Klyb Street Portland, Maine any) cr

Mr. Locord Force 19. Kigh threat Portland, Midno

Housing Supervisor

#### VIOLATIONS & SPECIFICATIONS

## Responsibility of Owner or Agent \*\* Responsibility of Occupant

eppair and fact in good order all dilapidated and becarding parts of the abresture on Repair or replace the Loose, and troken floor boards on the yords of 119 Brackett. Repair or replace the Loose door knots on the front door of 6121 and in the front bedreen of the 3rd floor ept. Negatir or replace the dilapidated parts of the coors in the bethings and kitchen of the 2nd floor reapte, and in the kitchen of the 2nd floor front wite lugair or replace the leese, som, broken, or missing drain pipe exciten on the 6 rivert aldo of #121, supair or replace the broken and dilaphisted parts of the roof over the front door of All. replace the all olds bricks and point up the losse faints on the front and alde of the skio talk. Remove the obstruction in the mar hall of the 20st floor. E haplace the mi-sing balanters on the from statumy from the let to the 3rd floor. family or oplace the lance relike along the front staining from the lat to the \$. 2mil filone. george on entress my rough nouse payor on upports proud on the collic usuable. Publy the loans elater comer, thirten his loose elater and living room and histophone to of the lat floor front opt., in the kitchen and living room the let floor rear spt., in the kitchen, and ladress (rear) of the lad floor rear spt., in the kitchen, middle bedress, and ladress (rear) of the lad floor rear spt., in the kitchen, middle bedress, and ladress (rear) of the lad floor rear spt., in the kitchen and bedress of the lad floor front opt., and throughout the 3rd floor app. 2. hoplace the broken wisdow reases in the coller and in the front of the 3nd ficar Regular or replace the creaters, loops, or chester pleater on the valle of the front and rear tail of the let and End Cloops, in the iditions amount of the let floor rear oft., in the rear bedroom of the 2nd floor rear aph., throughout the and floor from aph., and in the front bedroom and rear bedroom of the 2nd floor aph. height or regions the emoked, loose, or similar plactor on the ceiling of the living room in the let ficer front apt., in the rear beduces of the 2nd floor rear opts, in the kitchen of the 2nd floor front a t., and in the emer bedroom of the

In clair spt. In the set.

Determine the reason and record the condition with now cause the kitchen culture. ٥. to show after of location of the first the state of the floor and the first of the floor in the contract of the state of t P. Ç, the and believes of the lat floor left distributor attaching to directed to the content of the first top and the first top the first top and top and to the first top and top and to the first top and t morphism from the first state of the state of the first of the first of the state o the structure. Somired all defective electric edging and electrical equipment thereighout the finite of replace the defective fixtures in the tear hall of the 2nd floor in the internal and floor from halls, is the mining becomes of the 2nd floor floor in the internal floor that is wiring is defective throughout the entire ethnology. the toliscon and from technical of the M filter app.

One countries that the viring is defective disconstant the whire ethnicals of the M filter appropriate the contribution of the M filter appropriate the fi ۸, The inflaction rescale that the miring is detective throughout the entire ethics and a confidence of the confidence of t ٥. The Liver space of the persons of the graph too the constitute engine of the following the constitute of the constitute of the persons of the confidence of Ľ. decomplied a general element of the lest side of the less the party in the fresh and recently the containing and property discovery decomplished to the collections and decomplished to the party of the À. his the president of the some for you. If you are made to do the formal obtained with 遊奏 the time at the important was now made to have all interests and in the state index to make the state index to make the formation of the left flow made in the interest of the left flow. The along the continues consider are in statistics of the city Ordinance, Million and the corrected on or before April 23, 1960.

Loc wals 221 Freshett Fig.

Bldg Fire Elec gother

Issued 1955

Expires the part of 1955

CITY OF PORTLAND HEALTH DEPARTMENT HOUSING DIVISION

Fr. Looperd Reres 194 Eigh Street Fortlead, Palca

n 01-:	an evaminati	on was made of the premises located
Dear Sir:	THE PARTY AND THE PARTY NAMED TO BE ADDRESS OF THE PARTY NAMED TO	*
at	th the ordinances relating to industry ordinance, you a	are hereby ordered to hereby o
defects according	to specializate nermits	s which are to be obtained atom
Decessione resu	These must be	obtained before the series Office.
Building Inspect If any	additional information is desired, visit of telepron as a	11 corrections have been completed.
telephone 4-1431	, extension 220. Ve	ery truly yours, ward W. Colby, M.D.
. · ·	, He	ealth Director
•	By	using Supervisor
**	VIOLATIONS & SPECIFICAT	IONS
" San "	## Responsibility of Owner or Agent ** Respons	ibility of Occupant
	## Responsibility of Oxnor	a commentation of a state of the
W 114	m respective superiors oil defective plantic	SEC BIVEREAMS
the	de and have represented the convenient of any and any convenient	tly located within
(20	install a private flux tellet occident provincet or install a flux tellet con-	reducing something fix
1.	install a framework of install a fluor tellar com- operations which pay be shared. Provi the attractors which pay be shared to too to openhorie who used there do not tovo to	later through anather distilled
1 1 1	which the state where the the time	a tollet. (You will pate
1 1 1	the attractors who used where do not tovo to exchapted who used where do not to the fine that is under to pain account to the fine faction of Tollet Faci little abstracy no faction of Tollet Faci little abstracy no	d area tost to equility
1 1 1	rattice 7, collect first velleto) matte ray shere one flesh velleto)	the second second
111.	mails one above one floor tollate. Include the trop makes the bitches sink is	the true tract that
(d	51 - 121.	
9.8 254	#1 - 121. MATTIFEE TEXTUREDE MODE WAS DEPOSITED BLE SETTIFEETS	ric wiring and ploperions
	was way pras rebried all colors	A A D A SE WENT A SECOND
735	CIDANA CHILDREN TO THE STATE OF	SALES
	raincent throughout the anticte is the confinence outlets is the confinence outlets in the confinence of the confinence	se of extension floor after
111	the attention to directed to the test	The second second
111	ment 63 - 117. ) Replace the closing fluture in the beth	trees of the sector floor
1   1	) Wasters the missing respect to the	** ***********************************
	apartment #3 - 1/1.	the state of the
19 3	sportment of a large order all dilaridate order and put in sooi order all dilaridate order order all dilaridate order	the state the state of the stat
	processes de culturas	first floor sportscat ed - ally
	spair and put in 1000 dreve all than of the all intell a Midden in the Litchen of the all intell a Midden in the Litchen of the all intell a Midden in the Litchen of the all intelligences.	a the flore and constrained
	With the restaurant of the same of the party	COR ADMICTARING TOTAL
111	normal normalist with the expects of the creeked, house to be the creeked, house to be street floor upon	atilities and an engineer are a
111	acres of realize the crocked, house of	2 219
	b) begain or replace the enoched, hoose of its the testiness of the first floor uper its the testiness of the first floor uper	mailing which but there avigates
	b) begins or replace the first floor upon in the testrom of the first floor upon a) between the reson and remain the to of laskegs on the kitches callings in of laskegs on the kitches callings in	the first finor apartment and
1 1 1 1		(Cash)
	end appretinat is + 1190	
, , , ,		Loc.119-122 Breshets Ft.
	rision, Health Department Date	Loc w/i S" Bldg Fire Elect Other
To: Housing Div	Date Date	Bidg Fire Elect Other
From This is to	o inform you that deficiencies of which this Department h	Issued Sources 6, 1955
notified, have	o inform you that deliciencies of the property of the been corrected to our satisfaction.	Laplace
Remarks:		
		and the second s

orrections have been COMPLETED) (Please return to Housing Division of Health Department when

Structural Repairs - Continued

d) Replace the broken window pane in the bitchen window of the first
floor approach 18 - 119. e) Inter the loss vistor peace in the litates and bedress visions in the around floor spectment \$3 - 114. f) Install a window in the bed-com of the first floor spartness #2 - 121, the total sub area at least 1/12 of the floor ages, and so constructed so that at least 1/2 of the total are noy be open, ar install an approved evaluated ventilation system.

Separar or replace the cracked, licene or attending planter on the criling in the bedroom of the first floor operiment if - 1/1.

Patty the leads wisdow paper to the living room and bedroom windows

in the first flow spectages in the little read and section where is the first flow spectages in a life.

1) Seplece the broken whicher pure in the stile wisdow.

1) Replece the broken whicher pure in the stile wisdow.

1) Replece the broken of alaphasids at the left olds read of the structure life.

Rimport and Inconstruct Confidence at the left olds read of the structure life.

1) Provide an adaptate supply of solicite, sufficient, water-light, lightly, suffered setal garbage and subbled containers.

The shows continued conditions are in violation of the City Crotenances "Linksum Theodorin for Continued Cooppany", "Asthority to Vacute Dalidings" and "Carlege and Subbleb Containers" and must be corrected on or before August 6, 1955.

OF BLO'G. 183P. Y OF PORTLAND 1955 RECEIV Ģ DEPT. (

CITY OF PORTLAND, MAIN DEPARTMENT OF BUILDING INSP COMPLAINT OF BUILDING INSP COMPLAINT OF BUILDING INSP COMPLAINT Date Received 1/21/54	E F
1	•
Tenant's name and address WMcD	Telephone
	Telephone
Description: Of the three chimneys in the building there from and middle chimney and it looks from the street as masonry are defective.  NOTES://w/sq-Bettee-VW	are loose bricks at the top of the though the joints of the brick
74/04- hus Milligan can	in curl mll
The same to s	e of they are
to vad tricks and of por	reture them?
of the state of th	em condum.
Eline many under to le	o al a la contra de la contra del la contra del la contra del la contra de la contra del la contra de la contra de la contra del la contra del la contra de la contra del la co
good weather - M	The state of the s
This The Million con in De.	eddrown in now ( To
Starpork BS	
415/5%. Work is completed, us	7m
7	
A Company of the Comp	
The same of the sa	
The state of the s	
Section of the sectio	
A. 1. A. 1.	

C119-121 Brackett St. WMcD 2/15/54

0

February 3, 1954

Mr. James E. Milligan 119-121 Brackett St.

Our inspector finds that two of the three chimneys in the building which you are reported to own or control at 119-121 Brackett St. are in a Dear Mr. Milligan:-

As authorized and directed by Sect. 107 of the Building Code of dangerous condition above the roof. Portland (copy enclosed) you are hereby required to have these dangerous conditions permanently corrected before February 15, 1054.

Defects that are dangerous from the standpoint of falling and injuring persons or doing damage to property are evident in the front chimney and the middle chimney. Buth chimneys have one or more local butches of the chimneys persons or doing damage to property are evident in the front chimney and the middle chimney. Both chimneys have one or more loose bricks at the top which, if they should fall at time of high wind or otherwise would likely bounce down the steen roof and land in the word helds to the determent of anyone that might the steen roof and land in the word helds to the determent. the steep roof and land in the yard below to the detriment of anyone that might

It looks from the street also as though the joints of the brickwork in be there at the time.

While you are having a competent mason take care of the loose bricks at both chinneys are defective. the top of the chimneys, you should also have him go thoroughly over these the top of the chimneys, you should also have him go thoroughly over these joints and of course correct joints and rake or and points and the chimneys while he is up there, any other defects ich are evident in the chimneys while he is up there.

While he is working on the chimneys it would be well to make sure that while he is working on the chimneys it would be well to make sure that each chimney flue has a suitable cleanout door and frame at the bottom and that Very truly yours, the flues are cleaned out.

P. S. There is another rather high chimney in the rear which has one or more suys. Warren McDonald While your mason is there, please have him check over the safety of this one also, Inspector of Buildings and make good any defects.

Enclosure: Copy of Sect. 109 of the Bullding Code

#### Memorandum from Department of Building Inspection, Portland, Maine

February 1, 1954

Mr. Leonard Morse 194 High St.

Dear Mr.Morse:

Could you please tell us whether or not you own the property at 119-121 Brackett St? If you do not now own it would you be so kind as to let us know to whom you sold it.

ges Sin - Soed to James E. Mieligan Der 1 53

> (Signed) Warren McDonald Inspector of Buildings

PH

Hear Mr. Mexicald; 2001 Whis building was sold by us last summer to a Mr. Seonard Marse of bortland and it is our understanding that he has since resold it— To whom we do not brown to the form the format of the sold with the s

15 mg

1

Note that the second se

6

SECT..... 109. VIOLATIONS, DANGEROUS CONDITIONS. (Building Code City of Portland)
a. When any violation of any provision of this Code is found to exist, or
when any building, structure, plant, device, or object within the jurisdiction
of this Code is found to be broken, weakened or out of repair so as to be unsafe
or dangerous, the Inspector shall notify the owner of such violation or such
depressing conditions and shall order such above. dengerous, the inspector shall notify the owner of such violation or such dengerous condition; and shall order such change, repair, or alteration as deemed necessary to make good the violation or permanently correct such dengerous condition; and failure of the owner to conform to such an order within the time set forth in the order shall be a violation of this Code. Such a notice and order shall be sent by registered mail or handed to such owner, loft at his residence or at his or its usual place of business; or, if the owner cannot be located it shall be attached to the principal face or frontage of the premises involved. involved.

WARREN MCDONALD

On reply refer

CITY OF PORTLAND, MAINE

to file C 119-121 Brackett St. Department of Building Inspection

WMcD 2/1/54

January 22, 1954

Registered-Mail Return-Roccipt

Adrian H. & Bertha B. Vincent 112 Woodford St.

Dear Mr. & Mrs. Vincent:-

Our inspector finds that two of the three chimneys in the building which you are reported to own or control at 119-121 Brackett St. are in a dangerous condition above the roof.

As authorized and directed by Sect. 109 of the Building Code of Portland (copy enclosed) you are hereby required to have these dangerous conditions p rmanently corrected before February 1st, 1954. Set. 15, 1954

Defects that are dangerous from the standpoint of falling and injuring persons or doing damage to property are evident in the front chimney and the middle chimney. Both chimneys have one or more loose bricks at the top which, if they should call at time of high wind or otherwise would likely bounce down the steep roof and land in the yard below to the detriment of anyone that might be there at the time.

It looks from the screet also as though the joints of the brickwork in both chimneys are defective.

While you are having a competent mason take care of the loose bricks at the top of the chimneys, you should also have nim go thoroughly over these joints and rake out and point-up any defective joints, and of course correct any other defects which are evident in the chimneys while he is up there.

While he is working on the chimneys it would be well to make sure that each chimney flue has a suitable cleanout door and frame at the bottom and that the flues are cleaned out.

P. S. There is another rather high chimney in the rear which has one or more gurs. While your mason is there, please have him check over the safety of this one also, and make sood any defects.

Very truly yours

Warren McDonald Inspector of Buildings

(1) onemage

WMcD/G

Enclosure: Copy of Sect. 109 of the Building Code

0 119-121 Brackett St.

WMoD 2/1/54

January 22, 1954

Registered Moil Return Bacoins

Adrian H. & Bertha B. Vincent 112 Woodford Sts

Dear Mr. & Mrs. Vincent:-

Our inspector finds that two of the three chimneys in the building which you are reported to own or control at 119-121 Brackett St. are in a dangerous condition above the roof.

As authorized and directed by Sect. 109 of the Building Code of Portland (copy enclosed) you are hereby required to have these dangerous condiwions permanently corrected before February 1st, 1954.

Defects that are dangerous from the standpoint of falling and injuring persons or doing damige to property are avident in the front chimney and the middle chimney. Both chimneys have one or more loose bricks at the top which, if they should fall at time of high wind or otherwise would likely bounce down the steep roof and land in the yard below to the detriment of anyone that might be there at the time.

It looks from the street also as though the joints of the brickwork in both chimneys are defective.

While you are having a competent mason take cars of the loose bricks at the top of the chimneys, you should also have him go thoroughly over these joints and rake out and point-up any defective joints, and of course correct any other defects which are evident in the chimneys while he is up there.

While he is working on the chimneys it would be well to make sure that saith chimnly flum has a suitable cleanout door and frame at the bottom and that the fluor are clamed mit.

P. S. There is another rather high chimney in the rear which has one or more guys.
While your major is there, please have
him check over the safety of this one also, Very truly yours, and make good any defeats.

Warren McDoneld Inspector of Buildings

Enclosure: Copy of Sect. 109 of the Building Code

Building Importor Poilland Des Doar Sir -1-20-64 # 119 Brackett, St. Mas a chimney to ft in hight which is bearing with no grying that is all weady to fall over on othe brildings Vill you give it you alintion and see it is taken down Thanking you for you goovaption. your Troly a. Geighbor with children. of Bertha B. Vingens



FILL IN AND SIGN WITH INK

# APPLICATION FOR PERMIT FOR HEATING, COOKING OP POWER EQUIPMENT

**超别的** 1891街 02692 **637 9** 1947

Portland, Maine, October 3, 1947

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE	
The undersigned hereby applies for a permut to install the following hearing, cooking or power equipment to the Laws of Maine, the Building Code of the City of Portland, and the following specifications:	pment in accor
Location 121 Brack ett Strock V. Co. V.	
	New Builder
Name and address of owner of appliance Adrian H. Vincent, 121 112 Woodford St.  Installer's name and address Harris Oil Co., 202 Commercial St.  Telephone 2-	Exiating "
•	8304
General Description of Work	
To install oil burning equipment in connection with existing steam heat	
IF HEATER, OR POWER BOILER	
Escation of appliance or source of heat	
If wood, how protected? Type of noor beneath appliance	****
Minimum distance to wood or combustible material, from top of appliance or casing top of furnace  From top of smoke pipe. From front of appliance	
From top of smoke pipe From front of appliance From sides or back of appliance	
Size of chimney flue Other connections to come the	
11 gds irred, now vented?	****
Rated maximum demand per hour  IF OIL BURNER	
Name and type of hurner Quiet Heat	
Will operator be always in the state of the control	yes
Type of floor beneath burner concrete	bottom
Location of oil storage had an and	
If two 275-gallon tanks, will three-way valve he provided?	existing
will all tanks be more than five feet from any flame?	*****
Total capacity of any existing storage tanks for furnace humans	******
274.0	******
Location of appliance Kind of fuel The Cooking Appliance	
If wood how protected	
· · · · · · · · · · · · · · · · · · ·	
Minimum distance to wood or combustible material from top of appliance  From front of appliance	
Size of chimney flue Other connections to same flue	
Is hood to be provided?	
If gas fired, how vented?	***
If gas fired, how vented?	
MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION	
	******
en de la companya de	
to the state of th	
Amount of fee enclosed? 1.00 (\$1.00 for one heater etc. 50 annually	
Amount of fee enclosed? 1.00 (\$1.00 for one heater, etc., 50 cents additional for each additional	tc., in same
Will there be in charge of the above work a person consecutive that the State and City requirements pertaining observed? Yes	empetent to thereto are
INSPECTION COPY Signature of Installer By: Audio Landing	·

Permit No. 17/2682  Location 121 Bruckett St.  Owner advisor Vincent  Date of permit 10/9/47  Approved 1-29.48 Prof.  NOTES	Me ig Time was jumished	W.
1 Fill Pipe		
8 Kind of Heat		
d Burner Rigidity & Supports		
6 Name & Label		
O track to stry		
7 High Lin is Control		
8 Remote control.		
10 Valves in a quy tan		***
11 Capacity of aks		
12 T 66 Ru 1 3 & Suppletts		
18 Tuck December		
No.		
16		
1.20.48 Nald		
Diner Totale		
Sono taller 115		A 6.
card. To withe		ر بر المراجع ا المراجع المراجع
- Company		

FILL IN COMPLETELY AND SIGN WITH INK

PERLAIT ISSU TO



## APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER COULD NOT

Portland, Maine, //- /2 - 38-To the INSPECTOR OF BUILDINGS, PORTLAND, ME. The undersigned hereby applies for a permit to install the following hating, cooking or power equipment in the undersigned nereby applies for a permit to install the following Frating, cooking or power equipment reduce with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Use of Building Name and address of owner Maine Contractor's name and address Harris Off 32 97 Main General Description of Work IF HEATER, POWER BOILER OR COOKING DEVICE Is heater or source of heat to be in cellar? If not, which story Material of supports of heater or equipment (concrete floor or what kind)\_ Minimum distance to wood or combustible material, from top of boiler or casing top of furna \_, from front of heaterfrom top of smoke pipe \_\_ \_ Other connections to same flue. Size of chimney flue\_ F OIL BURNER Labeled and approved by Underwriters' Laboratories? Name and type of burner-Type of oil feed (gravity or pressure)\_ Will operator be "iways in attendance? .No. and capacity of tanks\_ Location oil storage... Will all tanks be more than seven feet from any flame? YELHow many tanks fireproofed?\_ Amount of fee enclosed? 100 (\$1.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.) INSPECTION COPY

IMPI DOLLOW

-

20/1000		-
Ward Permit No. 38/1993		_
Location 121 Bracket Street		
Owner mainled ount Bed, and		-
Date of permit 11/12/38		
Post Card sent	The second secon	_
Notif. for inspu.		_
Approval Tag issued 1/7/69, UKO,		<del>-</del>
Oil Burner Check List (date) 1/7/37	1	
1. Kind of heat Str 2.71		_
2. Label		7
3. Anti-siphon	-	
4. Oil storage		
5. Tank distance		- ,
7 6. Vent pipe		-,
7. Fill pipe		14
8. Gauge		
9. Rigidity		
10. Feed safety		
11. Pipe sizes and material		$ \diamond$
12. Control valve		
13. Ashi pit veht		<u>'</u>
14. Temp. or pressure safety		
15. Instruction card	7,	
16. Vantt O Statinsniky		
NOTES		
2 5 L + B 2-5434	<u> </u>	
The state of the s	1	. #

el resident