

CERTIFICATE 0 F COMPLIANCE

CITY OF PORTLAND

May 22, 1978

Department of Neighborhood Conservation Housing Inspections Division Telephone: 775-5451 - Extension 448 - 358

Mrs. Leona E. Thompson 207 State Street Portland, Haine 04101

Premises located at _____ 207 State Street, Portland, Maine NCP-WE Dear Mrs. Thompson: A re-inspection of the premises noted above was made on ____May 19, 1978 by Housing Inspector Leary This is to certify that you have complied with our request to correct the violation of the Municipal Codes relating to housing conditions as described in our "Notice of Housing Conditions" dated October 28, 1977 Thank you for your cooperation and your efforts to help us maintain decent, safe and sanitary housing for all Portland residents. In order to aid in the preservation of Portland's existing housing inventory, it shall be the policy of this department to inspect each residential building at least once every five years. Although a property is subject to re-inspection at any time during the said five year period, the next regular impection of this property is scheduled for _____1953

Sincerely yours, Joseph E. Gray, Jr., Director Neighborhood Conservation

Lyle D Noyes,

Chief of Housing Inspections

NOTICE OF HOUSING CONDITIONS

Fity of Postland		
Department of Neighborhood Conservation Tousing Inspections Division	ChBiLot: Location:	46-C-24 207 State Street
Tel. 775-5451 - Exc. 358 - 448	Project:	MCP-West End
Mrs. Leona E. Thropson 207 State Street Fortland, Maine 04101 DATE 5-19-20	Fasued: Expired:	October 28, 1977 Jan. 28, 1978
Dear Hrs. Thompson:		
An examination was made of the premises at Maine, by Housing Inspector Leary Housing conditions were found as described in de	. Violations of Munic	, Portland, cipal Coues relating to
In accordance with provisions of the above defects on or before	. You may contact this to make such repairs wil we do not hear from you set forth above, will as	s office to arrange a thin the specified time. I within ten days from Acticipate that the
Your cooperation will help this Department in i decent, safe and sanitary housing.	ts goal to maintain all	Portland residents in
	Very truly you	ırs,
	Joseph E. Gray	y, Jr. Director
	Neighborhood	onservation
Inspector	Neighborhood	onservation
Inspector	By Lyle D. Noyes	ing Inspections
H. Leary	By Lyle D. Noyes Chief of House	ing Inspections
M. Leary EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S"	By Lyle D. Noyes Chief of House TANDARDS FOR HOUSING" -	ing Inspections
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S"	By Lyle D. Noyes Chief of House TANDARDS FOR HOUSING" -	ing Inspections
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S" FIG. FRONT-GELLAR FOUNDATION - replace missing- FIRST FLOOR FRONT FRAR EEDROOM CEILING - determine the room	By Lyle D. Noyes Chief of Hous: TANDARDS FOR HOUSING" -	ing Inspections Section(s) 3a
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S" FIG. FRONT-GELIAR FOUNDATION - replace missing- FIRST FLOOR FRONT At the time of the survey the following were	Neighborhood By Lyle D. Noyes Chief of House TANDARDS FOR HOUSING" - ENEIGH	Ing Inspections Section(s) 3a tion: causing lookege, 3b
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S'	Neighborhood By Lyle D. Noyes Chief of House TANDARDS FOR HOUSING" - FARTER FOR AND TO BE TO	Ing Inspections Section(s) 3a tion: causing lookese: 3b or FIRST FLOOK REAR, THE PLOOK LIGHT APARTMENTS.
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S' FIG. FRONT-GELAR FOUNDATION - replace missing- FIRST FLOOR FRONT At the time of the survey the following were SECOND FLOOR FRONT OF REAR, SICOND FLOOR RIGHT We suggest that if there are the conditions make the repairs while doing the work on the	Neighborhood By Lyle D. Noyes Chief of House TANDARDS FOR HOUSING" - ENERTHY FOR HOUSING" - ENERTHY FOR HOUSING - TANDARDS FOR HOUSING" - ENERTHY FOR HOUSING - TANDARDS FOR HOUSING" - ENERTHY Which need corrections FOR HOUSING - TANDARDS FOR HOUSING" - TANDARDS FOR HOUSING" - ENERTHY - TANDARDS FOR HOUSING" - ENERTHY - TANDARDS FOR HOUSING" - ENERTHY - TANDARDS FOR HOUSING" - TANDARDS FOR HOUSING" - ENERTHY - TANDARDS FOR HOUSING" - TANDARDS FOR HOUSING" - ENERTHY - TANDARDS FOR HOUSING -	Ing Inspections Section(s) 3a tion: sausing lookese, 3b or FIRST FLOOK REAR IND FLOOR REAR APARTMENTS. B. Wood-counterness that way
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S' FIG. FRONT-GELLAR FOUNDATION - replace missing. FIRST FLOOR FRONT At the time of the survey the following were SECOND FLOOR FRONT OF REAR, SECOND FLOOR RIGHT We suggest that if there are England the content of the repairs while doing the work on the	Neighborhood By Lyle D. Noyes Chief of Hous: TANDARDS FOR HOUSING" - EAUTER. FOR SAIL TENEDY the condition of the condition of the structure. IN USITS	Ing Inspections Section(s) 3a tion: sausing lookese, 3b or FIRST FLOOK REAR IND FLOOR REAR APARTMENTS. B. Wood-counterness that way
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S' FIG. FRONT-GELLAR FOUNDATION - replace missing. FIRST FLOOR FRONT At the time of the survey the following were SECOND FLOOR FRONT & REAR, SECOND FLOOR RIGHT We suggest that if there are Eny conditions— Take the repairs while doing the work on the SECOND FLOOR RIGHT FRONT & RIGHT MIDDLE ROOM 3. BEDROOM WINDOWS - repair imperative Jacks	Neighborhood By Lyle D. Noyes Chief of Hous: TANDARDS FOR HOUSING" - EAUTER. FOR SAIL TENEDY the condition of the condition of the structure. IN USITS	Ing Inspections Section(s) 3a tion: sausing lookese, 3b or FIRST FLOOK REAR IND FLOOR REAR APARTMENTS. B. Wood-counterness that way
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S'	Neighborhood By Lyle D. Noyes Chief of Hous: TANDARDS FOR HOUSING" - FORTAGE TOTAGE TOTA	Ing Inspections Section(s) 3a tion: sausing lookese, 3b or FIRST FLOOK REAR IND FLOOR REAR APARTMENTS. B. Wood-counterness that way
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S' 5-/51. FRONT GELLAR POUNDATION replace missing. FIRST FLOOR FRONT At the time of the survey the following were SECOND FLOOR FRONT OF REAR, SECOND FLOOR RIGHT We suggest that if there are the cord on the SECOND FLOOR RIGHT FRONT & RIGHT MIDDLE ROOM 3. REDROOM WINDOWS repair inoperative 283h 5-/SECOND FLOOR REAR ROOMING UNIT 4. DEDROOM WINDOWS replace missing counterby	Neighborhood By Lyle D. Noyes Chief of Hous: TANDARDS FOR HOUSING" - FORTAR White and ready the good; TRONG MIDDLE, AND TO White need correcting of TASE of the structure.	ing Inspections Section(s) S
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S'	Neighborhood By Lyle D. Noyes Chief of Hous: TANDARDS FOR HOUSING" - FORTAR White and ready the good; White and ready the good; White and correcting for the structure. The structure of the	ing Inspections Section(s) S
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S' -/1: FRONT GELLAR POUNDATION replace missing FIRST FLOOR FRONT	Neighborhood By Lyle D. Noyes Chief of Hous: TANDARDS FOR HOUSING" - FARTAR, BOIL and Yeardy the conditionable to gain access to leave the conditional contenting of the structure. Whence cords allowing with the cords of the structure. TO BE GIVEN TO ITEMS WE SAFETY OF THE OCCUPANTS	ing Inspections Section(s) 3a tion: causing lookage: 3b or FIRST FLOOK REAR; IRD PLOOK
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S' -/1: FRONT GSLIAR POUNDATION replace missing FIRST FLOOR FRONT	Neighborhood By Lyle D. Noyes Chief of Hous: TANDARDS FOR HOUSING" - FORTAR, BOIL and Yeardy the conditional section of the structure. FIROMY & MIDDLE, AND TO THE OCCUPANTS SAFETY OF THE OCCUPANTS Building Juspection Departments	ing Inspections Section(s) 3a tion: causing lookage: 3b or FIRST FLOOK REAR; HRD PLOOK REAR; A shoot-epartments that you 3c ndow-eash-to-resein 3c ITH ASTERISKS, AS THEY OF THIS STRUCTURE. Etment. 389 Congress St.
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S' -/1: FRONT GELLAR POUNDATION replace missing FIRST FLOOR FRONT	Neighborhood By Lyle D. Noyes Chief of Hous: TANDARDS FOR HOUSING" - FORTAR, BOIL and Yeardy the conditional section of the structure. FIROMY & MIDDLE, AND TO THE OCCUPANTS SAFETY OF THE OCCUPANTS Building Juspection Departments	ing Inspections Section(s) 3a tion: causing lookage: 3b or FIRST FLOOK REAR; HRD PLOOK REAR; A shoot-epartments that you 3c ndow-eash-to-resein 3c ITH ASTERISKS, AS THEY OF THIS STRUCTURE. Etment. 389 Congress St.
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S' -/1: FRONT GSLIAR POUNDATION replace missing FIRST FLOOR FRONT	Neighborhood By Lyle D. Noyes Chief of Hous: TANDARDS FOR HOUSING" - FORTAR, BOIL and Yeardy the conditional section of the structure. FIROMY & MIDDLE, AND TO THE OCCUPANTS SAFETY OF THE OCCUPANTS Building Juspection Departments	ing Inspections Section(s) 3a tion: causing lookage: 3b or FIRST FLOOK REAR; HRD PLOOK REAR; A shoot-epartments that you 3c ndow-eash-to-resein 3c ITH ASTERISKS, AS THEY OF THIS STRUCTURE. Etment. 389 Congress St.
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S' -/1: FRONT GSLIAR POUNDATION replace missing FIRST FLOOR FRONT	Neighborhood By Lyle D. Noyes Chief of Hous: TANDARDS FOR HOUSING" - FORTAR, BOIL and Yeardy the conditional section of the structure. FIROMY & MIDDLE, AND TO THE OCCUPANTS SAFETY OF THE OCCUPANTS Building Juspection Departments	ing Inspections Section(s) 3a tion: causing lookage: 3b or FIRST FLOOK REAR; HRD PLOOK REAR; A shoot-epartments that you 3c ndow-eash-to-resein 3c ITH ASTERISKS, AS THEY OF THIS STRUCTURE. Etment. 389 Congress St.
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S' FIG. FRONT-GELLAR FOUNDATION - replace missing FIRST FLOOR FRONT At the time of the survey the following were SACORD FLOOR FRONT GELLING - determine the rose At the time of the survey the following were SACORD FLOOR FRONT GELLING - determine the rose We suggest that if there are any conditions	Neighborhood By Lyle D. Noyes Chief of Hous: TANDARDS FOR HOUSING" - FORTAR, BOIL and Yeardy the conditional section of the structure. FIROMY & MIDDLE, AND TO THE OCCUPANTS SAFETY OF THE OCCUPANTS Building Juspection Departments	ing Inspections Section(s) 3a tion: causing lookage: 3b or FIRST FLOOK REAR; HRD PLOOK REAR; A shoot-epartments that you 3c ndow-eash-to-resein 3c ITH ASTERISKS, AS THEY OF THIS STRUCTURE. Etment. 389 Congress St.
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S' FIG. FRONT-GELLAR FOUNDATION - replace missing FIRST FLOOR FRONT At the time of the survey the following were SACORD FLOOR FRONT GELLING - determine the rose At the time of the survey the following were SACORD FLOOR FRONT GELLING - determine the rose We suggest that if there are any conditions	Neighborhood By Lyle D. Noyes Chief of Hous: TANDARDS FOR HOUSING" - FORTAR, BOIL and Yeardy the conditional section of the structure. FIROMY & MIDDLE, AND TO THE OCCUPANTS SAFETY OF THE OCCUPANTS Building Juspection Departments	ing Inspections Section(s) 3a tion: causing lookage: 3b or FIRST FLOOK REAR; HRD PLOOK REAR; A shoot-epartments that you 3c ndow-eash-to-resein 3c ITH ASTERISKS, AS THEY OF THIS STRUCTURE. Etment. 389 Congress St.
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM S' FIGHT GENER FOUNDATION replace missing FIRST FLOOR FRONT At the time of the survey the following were SACORD FLOOR FRONT GENER, SECORD FLOOR RIGHT We suggest that if there are any conditions	Neighborhood By Lyle D. Noyes Chief of Hous: TANDARDS FOR HOUSING" - FORTAR, BOIL and Yeardy the conditional section of the structure. FIROMY & MIDDLE, AND TO THE OCCUPANTS SAFETY OF THE OCCUPANTS Building Juspection Departments	ing Inspections Section(s) 3a tion: causing lookage: 3b or FIRST FLOOK REAR; HRD PLOOK REAR; A shoot-epartments that you 3c ndow-eash-to-resein 3c ITH ASTERISKS, AS THEY OF THIS STRUCTURE. Etment. 389 Congress St.

1.3

	TION R	ECOMMENDA	TIONS						~ 1	A
						LOCAT	ICK =	200 :	Hate.	(🛬
	. A	1 /				PROJE		Nor	11/2/	17
*SPECTOR		Lear	/			OWNER		1	West	Eind
SCTUCE OF	LOUE!	/						Leons	1/200	350L
NOTICE OF	nuu5 !	Expired	TIONT	HEA	RING NOT	ICE	T	FILIAL	NOTICE	
				Issued		Expired	15	<u>sued</u>		red
10-281							1		1	1
A "s "sres	stion	was made	of the	above neo-					<u> </u>	
DETE	, ,	<u> </u>		above prem	ises and	i recommer	id the	follow	ing action	:
4/1.	ا ما	Send "CER	TIENS H	AVE BEEN OF E OF COMPL	DRRECTED	_>>				
3/19/21	. / .							L''POST I	NG RELEASE	E11
	1 1	SATISFACT	ORY Reh	abili:at:or	in Prog	ress				
		Time Exter								
	1 !									
	1 1	Time Exter								
	┼┼╀	ime Exten	ided To:							
	llu	NSATISFAC	TORY P.	.06.50						
	5	end "HEAR	ING NOT	ICEN			_			
	<u> </u>	NOTICE TO						FINAL	NOTICE"_	
1	P(OSI Entir	2							
- 1			_							
ì	I P	OST Dwell	ing Uni	ts				•		
								•		
	UN	SATISFACT	TORY Pro	20000				•		
5/19/26	UN "'L	SATISFACT	TORY Pro	gress Se Taken				· · 		
5/19/24 3	UN "'L	SATISFACT	TORY Pro	gress Se Taken		olitain	(0)	- a. H		
5/19/26 3	UN "'L	SATISFACT	TORY Pro	20000		olatem	60	ut	if	
5/19/24 3	UN "'L	SATISFACT	TORY Pro	gress Se Taken		olatem	60	ut	aft.	
5/19/2	UN "'L	SATISFACT	TORY Pro	gress Se Taken		olatem,	40	ud	e f	
5/19/24 =	UN "'L	SATISFACT	TORY Pro	gress Se Taken		olatin	42	ut.	i f	
5/19/24 3	UN "'L	SATISFACT	TORY Pro	gress Se Taken		olatem	40	udi	if	
5/19/2	UN "'L	SATISFACT	TORY Pro	gress Se Taken		olatem,	40	ud	e f	
5/19/24 =	UN "'L	SATISFACT	TORY Pro	gress Se Taken		olatin,	60	ut	if	
5/19/24	UN "'L	SATISFACT	TORY Pro	gress Se Taken		olatin	47	udi		
5/19/2	UN "'L	SATISFACT	TORY Pro	gress Se Taken		olatem	40	ud	e f	
5/19/2	UN "'L	SATISFACT	TORY Pro	gress Se Taken		olatin,	60	uch		
5/19/24	1 N	SATISFACT EGAL ACTI	TORY Pro	ogress 5e Taken _		olatin	62	ut		
5/19/2	1 N	SATISFACT	TORY Pro	ogress 5e Taken _		olations	40	ut		
5/19/2	1 N	SATISFACT EGAL ACTI	TORY Pro	ogress 5e Taken _		datin	60	uch		
5/19/2	1 N	SATISFACT EGAL ACTI	TORY Pro	ogress 5e Taken _		olatim,	62	ud		
5/19/2	1 N	SATISFACT EGAL ACTI	TORY Pro	ogress 5e Taken _		Olatin	40	udi		
5/19/2	1 N	SATISFACT EGAL ACTI	TORY Pro	ogress 5e Taken _		datin	(47)	ud		
5/19/2	1 N	SATISFACT EGAL ACTI	TORY Pro	ogress 5e Taken _		olatim	60	ut		
5/19/24	1 N	SATISFACT EGAL ACTI	TORY Pro	ogress 5e Taken _		olation	62	·		

Planning and Urban Development Joseph E. Gray Jr. Director

CITY OF PORTLAND

February 6, 1992

Inspection Services

Samuel P. Hoffses

Chief

Josephine Doe 207 State Street Portland, Maine 04102

> Re: 207 State Street 46-C-24 DU: -

Dear Ms. Doe:

We recently received a complaint and an inspection was made by Code Enforcement Officer Marland Wing of the property owned by you at 107 State St. 1st floor apartment, (right front) Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following substandard housing condition:

1. Holes in kitchen & livingroom floor

- 108-2
- 2. Peeling paint and missing plaster kitchen ceiling
- 108-2

3. Worn linoleum bathroom floor

108-2

4. Broken windows overall apartment

108-3

The above rentioned condition is in violation of Article V of the Naulcipal Code of the City of Portland, Maine, and must be corrected on or before March 6, 1992. Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely,

Marland Wing
Code Enforcement Officer

Chief of inspection Services

/e1

389 Congress Street • Portland, Maine 04101 • (207) 874-8704

.

Inspection Services Samuel P. Hoffses Chief



Planning and Urban Development Joseph E. Gray Jr. Director

CITY OF PORTLAND

February 6, 1992

Josephine Doe 207 State Street Portland, Me 04102

> Re: 207 State St. lst floor Ri. Front Apartment CBL: 46-C-24 DU: -

Dear Ms. Doe:

During a recent inspection of the property owned by you at 207 State Street, 1st floor Ri. Front Apartment, it was noted that smok. detectors were

25 MRSA 2464 required that approved smoke detectors be installed in each apartment in the immediate vicinity of the bedrooms. When actuated, the detector shall provide an alarm suitable to warn the occupants within the individual unit. Failure to comply with this statute may result in a fine

Re-insection of your property will be made in 24 1 mrs. Lack of compliance will result in referral of the matter for legal . et on.

Loss control is a responsibility of your management. Our observations are intended to assist you. Recommendations are a result of conditions observed at the time of our visits. They do not necessarily include every possible loss potential code violation, or exception to good practice.

Sincerely,

Code Enforcement Off

of fuspection Services

cc: LT. Wallace Garroway, Fire Prevention Bureau

/e1

389 Congress Street · Portland, Maine 04101 · (207) 874-8704

Inspection Services
P Samuel Hoffses
Chief



Planning and Urban Development Joseph E. Gray Jr. Director

MAY 02, 1996

CITY OF PORTLAND

SMALL KARL H JR 207 STATE ST PORTLAND ME 04101

> Re: 207 STATE ST CBL: 046 - - C - 24

DU: 3

Dear Mr. Small:

The Housing Inspections Division of the Department of Planning and Urban Development has recently completed an overall inspection of the above referred property.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following terms that could cause future problems:

1. EXT - RIGHT - WALL IS MISSING SHINGLES

108.10

2. EXT - RIGHT - FOUNDATION IS MISSING MORTAR

108.10

3. EXT - RIGHT -TRIM IS MISSING BOARDS

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely,

Marland Wing

Code Enforcement Officer

Tralad Win

Tammy Munson

Code Enfc. Offr./ Field Supv.