


200 Banforth Street

NEP-AB II



SHAW-WALKER

#3503-1R



Loc. 200 Danforth Street
Proj: NDP 2
Block 57K

Issued: Nov. 10, 1971 Expires: Dec. 10, 1971

Mr. John P. Talbot
200 Danforth Street
Portland, Maine

ROOM 215, CITY HALL
PORTLAND, MAINE 04111
775-5451

Board of Commissioners
PAUL M. FOLAN, Chairman
HORACE M. BUDD, Vice Chairman
JOHN H. MALCONIAN
THE REVEREND HAROLD A. McILWAIN
CHARLES W. REDMAN JR.
THOMAS F. VALLEAU, Executive Director

Dear Mr. Talbot:

An examination was made on November 1, 1971 of the premises located at 200 Danforth Street, Portland, Maine by Rehabilitation Specialist Max Furrer. Violations of Municipal Codes relating to housing conditions were found as described below.

In accordance with the provisions of the above named codes you are required to correct these defects. Some repairs or improvements will require permits which are obtained from the Building, Health, Fire or other City Departments.

Financial assistance and construction advice are available from the federal government, by contacting the Neighborhood Development Program office at 247 Danforth Street, 774-3611. Please call us to discuss these before beginning work on your property.

Very truly yours,

Joseph J. (P. 100)

Project Director

BY *Richard E. [Signature]*
Chief, Rehabilitation Services

VIOLATIONS

HOUSING CODE REFERENCE

Exterior

1. Replace all missing or loose brick and point on walls of structure.
2. Replace missing or loose putty.

3. Replace all broke and cracked glass
4. Repair or replace deteriorated or missing trim
5. Repair the blistered, cracked or peeling paint on all exterior casings and trim.
6. Repair all deteriorated sills at cellar windows.
7. Repair all deteriorated brownstone lintels.

