- Building or Use Permit Application 389 Congress Street, 04101, Tel: (207) 874-8703, F4X: 874-8716 City of Portland, Maine Location of Construction: Phone: Owner: 950969 4 AL Mckey Ave (Jetport) U.S. Dept of Commerce/Wat's eather Serva BusinessName: Owner Address: Leasee/Buyer's Name: Phone: Address: P.O. Box 35 Phone: Contractor Name: Gray, ME C4O39 657-4569 A.L. Nossett SEP | 4 1995 COST OF WORK: PERMIT FEE: Past Use: Proposed Use: 20.00 FIRE DEPT. Approved INSPECTION: OF PORT Radar Toyer Same ☐ Denied Use Group: & Office Bldgs CBL: JAMA Signature: Signature: Proposed Project Description: FEDESTRIAN ACTIVITIES DISTRICTAN Action: Approved Special Zone of Rev Approved with Conditions: ☐ Shoreland Remove (2) Underground tacks Denied □ Wetland ☐ Flood Zone ☐ Subdivision Date: Signature: ☐ Site Plan maj ☐ minor ☐ mm ☐ Permit Taken By: Date Applied For: Mary Gresik 12 Sept 1995 Zoning Appeal □ Variance This permit application doesn't preclude the Applicant(s) from meeting applicable State and Federal rules. ☐ Miscellaneous Building permits do not include plumbing, septic or electrical work. □ Conditional Use ☐ Interpretation Building permits are void if work is not started within six (6) months of the date of issuance. False informa-□ Approved tion may invalidate a building permit and stop all work.. ☐ Denied Historic Preservation ☐ Not in District or Landmark aneno DEP forms - ISSN Paperwork to be unived Does Not Require Review ☐ Requires Review Action: CERTIFICATION □ Appoved □ Approved I hereby certify that I am the owner of record of the named property, or that the proposed work is authorized by the owner of record and that I have been authorized by the owner to make this application as his authorized agent and I agree to conform to all applicable laws of this jurisdiction. In addition, if a permit for work described in the application issued, I certify that the code official's authorized representative shall have the authority to enter all areas covered by such permit at any reasonable hour to enforce the provisions of the code(s) applicable to such permit 12 Sept 1995 PHONE: SIGNATURE OF APPLICANT ADDRESS: DATE: H43.e RF TPONSIBLE PERSON IN CHARGE OF WORK, TITLE PHONE: CEO DISTRICT White-Permit Desk Green-Assessor's Canary-D.P.W. Pink-Public File Ivory Card-Inspector


AND THE PROPERTY OF THE PROPER


BUILDING PERMIT REPORT

Date:		9/1	7/95	<u> </u>		
Address:		4 A-1 MC	Kan	·		
Type of Permit:		Rimove	tacks	13		
Owner:		U.S. D.	et Conm	er igner og		
Contractor:		AL Down		· 's		
Applicant:		Mila Lo) &	
	9,2	Approved:			enied:	

Conditions

- 1. All underground tank removal(s) and/or installation(s) shall be done in accordance with Department of Environmental Protection Regulations (Chapter 691).
- 2. No cutting of tanks on site. Cutting of tanks to be done at an approved tank disposal site.
- 3. Fire Dispatcher must be notified 48 hours in advance of removal and/or transporation of tanks.





Fire Department



Joseph E. Thomas, Jr. Chief of Department

CITY OF PORTLAND

F.Y.I

Jeffrey Schultes, A.A.E. Manager, Portland International Jetport 1001 Westbrook Street Portland, Maine 04102

September 13, 1995

Dear Jeff:

On this date, I did a reinspection of the hanger building currently being used by NorthEast Air. The original inspection was dated August 28, 1993. (I have enclosed a copy for your review) As of this date, none of the fourteen items have been addressed.

Our last conversation regarding this was that the structure was going to be torn down when Federal Express moved to their new building.

I will be expecting a plan of correction for this hanger or I will have to post the structure against occupancy.

If-you have any questions please call 874-8/05.

Sincerely,

It Dayle w m. Dange

Gaylen W. McDougall, Lieutenant Portland Fire Prevention Bureau

pc Chief Joseph Thomas, Fire Capt. Tom Blaisdell, AARF Tom Valleau, Director, Transportation & Waterfront Sam Hoffses, Chief Building Linguist ector

380 Congress Street • Portland, Maine 04101 • (207) 87-r-8400

Fire Department



Joseph E. Thomas, Jr. Chief of Department

CITY OF PORTLAND

Jeffrey Schultes, A.A.E.
Manager, Portland International Jetport
1001 Westbrook Street
Portland, Maine 04102

September 13, 1995

Dear Jeff:

On this date, I did a reinspection of the hanger building currently being used by NorthEast Air. The original maninspection was dated August 28, 1993. (I have enclosed a copy for your review) As of this date, none of the fourteen litems have been addressed.

Our last conversation regarding this was that the structure was going to be torn down when Federal Express moved to their new building.

will be expecting a plan of correction for this hanger or I will have to post the structure against occupancy.

MITTY you have any questions please call 874-8405.

Sincerely,

It Sayle en m Dange

Gaylen W. McDougall, Lieutenant Portland Fire Prevention Bureau

pc Chief Joseph Thomas, Fire
Capt. Tom Blaisdell, AARF
Tom Valleau, Director, Transportation & Waterfront
Sam Hoffses, Chief Building Inspector

380 Congress Street • Portland, Maine 04101 • (207) 874-8400

CITY OF PORTLAND FIRE DEPARTMENT Air Rescue Station Portland International Jetport Portland, ME 04102

(pp - 1)

September 6, 1993

Jeffrey Schultes, A.A.E. Manager, Portland International Jetport 1001 Westbrook Street Portland, ME 04102

Dear Jeff, On August 28, 1993, a routine fire prevention inspection was conducted of the hangar building currently being used by Northeast Air and Federal Express.

A number of serious fire code violations were noticed and serious action to remedy the hazards needs to be developed. These hazards include:

- NC 1. All of the existing holes and other poke throughs for various building utilities such as pipes, wires and ducts will have to be sealed.
 - The ceiling over the garage area will have to be replaced with a one hour fire rated enclosure. The ceiling presently has numerous holes throughout that would allow fire travel into the void spaces of the roof trusses which negates the effectiveness of the automatic sprinkler system. Even a small fire could rapidly extend into the unprotected area of the roof trusses and quickly spread unchecked. The use of the bowstring trusses in this area adds additional danger because of the early structural collapse hazard.
 - The electrical service in the building should be examined by a qualified electrical inspector determine compliance with the National Electrical Code. There are numerous additions of circuits from the original pattern and the adequacy of the ratings of the wiring, fuses and breakers is in doubt. Also much of the wiring is unsecured, uncovered, and not labeled. This creates a danger from physical hazards and confusion when an emergency occurs.

CITY OF PORTLAND FIRE DEPARTMENT A PROPERTY OF PORTLAND FIRE DEPARTMENT PORTLAND INTERNATIONAL Jetport Portland, ME 04102

(pp - 2)

September 6, 1993

- $\mathcal{N} \cup \mathcal{A}$. All materials shall be stored at least three feet from the electrical service panels.
 - 5. An emergency lighting system needs to be installed where absent and existing lights shall be repaired or replaced.
- 6. Existing exit signs need to be upgraded and current exit lights that are inoperative shall be repaired.
- The ceilings in the office areas shall also be regained to maintain an integral barrier to fire and smoke spread. This also includes any holes caused by building utilities.
- 8. Clearances from combustible surfaces and the radiant ceiling heater and flue pipes in the garage shall be measured against manufacturers requirements. The flu pipe for this heater needs repair for leakage and corrosion at joints and seams.
- All exit doors and travel paths shall be kept free and clear of obstructions and storage.
- With National Electrical Code Requirements.
 - 11. The storage of 55 gallon drums of miscellaneous flammable and combustible liquids shall be removed. These drums are being ker in poor condition with large amounts leakage and spillage present. The containers also are not marked or labeled as to the contents making identification difficult in an emergency.
- W/L12. The stairs into the basement are in poor repair and should be replaced or repaired.
- μ There is no record of a recent inspection or servicing of the automatic sprinkler system.
 - 14. Existing signs for "Fire Extinguisher" shall be removed or an approved fire extinguisher shall be put in place where signs indicate.

72 M3.4

CITY OF FORTLAND FIRE DEPARTMENT Air Rescue Station Portland International Jetport Portland, ME 04102

(pp - 3)

September 6, 1993

Correction of these hazards shall begin as soon as possible and a definite plan and timetable needs to be developed to rectify the more serious problems. If you require any further assistance please contact myself or Lt. McDougall in the Fire Prevention Bureau, Extension 8405.

Sincerely,

John A. Cannon Lieuterant, Air Rescue Station

cc: Captain Fletcher Lieutenant McDougall