

APPLICATION	Y FUR FEI	ZIAIE #	MAY 19 1954
Class of Building or Type of Structu  Portland, Main  To the INSPECTOR OF BUILDINGS, PORTLAND,	re Second Clas	Bunnesensiering werder werde gewein der der gewein der ge	TIV A WISH AND
Portland, Main	rs, 1ay 19, 195	Edit and a second secon	4774 01 7 7747474
To the INSPECTOR OF BUILDINGS, PORTLAND,	MAINE		34 2 32 X X X
To the INSPECTOR OF BUILDINGS, FORTILARD,  The undersigned hereby applies for a permit to es in accordance with the Laws of the State of Maine, the specifications, if any, submitted herewith and the following  Location 32 Bates St.	rectation xapus demoli. Building Code and Zo ing specifications:	snuusiau-the jouowi oning Ordinance of	the City of Portland, plans and
Owner's name and address State of Maine (	Vincent)		Telephone
Lessee's name and address	A de de de la constant de la constan	Mary Company of the C	Telephone
Lessee's name and address Renjacin Huildi	not & Wrecking C	a. 12 Parris	St. Telephone
Contractor's name and address Deligibility districts	Specifications	Plans	No. of sheets
Architect Proposed use of building	Specimentono		No. families
Proposed use of buildingservice_sta	tion		No. families
Last use	Style of re	of	Roofing
Material brick No. stories I Heat			A SA
	a no control	The state of the s	Fee \$
Estimated cost \$	acceleration of New	w Work	
Light De	cacribitot or 1.04	1 110410	V ,
on the transfer to make the control of the control	eintion 121 x 21	.f	
To demolish 1-story brick service a	and the stand		· · · · · · · · · · · · · · · · · · ·
* . *	}		9
. ~	1		There has consulting
	•		
Do you agree to tightly and permanent public or private sewers from this the supervision and to the approva- of Portland? YES	1 of the Derartm	ment of Public	works of the fity
It is understood that this permit does not include inside the name of the heating contractor. PERMIT TO L	BE ISSUED TO 1 tails of New Wor	rk	Tug or Meaching 40%
Is any plumbing involved in this work?	Is any elect	rical work involved	in this work?
To connection to be made to public sewer?	If not, wha	t is proposed for s	ewage?
Has septic tank notice been sent?	Form notic	ce sent?	
Height average grade to top of plate		e grade to highest	point of roof
Size, frontNo. stories	ssolid or fille	d land?	earth of rockf
Material of foundation	hickness, top	bottom	a cellar manusumananananananananananananananananananan
Material of underpinning		M des sens i tena cesas si adrige caperes per cessos interfer per cesata	Thickness
Kind of roof Rise per foot	Roof cover	ing	proper for every boson og 14 m spans for fra proper fil men stefer span om og er enger ever gary en et er deski
No of chimneys Material of chimney	ys of lining	Kind	ol heat
Traming lumber-Kind	Dressed or	full size?	10 11 10 14 1 15 1 15 1 15 1 15 1 15 1 1
Corner posts Sills Girt o	or ledger board?		Size
Girders Size Columns und	der girders	Size	Max. on centers
Stude (outside walls and carrying partitions) 2x4-1	16" O. C. Bridging in	i every floor and f	lat roof span over 8 feet.
Toists and rafters: 1st floor	, 2nd	, 3rd	
On centers: 1st floor	2nd	, 3rd	roof
Mazimum span: 1st floor	, 2nd	3rd	roofexempersonement
If one story building with masonry walls, thickness	s of walls?	**************************************	height?
2.01.0	tu 1	-	
والمراجع	If a Garage	number comme-c	ial dam, to he accommodated
No. cars now accommodated on same lot, to b	e accommodated	micumor commerc	so proposed building?
Will automobile repairing be done other than mine	or repairs to cars hab		
DOTED.		Miscella	
PROVED:			tree on a public street?no
and with the state of the state			ove work a person competent
n er	see that the St	ate and City requ	uirements pertaining thereto a
findering der ein gerein gerein dem berein der gereint finde abreit ten eine eine eine eine eine eine ei	observed?y.as	hans and the second	vanianie!
mejalangungan menakerukan alam menangkan terun menangkan di kendi keman menangkan semina melak	State of Mai		
	all on the or hard	1.0	ه و در او در او در او در او د
Signature of severy by	kisserd a	Ulgen/	min
Niprature of ceress QXX	. Milette Butter amount on Bymmin	iranington	renter erent mer vertreteren er effente, processen februar betreter an fin

Inspection copy

Inspection Services
P. Samuel Hoffses
Chief



出来。12.15年5月 10.16月1日 12.16月1日 12.16月1日 12.16日 1

Planning and Urban Development Joseph E. Gray Jr. Director

## CITY OF PORTLAND

OCTOBER 17, 1996

HOY JAMES E & PAUL M ROUSSEAU 35 E GRAND AVE OLD ORCHARD BEACH ME 04064

> Re: 29 BATES ST CBL: 429-- J-007-001-01

DU: 3

Dear Mr. Hoy & Mr. Rousseau:

The Housing Inspections Division of the Department of Planning and Urban Development has recently completed an overall inspection of the above-referred property.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems:

1. EXT - REAR STAIRS -

108.40

RAILING AND BALUSTERS ARE MISSING

2. INT - CELLAR -STAIRS ARE MISSING A RAILING 108.20

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely,

Merle Leary

i januaria januaria

Code Enforcement Officer

Tammy Munson

Code Enfc.Offc./ Field Supv.

Inspection Services P. Samuel Hoffres Chief



Planning and Urban Development Joseph E. Gray Jr. Director

OCTOBER 16, 1996

CITY OF PORTLAND

HOY JAMES E & PAUL M ROUSSEAU 35 E GRAND AVE OLD ORCHARD BEACH ME 04064

> Re: 29 BATES ST CBL: 429- - J-007-001-01

DU: 3

Dear Mr. Hoy & Mr. Rousseau:

During a recent inspection of the property owned by you at the above-referred address, it was noted that smoke detectors were missing/inoperable in some locations (i.e.; the third-floor apartment is missing a smoke detector and the second-floor apartment has an inoperative smoke detector).

25 MRSA 2464 required that approved smoke detectors be installed in each apartment in the immediate vicinity of the bedrooms. When activated, the detector shall provide an alarm suitable to warn the occupants within the individual unit. Failure to comply with this statute may result in a fine of up to \$500 for each violation.

Reinspection of your property will be made in twenty-four (24) hours. Lack of compliance will result in referral of the matter for legal action.

Loss control is a responsibility of your management. Our observations are intended to assist you. Recommendations are a result of conditions observed at the time of our visits. They do not necessarily include every possible loss potential code violation, or exception to good practice.

Please read and implement the attached formal code interpretation or determination - Number 93-1 - March 10, 1993 - from the State Fire Marshall's office.

Sincerely,

Merle Leary

Code Enforcement Officer

Tammy Munson

Code Enfc. Offr./ Field Supv.

Taning Thurson