#### ST. LAWRENCE ARTS CENTER ADDITION PORTLAND, MAINE September 29, 2016

## INSPECTION AND MAINTENANCE OF STORMWATER MANAGEMENT FACILITIES

The owner is Friends of St. Lawrence Church, 76 Congress Street, Portland, Maine 04101. The owner will be responsible for the inspection and maintenance of all stormwater management facilities, the establishment of any contract services required to implement the program, and the keeping of records and maintenance log book as described herein. At a minimum, the appropriate and relevant activities for each of the stormwater management facilities should be performed on the prescribed schedule. Periodic inspection and maintenance of these site features and devices is necessary to prevent erosion and remove pollutants from stormwater runoff.

#### **POST CONSTRUCTION MONITORING:**

32-38. Post-construction stormwater management plan compliance.

Any person owning, operating, or otherwise having control over a BMP required by a post Construction stormwater management plan shall maintain the BMPs in accordance with the approved plan and shall demonstrate compliance with that plan as follows:

- (a) Inspections. The owner or operator of a BMP shall hire a qualified post-construction stormwater inspector to at least annually, inspect the BMPs, including but not limited to any parking areas, catch basins, drainage swales, detention basins and ponds, pipes and related structures, in accordance with all municipal and state inspection, cleaning and maintenance requirements of the approved post-construction stormwater management plan.
- (b) Maintenance and repair. If the BMP requires maintenance, repair or replacement to function as intended by the approved post-construction stormwater management plan, the owner or operator of the BMP shall take corrective action(s) to address the deficiency or deficiencies as soon as possible after the deficiency is discovered and shall provide a record of the deficiency and corrective action(s) to the department of public services ("DPS") in the annual report.
- (c) Annual report. The owner or operator of a BMP or a qualified post-construction stormwater inspector hired by that person, shall, on or by June 30 of each year, provide a completed and signed certification to DPS in a form provided by DPS, certifying that the person has inspected the BMP(s) and that they are adequately maintained and functioning as intended by the approved post-construction stormwater management plan, or that they require maintenance or repair, including the record of the deficiency and corrective action(s) taken.

- (d) Filing fee. Any persons required to file and annual certification under this section shall include with the annual certification a filing fee established by DPS to pay the administrative and technical costs of review of the annual certification.
- (e) Right of entry. In order to determine compliance with this article and with the post-construction stormwater management plan, DPS may enter upon property at reasonable hours with the consent of the owner, occupant or agent to inspect the BMPs.

(Ord. No. 35-09/10, 8-17-09)

#### **FILTERRA BIORETENTION SYSTEM:**

Each correctly installed system is to be maintained by the supplier for a minimum period of one year. The cost of this service is to be included in the supplier's price of the system.

Annual maintenance consists of two (2) scheduled visits unless otherwise specified.

Each maintenance visit consists of the following:

- Inspection of Filterra and surrounding area
- Removal of tree grate and erosion control stones
- Removal of debris, trash and mulch
- Mulch replacement
- Plant health evaluation and pruning or replacement as necessary
- Clean area around Filterra
- Complete paperwork

## ST. LAWRENCE ARTS CENTER ADDITION PORTLAND, MAINE

#### **INSPECTION / MAINTENANCE LOG**

#### **FILTERRA BIORETENTION SYSTEM**

# I: INSPECTED - C: CLEANED - R: REPAIRED **DATE INITIALS ACTION COMMENT** 8/12/16 ABC I, C EXAMPLE: Remove sand deposits and debris as necessary.

# Operation & Maintenance (OM) Manual v01







## **Table of Contents**

#### **Overview**

- Filterra General Description
- Filterra Schematic
- Basic Operations
- Design

#### **Maintenance**

- Maintenance Overview
  - » Why Maintain?
  - » When to Maintain?
- Exclusion of Services
- Maintenance Visit Summary
- Maintenance Tools, Safety Equipment and Supplies
- Maintenance Visit Procedure
- Maintenance Checklist


#### Resources

- Example Filterra Project Maintenance Report Sheet
- Example Filterra Structure Maintenance Report Sheet
- Filterra Warranty
- Drawing FTST-2: Filterra Standard Configuration Detail
- Drawing FTNL-3: Filterra Narrow Length Configuration Detail
- Drawing FTNW-3: Filterra Narrow Width Configuration Detail



## **General Description**

The following general specifications describe the general operations and maintenance requirements for the Contech Engineered Solutions LLC stormwater bioretention filtration system, the Filterra. The system utilizes physical, chemical and biological mechanisms of a soil, plant and microbe complex to remove pollutants typically found in urban stormwater runoff. The treatment system is a fully equipped, pre-constructed drop-in place unit designed for applications in the urban landscape to treat contaminated runoff.



Stormwater flows through a specially designed filter media mixture contained in a landscaped concrete container. The mixture immobilizes pollutants which are then decomposed, volatilized and incorporated into the biomass of the Filterra system's micro/macro fauna and flora. Stormwater runoff flows through the media and into an underdrain system at the bottom of the container, where the treated water is discharged. Higher flows bypass the Filterra to a downstream inlet or outfall. Maintenance is a simple, inexpensive and safe operation that does not require confined space access, pumping or vacuum equipment or specialized tools. Properly trained landscape personnel can effectively maintain Filterra Stormwater systems by following instructions in this manual.

## **Basic Operations**

Filterra is a bioretention system in a concrete box.

Contaminated stormwater runoff enters the filter box through the curb inlet spreading over the 3-inch layer of mulch on the surface of the filter media. As the water passes through the mulch layer, most of the larger sediment particles and heavy metals are removed through sedimentation and chemical reactions with the organic material in the mulch. Water passes through the soil media where the finer particles are removed and other chemical reactions take place to immobilize and capture pollutants in the soil media. The cleansed water passes into an underdrain and flows to a pipe system or other appropriate discharge point. Once the pollutants are in the soil, the bacteria begin to break down and metabolize the materials and the plants begin to uptake and metabolize the pollutants. Some pollutants such as heavy metals, which are chemically bound to organic particles in the mulch, are released over time as the organic matter decomposes to release the metals to the feeder roots of the plants and the cells of the bacteria in the soil where they remain and are recycled. Other pollutants such as phosphorus are chemically bound to the soil particles and released slowly back to the plants and bacteria and used in their metabolic processes. Nitrogen goes through a very complex variety of biochemical processes where it can ultimately end up in the plant/bacteria biomass, turned to nitrogen gas or dissolves back into the water column as nitrates depending on soil temperature, pH and the availability of oxygen. The pollutants ultimately are retained in the mulch, soil and biomass with some passing out of the system into the air or back into the water.

#### **Design and Installation**

Each project presents different scopes for the use of Filterra systems. To ensure the safe and specified function of the stormwater BMP, Contech reviews each application before supply. Information and help may be provided to the design engineer during the planning process. Correct Filterra box sizing (by rainfall region) is essential to predict pollutant removal rates for a given area. The engineer shall submit calculations for approval by the local jurisdiction. The contractor is responsible for the correct installation of Filterra units as shown in approved plans. A comprehensive installation manual is available at www.conteches.com.

### **Maintenance**

## **Why Maintain?**

All stormwater treatment systems require maintenance for effective operation. This necessity is often incorporated in your property's permitting process as a legally binding BMP maintenance agreement.

 Avoid legal challenges from your jurisdiction's maintenance enforcement program.

- Prolong the expected lifespan of your Filterra media.
- Avoid more costly media replacement.
- Help reduce pollutant loads leaving your property.

Simple maintenance of the Filterra is required to continue effective pollutant removal from stormwater runoff before discharge into downstream waters. This procedure will also extend the longevity of the living biofilter system. The unit will recycle and accumulate pollutants within the biomass, but is also subjected to other materials entering the throat. This may include trash, silt and leaves etc. which will be contained within the void below the top grate and above the mulch layer. Too much silt may inhibit the Filterra's® flow rate, which is the reason for site stabilization before activation. Regular replacement of the mulch stops accumulation of such sediment.

#### When to Maintain?

Contech includes a 1-year maintenance plan with each system purchase. Annual included maintenance consists of a maximum of two (2) scheduled visits. Additional maintenance may be necessary depending on sediment and trash loading (by Owner or at additional cost). The start of the maintenance plan begins when the system is activated for full operation. Full operation is defined as the unit installed, curb and gutter and transitions in place and activation (by Supplier) when mulch and plant are added and temporary throat protection removed.

Activation cannot be carried out until the site is fully stabilized (full landscaping, grass cover, final paving and street sweeping completed). Maintenance visits are scheduled seasonally; the spring visit aims to clean up after winter loads including salts and sands while the fall visit helps the system by removing excessive leaf litter.

It has been found that in regions which receive between 30-50 inches of annual rainfall, (2) two visits are generally required; regions with less rainfall often only require (1) one visit per annum. Varying land uses can affect maintenance frequency; e.g. some fast food restaurants require more frequent trash removal. Contributing drainage areas which are subject to new development wherein the recommended erosion and sediment control measures have not been implemented may require additional maintenance visits.

Some sites may be subjected to extreme sediment or trash loads, requiring more frequent maintenance visits. This is the reason for detailed notes of maintenance actions per unit, helping the Supplier and Owner predict future maintenance frequencies, reflecting individual site conditions.

Owners must promptly notify the (maintenance) Supplier of any damage to the plant(s), which constitute(s) an integral part of the bioretention technology. Owners should also advise other landscape or maintenance contractors to leave all maintenance to the Supplier (i.e. no pruning or fertilizing).

#### **Exclusion of Services**

It is the responsibility of the owner to provide adequate irrigation when necessary to the plant of the Filterra system.

Clean up due to major contamination such as oils, chemicals, toxic spills, etc. will result in additional costs and are not covered under the Supplier maintenance contract. Should a major contamination event occur the Owner must block off the outlet pipe of the Filterra (where the cleaned runoff drains to, such as drop inlet) and block off the throat of the Filterra. The Supplier should be informed immediately.

## **Maintenance Visit Summary**

Each maintenance visit consists of the following simple tasks (detailed instructions below).

- 1. Inspection of Filterra and surrounding area
- 2. Removal of tree grate and erosion control stones
- 3. Removal of debris, trash and mulch
- 4. Mulch replacement
- 5. Plant health evaluation and pruning or replacement as necessary
- 6. Clean area around Filterra
- 7. Complete paperwork

## **Maintenance Tools, Safety Equipment and Supplies**

Ideal tools include: camera, bucket, shovel, broom, pruners, hoe/rake, and tape measure. Appropriate Personal Protective Equipment (PPE) should be used in accordance with local or company procedures. This may include impervious gloves where the type of trash is unknown, high visibility clothing and barricades when working in close proximity to traffic and also safety hats and shoes. A T-Bar or crowbar should be used for moving the tree grates (up to 170 lbs ea.). Most visits require minor trash removal and a full replacement of mulch. See below for actual number of bagged mulch that is required in each unit size. Mulch should be a double shredded, hardwood variety; do not use colored or dyed mulch. Some visits may require additional Filterra engineered soil media available from the Supplier.

Box Length	Box Width	Filter Surface Area (ft²)	Volume at 3" (ft³)	# of 2 ft³ Mulch Bags
4	4	4	4	2
6	4	6	6	3
8	4	8	8	4
6	6	9	9	5
8	6	12	12	6
10	6	15	15	8
12	6	18	18	9
13	7	23	23	12

### **Maintenance Visit Procedure**

Keep sufficient documentation of maintenance actions to predict location specific maintenance frequencies and needs. An example Maintenance Report is included in this manual.



Record on Maintenance Report the following:

Record individual unit before maintenance with photograph (numbered).
 Record on Maintenance Report (see example in this document) the following:



Record of Maintenance Report the following.	
Standing Water	yes   no
Damage to Box Structure	yes   no
Damage to Grate	yes   no
Is Bypass Clear	yes   no

If yes answered to any of these observations, record with close-up photograph (numbered).



#### 2. Removal of tree grate and erosion control stones

- Remove cast iron grates for access into Filterra box.
- Dig out silt (if any) and mulch and remove trash & foreign items.

Record on Maintenance Report the following:

Silt/Clay yes | no
Cups/ Bags yes | no
Leaves yes | no
# of Buckets Removed



#### 3. Removal of debris, trash and mulch

• After removal of mulch and debris, measure distance from the top of the Filterra engineered media soil to the bottom of the top slab. If this distance is greater than 12", add Filterra media (not top soil or other) to recharge to a 9" distance

Record on Maintenance Report the following:	
Distance of Bottom of Top Slab (inches) # of Buckets of Media Added	



#### 4. Mulch replacement

- Please see mulch specifications.
- Add double shredded mulch evenly across the entire unit to a depth of 3".
- Ensure correct repositioning of erosion control stones by the Filterra inlet to allow for entry of trash during a storm event.
- Replace Filterra grates correctly using appropriate lifting or moving tools, taking care not to damage the plant.



# 5. Plant health evaluation and pruning or replacement as necessary

- Examine the plant's health and replace if dead.
- Prune as necessary to encourage growth in the correct directions

Record on Maintenance Report the tollowing	g:
Height above Grate	(Feet)
Width at Widest Point	(feet)
Health	alive   dead
Damage to Plant	yes   no
Plant Replaced	yes   no



#### 6. Clean area around Filterra

 Clean area around unit and remove all refuse to be disposed of appropriately.



#### 7. Complete paperwork

- Deliver Maintenance Report and photographs to appropriate location (normally Contech during maintenance contract period).
- Some jurisdictions may require submission of maintenance reports in accordance with approvals. It is the responsibility of the Owner to comply with local regulations.

## **Maintenance Checklist**

Drainage System Failure	Problem	Conditions to Check	Condition that Should Exist	Actions
Inlet	Excessive sediment or trash accumulation.	Accumulated sediments or trash impair free flow of water into Filterra.	Inlet should be free of obstructions allowing free distributed flow of water into Filterra.	Sediments and/or trash should be removed.
Mulch Cover	Trash and floatable debris accumulation.	Excessive trash and/or debris accumulation.	Minimal trash or other debris on mulch cover.	Trash and debris should be removed and mulch cover raked level. Ensure bark nugget mulch is not used.
Mulch Cover	"Ponding" of water on mulch cover.	"Ponding" in unit could be indicative of clogging due to excessive fine sediment accumulation or spill of petroleum oils.	Stormwater should drain freely and evenly through mulch cover.	Recommend contact manufacturer and replace mulch as a minimum.
Vegetation	Plants not growing or in poor condition.	Soil/mulch too wet, evidence of spill. Incorrect plant selection. Pest infestation. Vandalism to plants.	Plants should be healthy and pest free.	Contact manufacturer for advice.
Vegetation	Plant growth excessive.	Plants should be appropriate to the species and location of Filterra.		Trim/prune plants in accordance with typical landscaping and safety needs.
Structure	Structure has visible cracks.  be performed twice annual tracks.	Cracks wider than 1/2 inch or evidence of soil particles entering the structure through the cracks.		Vault should be repaired.



#### HOUSEKEEPNG REPORT

#### St. Lawrence Arts Center Addition PORTLAND, MAINE September 29, 2016

#### Housekeeping:

This project is located in a residential zone. Protection of the groundwater and surface water quality is ensured by having good housekeeping practices and maintenance of the stormwater systems. Spill prevention must be incorporated into the plan. The facility should follow the following steps:

- 1. Identify any products that if spilled will create contamination of the groundwater.
- 2. Maintain a list of the materials and keep the MSDS sheets available to all employees.
- 3. If petroleum products are stored on site, keep absorbent pads available for use in clean up.
- 4. Post the names and contract information for the employee responsible for environmental matters and the names and contact information of companies to be called in the event of a spill.
- 5. As part of employee training, inform employees of the procedures for response to environmental matters.

The maintenance of the landscaping and parking area should include removal of the materials that may cause dust.

During construction follow the erosion control measures outlined on the plans.

During construction, develop a waste handling program that identified potential contaminates that could be introduced to the environment. Follow hazardous waste rules if any items used are considered a hazardous waste. It is critical to the site that uncontrolled releases be prevented.

This site will not require dewatering of trenches. During construction, monitor stormwater runoff from the equipment and ground areas to minimize contamination of groundwater.