Portland, Maine



Yes. Life's good here.

Permitting and Inspections Department Michael A. Russell, MS, Director

Jonathan Rioux, Inspections Director

3/20/2018

Jeffery & Diane Davison 29 Morning St. Portland, ME 04101

RE: 33 Morning St. CBL: 003 C014001

NOTICE OF VIOLATION AND ORDER TO CORRECT

To Whom it May Concern,

The City of Portland Housing Safety Office inspected the above-referenced property on March 20, 2018 and found violations of the City of Portland Code of Ordinances, which are listed on the attached page(s). You are hereby ordered to correct these violations by the dates given on the attached.

If you fail to do so, this matter may be referred to the City of Portland Corporation Counsel for legal action, including civil penalties and other legal remedies.

This constitutes an appealable decision under the City of Portland Code of Ordinances. Your failure to appeal this Notice may result in you being barred from challenging the City's determinations in the future.

Please feel free to contact me if you have any questions with respect to this matter.

Sincerely,

Matt Sarapas



INSPECTION WORKSHEET (142016) FOR CITY OF PORTLAND

Case Number:

Case Module:

Permit Management

Inspection Date:

03/20/2018

Inspection Status:

Re-inspection required

Inspector:

Matt Sarapas

Inspection Type:

Long Term Rental Registration

Job Address:

33 Morning St

Portland, ME 04101

Parcel Number:

Contact Type

Company Name

Name

Checklist Item

Passed Comments

| Noncompliance | | | | |
|---|--|--|------------------------|----------------------------|
| Code Name NFPA 101-4.5.3.2, 7.1.10.1 | Description Obstructed Egress | Comments IMMEDIATELY remove all obstructions to the means of egress | Deadline 03/20/2018 | Resolve Date 04/20/2018 |
| PFD Rules, 4.6 | Unit/Suite Numbers Not Marked | Unit entry doors must be numbered front and rear. | 03/20/2018 | 04/20/2018 |
| NFPA101-31.3 | Interior Finish Noncompliant | Paneling in third floor front hallway must be fire rated or removed. | 04/20/2018 | 04/20/2018 |
| NFPA 101-8.3.3.3 | Fire Doors Must Be Self- Or Auto-Closing | Self closing hinges need adjustment throughout, doors must self close and latch. | 03/20/2018 | 04/20/2018 |
| NFPA 101-8.6 | Vertical Openings Not Fire Rated | Attic scuttle in front hallway must be one hour fire rated. | 03/20/2018 | 04/20/2018 |