Location of Construction: 94 Morning Street Portland	Owner: Rose Morey	•.	т	Phone: 774-	7736		Permit No: 990838
Owner Address: SAA	Lessee/Buyer's Name:	,	Phone:	Busines	ssName:	200	PERMIT ISSUED
Contractor Name:	Address:	E 04038	杂杂金衣	Phone: 929	-85\$3	A Petroleit in	Permit Issued:
Past Use:	Proposed Use:		OST OF V 5 6, 100.	WORK:	PERMIT FEE: \$ 66.00	Difference on 3.7 Fe	AUG 9 1999
3 unity	8 A TIC			C. ☐ Approved ☐ Denied	INSPECTION: Use Group 23 Typ 30C9 96 Signature:	A	Zone: CBL: 003-D-003
Proposed Project Description:			gnature: EDESTRL	AN ACTIVITII	ES DISTRICT (A)		
re-construct esisting perch in es	isting foot print	Ac	etion:	Approved	with Conditions: Date:		Special Zone or Reviews: Shoreland Wetland Flood Zone
Permit Taken By:	Date Applied For:	Aug. 5	1999 K.				☐ Site Plan maj ☐minor ☐mm ☐
 Building permits do not include plumbing, so Building permits are void if work is not started tion may invalidate a building permit and sto 	ed within six (6) months of the date	of issuance.	. False info		PERMIT ISSUED VITH REQUIREMENTS		☐ Miscellaneous ☐ Conditional Use ☐ Interpretation ☐ Approved ☐ Denied Historic Preservation ☐ Not in District or Landmark ☐ Does Not Require Review ☐ Requires Review Action:
I hereby certify that I am the owner of record of th authorized by the owner to make this application if a permit for work described in the application is areas covered by such permit at any reasonable h	as his authorized agent and I agree s issued, I certify that the code office	sed work is to conform ial's author code(s) ap	to all appl ized repres plicable to	licable laws of the sentative shall has such permit	nis jurisdiction. In add	dition,	□ Appoved □ Approved with Conditions □ Denied Date:
SIGNATURE OF APPLICANT	ADDRESS:	Aug	. 5, 19 ^o	y y	PHONE:		
RESPONSIBLE PERSON IN CHARGE OF WOR					PHONE:		CEO DISTRICT
THE RESERVE OF THE PROPERTY OF							

Additional Plans or Technical Submissions may not be shown in this format.

If you wish to see additional information, Please ask the support staff.

COMMENTS

	3	
9-6-99 Met w/ contractor on site after ph	one call to Mrs. Morey located him To	huo.
Advised to Lag Rim joist to posts al	levels and Drovide a graspable	handrail.
7-6-99 Met w/ contractor on site after pho Advised to Lag Rim joist to posts al Plans and not show stair detail and	Guardrail height is 32" Exception	individual
Lecks which as 42". North was ch	ecked dimensions on deck us o	n Dlans
Lecks which as 42". Helt with Sa hown=6'6" x 9'10'z". Check with Sa	m on bost regurrement and	he waived
it's need so These measurements. U	Vill head to cause Guardiail 10"	instell
bandrail 34-38" (hock 6' sethock to	curb of Dier Fasteners 00	<u> </u>
4	January Criticis .	
its need per These measurements. U handrail 34-38; check 6' sethack to 7/8 Met w/ Darren - reviewed code Guardrail height in R-2 on stairs	021.2 and determined That 36'	is accortable
Guard rail height in R-2 on stairs	under 20. XB	73 of ecepain
	000000	47.
10/18 Work Complete DC	3 2 3.	
Total Conference in		
		·- <u>-</u>
	Inspection Record	
	Туре	Date
	Foundation:Framing:	
	Plumbing:	
	Final:	

Other: