




- 1 1/2" DIA. GALVANIZED STEEL RAIL HANDRAIL SON EXISTING 1/4" DIA. GALVANIZED STEEL SUPPORT FASTEN TO EACH VERTICAL MEMBER OF **GUARDRAIL SYSTEM** - GALVANIZED STEEL ESCUTCHEON PLATE FASTEN TO EXISTING WALL WITH MASONRY ANCHORS; MAXIMUM 4'-0" HORIZONTAL SEPERATION TYPICAL - HANDRAIL SECTION DETAIL @ EXISTING WALL







© 2016 RYAN SENATORE ARCHITECTURE

WASHINGTON AVENUE

23

123 WASHINGTON

ARCHITECTURE 565 CONGRESS STREET PORTLAND, MAINE 04101 207-650-6414 senatorearchitecture.com

CONSULTANTS:

DATE: DECEMBER 05, 2016 PROJECT No.

DRAWN BY: CHECKED BY: AS NOTED SCALE:

SHEET TITLE: DETAILS