



GRANT HAY

ARCHITECTURE & IMTERIOR DE/IGM P.O. BOX 6179 FALMOUTH MAIME 04105

207.871.5900 www.granthays.com

MICHAEL F.
HAYS
NO. 1724

MICHAEL F.
HAYS
NO. 1724

MICHAEL F.
HAYS
NO. 1724

REVI/10/I/

PROJECT MAME

DXDC BLEADING & BO TOILET ROC

∫ĦEET

NFPA LEGEND

LIFE SAFETY NOTES

THE ENTIRE BUILDING HAS AN EXISTING

SYSTEM SHALL BE MODIFIED FOR NEW CONFIGURATION, THEN REVIEWED AND APPROVED BY THE STATE OF MAINE

FIRE MARSHAL AS WELL AS THE LOCAL AUTHORITY HAVING JURISDICTION. THE

SPRINKLER CONTRACTOR SHALL BEAR SOLE RESPONSIBILITY FOR THE DESIGN

AND INSTALLATION OF THE SYSTEM

OF GORHAM ORDINANCES AND AUTHORITY HAVING JURISDICTION.

THE BUILDING HAS AN EXISTING FIRE

WITH NFPA 101 LIFE SAFETY CODE. COORDINATE WITH SPRINKLER SYSTEM

ALARM SYSTEM IN FOR COMPLIANCE

FOR FIRE ALARM SYSTEM WORK FOR

NEW CONFIGURATION. VERIFY

SAFETY DEVICES.

4. SEE SHEET A-3 FOR SIGNAGE.

LOCATION OF ALARMS WITH THE

AUTHORITY HAVING JURISDICTION.

SEE ACCESSIBILITY DETAILS ON SHEET A-3 FOR MOUNTING HEIGHTS OF LIFE

FOR OCCUPANCY. VERIFY SPRINKLER

ROOM REQUIREMENTS WITH THE TOWN

NFPA 13 FIRE SUPPRESSION SPRINKLER SYSTEM. SPRINKLER

△▶ EMERGENCY LIGHT

HORN / STROBE UNIT

STROBE UNIT

(E) EXISTING FIXTURE

SYMBOL

DESCRIPTION

OMPLIANCE

16 JUNE 2017

1/2"=1'-0"

MFH / mgk

JOB NO.
170608

MEET A-1

COPYRIGHT

REPRODUCTION OR REU/E OF THU

DOCUMENT WITHOUT WRITTEN

PERML/JON FROM GRANT HAY/

A//OCIATE/ J/ PROHIBITED.