## CITY OF PORTLAND

June 28, 1999

To: Peter E. O'Donnell

From: Mike Nugent/Manager of Inspection Services

Re: 121 Sheridan St. (013 K017)

Evaluation of the work performed pursuant to Permit # 990657 revealed that the work is still incomplete. We have requested product information of the sections of "I" beam that are used to affix the deck to the 3rd floor band. We have reviewed the "Simpson" products that tie the 4" X 4" supports to the shoe plates and find that this product is not designed for this use. The Builder will be notified.

Sam Hoffses, City Building Inspector, is going to review the through bolting of the 4" X 4" supports at the deck level to ascertain if additional ledger support is needed.

We have been advised by CMP that the electrical service meets CMP standards and they have fully connected it. It has been reviewed and approved by Sam Hoffses.