

3-20-13  
GF-BKL FAIL

→ CELLS NOT PER PLAN

- + GWB SEPERATION BSMT TO BOILER RM
- + GFCI - TR - AFB - LETTERS TO BKL
- + ADJ SELF CLOSERS - DOORS
- + FIRE STOP CAULK - BSMT.
- + BATH SINK TRAP "S" - FAIL - CORRECTED ✓
- + BSMT USE NOT PER PLN? 2ND EGRESS

12-9-13 GF - JM - CM

- + ADJ SELF CLOSERS - DOORS
- + "A" REAR FIRE DOOR
- + "A" SMOKE/CO COMBO UNIT
- + "B" REAR FIRE DOOR
- + "B" HARDWIRED SMOKE C/O (2)
- + FIRE STOP ASSY. IN BSMT HEAD OF WALL NTC. ✓ OK per 3/13/14  
Insp JMB