

**City of Portland, Maine**  
**Inspections Division**  
**Inspection Results**  
**All Results**

| <b>Date</b>   | <b>CBL</b>  | <b>Business</b>   | <b>Appl ID</b> | <b>Appl Type</b> | <b>FT</b> | <b>Sch. Type</b>               | <b>Status</b> |
|---|-------------|-------------------|----------------|------------------|-----------|--------------------------------|---------------|
| 11/01/1995  | 013 L018001 |                   | 0              | Housing          | No        | Housing Inspection             | Green 0-4     |
| 151 CONGRESS ST UNIT 1<br>Letter Info: 5/26/95: NOHC LTR, 11/14/95: CERT/COMPL  |             |                   |                |                  |           |                                |               |
| 01/14/2000  | 013 L018001 |                   | 0              | Housing          | No        | Housing Inspection             | Green 0-4     |
| 151 CONGRESS ST UNIT 1  |             |                   |                |                  |           |                                |               |
| 10/14/2005  | 013 L018001 | Hannan's Electric | 20054862       | Electrical       | No        | Electrical Service             |               |
| 151 CONGRESS ST UNIT 1<br>OH service upgrade.   |             |                   |                |                  |           |                                |               |
| 02/02/2010  | 013 L018001 |                   | 50631          | Building         | No        | Certificate of Occupancy/Final |               |
| 151 CONGRESS ST UNIT 1<br>Alex 730-1668 Condo President coordinating for ALL SIX UNITS MUST HAVE FIRE NEEDS SIX INDIVIDUAL C of O's Must have call in a.m. W/ time<br>2-2-10 Violations corrected before CO's can be issued : Basement - secure bx cable at top of stairway , change box for hallway light , switch plate , secure three-way switch and box in front of basement , secure outlet/switch box by Unit #1 storage locker ; Unit #1 - replace reg outlets with GFCI outlets in sink area ; Unit # 2 - OK : issue CO ; Unit #3 - OK : issue CO ; Unit #4 - fix electrical box ceiling liv room , fire cock around chimney , paint removed in rear hallway ; Unit #5 - transom window in front hallway needs to be sheet rocked , GFCI outlets in kit sink area ; Unit #6 - complete construction to roof Permit # 090555 , GFCI outlets in kit sink area |             |                   |                |                  |           |                                |               |
| 03/03/2010  | 013 L018001 |                   | 50631          | Building         | No        | Certificate of Occupancy/Final |               |
| 151 CONGRESS ST UNIT 1<br>NO ELECTRIC Keith went out and gave them a list list complete please call with time 730-1668 Alex<br>03-03-10 Follow-up inspection for C of O, CO det. and interconnected smk.'s/ fire doors in place, electrical violations corrected- all violations in previous inspection corrected with the exemption of Unit six (6), out @ 10:35 AM, JGR.  |             |                   |                |                  |           |                                |               |