



# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 621601565  
Customer ID: ABAT52  
Customer PO: 16-289  
Project ID:

**Attn:** Kris Rickett  
Abatement Professionals Corporation  
590 County Road  
Suite #2  
Westbrook, ME 04092  
**Phone:** (207) 773-1276  
**Fax:** (207) 772-1203  
**Collected:** 10/10/2016  
**Received:** 10/11/2016  
**Analyzed:** 10/17/2016  
**Proj:** 16-289 / 42 LAFAYETTE ST.

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** B1A **Lab Sample ID:** 621601565-0001  
**Sample Description:** 1ST FLOOR KITCHEN TOP LAYER - LINOLEUM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/13/2016	Gray/Tan	0.0%	100%	None Detected	

**Client Sample ID:** B1B **Lab Sample ID:** 621601565-0002  
**Sample Description:** 1ST FLOOR KITCHEN TOP LAYER - LINOLEUM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/13/2016	Gray/Tan	0.0%	100%	None Detected	

**Client Sample ID:** B1C **Lab Sample ID:** 621601565-0003  
**Sample Description:** 1ST FLOOR KITCHEN TOP LAYER - LINOLEUM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/17/2016	Gray/Tan	0.0%	100%	None Detected	

**Client Sample ID:** B2A **Lab Sample ID:** 621601565-0004  
**Sample Description:** 1ST FLOOR KITCHEN 2ND LAYER - LINOLEUM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/13/2016	Gray/Black	0.0%	98.8%	1.2% Chrysotile	

**Client Sample ID:** B2B **Lab Sample ID:** 621601565-0005  
**Sample Description:** 1ST FLOOR KITCHEN 2ND LAYER - LINOLEUM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/13/2016				Positive Stop (Not Analyzed)	

**Client Sample ID:** B2C **Lab Sample ID:** 621601565-0006  
**Sample Description:** 1ST FLOOR KITCHEN 2ND LAYER - LINOLEUM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/13/2016				Positive Stop (Not Analyzed)	

**Client Sample ID:** B3A **Lab Sample ID:** 621601565-0007  
**Sample Description:** 1ST FLOOR KITCHEN 3RD LAYER - LINOLEUM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/13/2016	Gray/Black	0.0%	100%	None Detected	



# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 621601565  
Customer ID: ABAT52  
Customer PO: 16-289  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** B3B **Lab Sample ID:** 621601565-0008

**Sample Description:** 1ST FLOOR KITCHEN 3RD LAYER - LINOLEUM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/13/2016	Gray/Black	0.0%	100%	None Detected	

**Client Sample ID:** B3C **Lab Sample ID:** 621601565-0009

**Sample Description:** 1ST FLOOR KITCHEN 3RD LAYER - LINOLEUM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/17/2016	Gray/Black	0.0%	100%	None Detected	

**Client Sample ID:** B4A **Lab Sample ID:** 621601565-0010

**Sample Description:** 1ST FLOOR KITCHEN BOTTOM LAYER - LINOLEUM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/17/2016	Tan/Black	0.0%	100%	None Detected	

**Client Sample ID:** B4B **Lab Sample ID:** 621601565-0011

**Sample Description:** 1ST FLOOR KITCHEN BOTTOM LAYER - LINOLEUM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/17/2016	Tan/Black	0.0%	100%	None Detected	

**Client Sample ID:** B4C **Lab Sample ID:** 621601565-0012

**Sample Description:** 1ST FLOOR KITCHEN BOTTOM LAYER - LINOLEUM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/17/2016	Tan/Black	0.0%	100%	None Detected	

**Client Sample ID:** B5A **Lab Sample ID:** 621601565-0013

**Sample Description:** 1ST FLOOR BATHROOM FLOOR - LINOLEUM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/13/2016	Tan/Beige	0.0%	68.9%	31.1% Chrysotile	

**Client Sample ID:** B5B **Lab Sample ID:** 621601565-0014

**Sample Description:** 1ST FLOOR BATHROOM FLOOR - LINOLEUM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/13/2016					Positive Stop (Not Analyzed)

**Client Sample ID:** B5C **Lab Sample ID:** 621601565-0015

**Sample Description:** 1ST FLOOR BATHROOM FLOOR - LINOLEUM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/13/2016					Positive Stop (Not Analyzed)



# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 621601565  
Customer ID: ABAT52  
Customer PO: 16-289  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** B6A **Lab Sample ID:** 621601565-0016

**Sample Description:** 1ST FLOOR KITCHEN CEILING - CEILING TILES

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/13/2016	Gray	95%	5%	None Detected	

**Client Sample ID:** B6B **Lab Sample ID:** 621601565-0017

**Sample Description:** 1ST FLOOR KITCHEN CEILING - CEILING TILES

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/13/2016	Gray	95%	5%	None Detected	

**Client Sample ID:** B6C **Lab Sample ID:** 621601565-0018

**Sample Description:** 1ST FLOOR KITCHEN CEILING - CEILING TILES

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/17/2016	Gray	95%	5%	None Detected	

**Client Sample ID:** B7A **Lab Sample ID:** 621601565-0019

**Sample Description:** 1ST FLOOR DINING CEILING - CEILING TILES

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/13/2016	Brown	90%	10%	None Detected	

**Client Sample ID:** B7B **Lab Sample ID:** 621601565-0020

**Sample Description:** 1ST FLOOR DINING CEILING - CEILING TILES

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/13/2016	Brown	90%	10%	None Detected	

**Client Sample ID:** B7C **Lab Sample ID:** 621601565-0021

**Sample Description:** 1ST FLOOR DINING CEILING - CEILING TILES

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/17/2016	Brown	95%	5%	None Detected	

**Client Sample ID:** B8A **Lab Sample ID:** 621601565-0022

**Sample Description:** 1ST FLOOR SUN PORCH FLOORS - 12X12 TILES

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/13/2016	Brown	0.0%	100%	None Detected	

**Client Sample ID:** B8B **Lab Sample ID:** 621601565-0023

**Sample Description:** 1ST FLOOR SUN PORCH FLOORS - 12X12 TILES

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/13/2016	Brown	0.0%	100%	None Detected	



# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 621601565  
Customer ID: ABAT52  
Customer PO: 16-289  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** B8C **Lab Sample ID:** 621601565-0024

**Sample Description:** 1ST FLOOR SUN PORCH FLOORS - 12X12 TILES

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/17/2016	Brown	0.0%	100%	None Detected	

**Client Sample ID:** B9A **Lab Sample ID:** 621601565-0025

**Sample Description:** 1ST FLOOR WALLS - PLASTER

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/13/2016	Gray	0%	100%	None Detected	

**Client Sample ID:** B9B **Lab Sample ID:** 621601565-0026

**Sample Description:** 1ST FLOOR WALLS - PLASTER

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/13/2016	Gray	0%	100%	None Detected	

**Client Sample ID:** B9C **Lab Sample ID:** 621601565-0027

**Sample Description:** 1ST FLOOR WALLS - PLASTER

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/17/2016	Gray	0%	100%	None Detected	

**Client Sample ID:** B10A **Lab Sample ID:** 621601565-0028

**Sample Description:** 2ND BATHROOM FLOOR - 12X12 TILES

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/13/2016	Gray	0.59%	99.4%	None Detected	

**Client Sample ID:** B10B **Lab Sample ID:** 621601565-0029

**Sample Description:** 2ND BATHROOM FLOOR - 12X12 TILES

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/13/2016	Gray	1.1%	98.9%	None Detected	

**Client Sample ID:** B10C **Lab Sample ID:** 621601565-0030

**Sample Description:** 2ND BATHROOM FLOOR - 12X12 TILES

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	10/17/2016	Gray	<0.25%	100%	None Detected	



## EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID:	621601565
Customer ID:	ABAT52
Customer PO:	16-289
Project ID:	

---

### Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

---

PLM: Maine Certification # BA-0174, BA-0178

PLM EPA NOB: Maine Certification # BA-0174, BA-0178

#### Analyst(s):

---

Stephen Severn	PLM (6) PLM Grav. Reduction (10)
Zackary Carbee	PLM (3) PLM Grav. Reduction (7)

#### Reviewed and approved by:

---

Christina Walker, Laboratory Manager  
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. This test report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. EMSL bears no responsibility for sample collection activities or analytical method limitations. The laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. PLM alone is not consistently reliable in detecting asbestos in floor coverings and similar NOBs

Samples analyzed by EMSL Analytical, Inc. South Portland, ME

Initial report from: 10/17/2016 09:17:04