

Letter of Correction

CITY OF PORTLAND
Fire Department
380 Congress Street
Portland, Maine 04101

File

Fire Inspection Violations

Business 7 APARTMENTS	Location 0077 CONGRESS ST	Number 66522-0-0	Inspection Type FP Routine Inspection
Owner/Manager Susan Baker-Caplin	CBL 014 F019001	Inspector ROBERT V PINDER Shift: 001 Unit: E1	

Code	Type	Location	Inspection Date	Target Compliance	Actual Compliance
1	NFPA18-1. Smoke detector needs repair	2nd. & 3rd. floor rear stairwell.	8/23/06	9/22/06	
2	101-5-21 Fire Doors Required	Apartment Doors	8/23/06	9/22/06	

10/1/06

Dear Sirs,
Thank you for your recent visit + inspection of 77 Congress St, Portland, Me 04101.

The above smoke detectors have been repaired. (Tenants unplugged them + have since vacated the building).

The fire doors are needing to be specially ordered + fitted. I am wondering if you would approve an action plan of replacing one at a time as they are very expensive. ??? Is one door per year reasonable? I need five replaced.

Thank-you very much.
Sincerely,
Susan Baker-Caplin