

Floor 1, Att 1

- HEAT :- No heat in bathroom or
- Entire bedroom
- No heat in Dining room
(Register near plants)

DRAFTS :- Checked throughout kitchen
cabinet below oven &
MOVED THROUGHT SEVERAL
HOLES IN FLOOR - now
fixed w/ insulation / some
COVERED w/ ROCKS
* COMING UP THROUGHT BASEMENT
TAPS currently in use

WATER DAMAGE :- Leaking by showering

- Doors - HAD REPLACED
TRIWE - Blatale wood
- WALK BY SHOWER DOORS
TURNS TO MUST w/ RAIN
AS RAIN POURS THE DRAINS
WITTER THE CEILING MEETS WALL
* ALL SLOPS OF SHOWER
- WATER COMES THROUGH ATTIC
IN MASTERS BEDROOM AND SET

PANTRY : OPENED IN CEILING, WILDES
ARE OVER THE PLACE

SMOKE DETECTORS = NONE WORKING

NONE IN BEDROOMS

CO₂ DETECTOR - NONE

Floor 2

Apt 2

- WATER DAMAGE - WATER PONES
TOUGH CAN LIGHTS
AND CEILING WHEN IT RAINS
- I THOUGHT IT WAS A CONTRACTOR
FOUND WOOD AND PAPER
FECTS & CLEW MARKS ON WELING,

HENT - NO HENT IN BATHROOM
BEDROOM OR BATHROOM

ANTS - INFESTATION IN WINDOWS

WIRINH - APT 2 TAINS HENT →
ELECTRICITY FOR
DASEMENT

- Front Porch - HAY - FIRE HAZARD
- NO RAILINGS
 - RUST & RUN OF
STEPS
 - 1/4 OF BOTTOM STAIR
IS MISSING