

**Jeanie Bourke - 118 Congress street field measurements for window heights**

---

**From:** David Lloyd <lloyd@archetypepa.com>  
**To:** Jeanie Bourke <jmb@portlandmaine.gov>  
**Date:** 4/2/2015 4:00 PM  
**Subject:** 118 Congress street field measurements for window heights  
**Attachments:** 118 On Munjoy Hill Second Floor Windows.pdf; 118 On Munjoy Hill Fourth Floor Windows.pdf; 118 On Munjoy Hill Third Floor Windows.pdf

---

Jeanie

Wright Ryan had one of their project engineers carefully measure all window heights with finish flooring in place . As you can see on the attached list most windows are 24 inches with a few being a 1/16<sup>th</sup> of an inch too low . This is much better than I anticipated . these dimensions do not include the screen frame which is an inch higher Please let us know your thoughts

Thank You

David

**David Lloyd****Architect**

Archetype, P.A.

48 Union Wharf

Portland, ME 04101

Tele: (207) 772-6022

Fax: (207) 772-4056

Cell: (207) 831-8627

[lloyd@archetypepa.com](mailto:lloyd@archetypepa.com)

<http://www.archetype-architects.com>

---

**From:** Tim Reinken [mailto:[treinken@wright-ryan.com](mailto:treinken@wright-ryan.com)]  
**Sent:** Thursday, April 02, 2015 3:29 PM  
**To:** David Lloyd - Archetype, PA ([lloyd@archetypepa.com](mailto:lloyd@archetypepa.com))  
**Cc:** Jason Le Shane; Tom Carey  
**Subject:** RE: 118 Fourth Floor Windows

Good Afternoon,

Please see the attached documents as discussed. Please let me know if you are looking for something different.

Thank you,

Tim Reinken, LEED Green Associate  
Project Engineer  
Wright-Ryan Construction, Inc.  
(207) 773-3625

---

**From:** Tom Carey

**Sent:** Thursday, April 02, 2015 2:53 PM  
**To:** David Lloyd - Archetype, PA ([lloyd@archetypepa.com](mailto:lloyd@archetypepa.com))  
**Cc:** Jason Le Shane; Tim Reinken  
**Subject:** FW: 118 Fourth Floor Windows

David – Attached is the diagram and spreadsheet for the 4<sup>th</sup> floor. The 4 red items seem like they do not pass. The yellow, do not add up to 24", but we feel that if we account for the slight slope of the finished window sill it meets. Tim is doing the same for the 2<sup>nd</sup> floor

However, we do not have flooring in in some units so it is impossible to tell our status in those units since we are measuring down to the 1/16<sup>th</sup>

Tom Carey, LEED AP  
Project Manager  
Wright-Ryan Construction, Inc.  
(207) 773-3625  
(207) 773-5173 Fax

---

**From:** Tim Reinken  
**Sent:** Thursday, April 02, 2015 2:37 PM  
**To:** Tom Carey  
**Subject:** 118 Fourth Floor Windows

Good Afternoon,

Please see the attached fourth floor window survey.

Tim Reinken, LEED Green Associate  
Project Engineer  
Wright-Ryan Construction, Inc.  
(207) 773-3625