

5. BENCH MARK: HIGHEST POINT ON "M" MONUMENT AT NORTHWESTERLY

CORNER OF ST. LAWRENCE AND FORE STREET, ELEVATION=69.35


NGVD 1929.

CASCO BAY VENTURES DATED 2-20-2001 BY BACK BAY BOUNDARY, INC.

3. STANDARD BOUNDARY SURVEY ON WATERVILLE STREET, PORTLAND, MAINE MADE

FOR LARRY DAVIS DATED SEPT. 12, 2000 BY OWEN HASKELL, INC.

GRAPHIC SCALE



LOCATION MAP

CONDOMINIUM PLAT

FORE ST. AND WATERVILLE ST, PORTLAND, MAINE MADE FOR OWNER OF RECORD PENINSULA PROPERTY DEVELOPMENT LLC


71 WEST ST., PORTLAND, ME 04102


OWEN HASKELL, INC. 390 U.S. ROUTE ONE, FALMOUTH, ME 04105 (207) 774-0424 PROFESSIONAL LAND SURVEYORS


PROFESSIONAL LAND SURVEYORS SEPTEMBER 24, 2015 2015-189P Trace By JLW Drwg. No. Check By JWS 1" = 10'Book No. FILE


OWEN HASKELL, INC. CERTIFIES THAT THIS PLAN IS BASED ON, AND THE RESULT OF, AN ON THE GROUND FIELD SURVEY AND THAT TO THE BEST OF OUR KNOWLEDGE, INFORMATION AND BELIEF, IT CONFORMS TO THE BOARD OF LICENSURE FOR PROFESSIONAL LAND SURVEYORS CURRENT STANDARDS OF PRACTICE.


JOHN W. SWAN, PLS NO. 1038











65 Newbury Street, Portland, ME 04101-4218 • Voice 207.761.9000 • www.portcityarch.com

31 Fore St Portland Maine

Pre-Application Meeting Questions

- 1. What Level of Review will the city of Portland require going from a 3-unit to a 5-unit?
- 2. Is location of new curb cut acceptable as shown on drawings?
- 3. Are the Elevator and stair tower located within 10ft setback above 35' acceptable?
- 4. Is a Deck located within 10ft setback above 35' acceptable?