





TYPICAL LOW LIFT GROUTING DETAIL













- 1. WHERE ANGLE LINTELS ARE REQUIRED, PROVIDE ONE ANGLE FOR EACH 4" OR LESS THICKNESS OF MASONRY.
- 2. FOR OPENINGS OVER 6'-0", PROVIDE SOLID MASONRY JAMB UNDER LINTEL AT EACH SIDE OF OPENING.
- 3. LINTELS INDICATED ON PLAN SUPERSEDE THE REQUIREMENTS OF THIS SCHEDULE.
- 4. ALL EXTERIOR LINTELS SHALL BE GALVANIZED.
- 5. ALL OTHER LINTELS SHALL BE PRIME PAINTED.




CMU BEAM BEARING DETAIL







TOP OF CMU WALL SUPPORT DETAIL



DETAIL

YPIC,

indicated

2017

RIMANTAS

VEITAS

→No. 9477

CENSED ON AL FIGURE

Portland LLC

exNorth

Ess

gue

S

Щ

THAMES STRE