



Jeanie Bourke <jmb@portlandmaine.gov>

107 India ASK-1 Top of wall Detail

Jeanie Bourke <jmb@portlandmaine.gov>

Mon, May 2, 2016 at 12:14 PM

To: Ryan Senatore <ryan@senatorearchitecture.com>

Cc: Laurie Leader <LRL@portlandmaine.gov>, Peter Bouchard <peter@bouchard.us>, Rich Meoli <indoorairinc@gmail.com>

Hi Ryan,

Thank you for sending this wall partition detail. It an acceptable method for maintaining the continuity of the rated horizontal assembly per Sec. 714.4.2 exception #7 of the 2015 IBC for membrane protection. This is approved per IBC Sec. 104.11 for alternative design methods, I will add this to the approved plans folder.

Let us know if you decided to contact the I-codes for further technical support on the prescriptive aspects of the wall plates in relation to the hourly rating of the floor/ceiling assembly.

Best,

Jeanie

Jeanie Bourke
Code Enforcement Officer/Plan Reviewer

City of Portland
Planning & Urban Development Dept./ Inspections Division
389 Congress St. Rm 315
Portland, ME 04101
jmb@portlandmaine.gov
(207)874-8715

[Quoted text hidden]