## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

August 23, 2017

Responsible Party 1:				
SHIPYARD BREWING COMPANY LIMITED				
86 NEWBURY ST				
PORTLAND, ME 04102				
T	CDY	T TO		
Location	CBL	Inspection Date		
Location 127 FORE ST	020 C009001	7/26/2017		
		-		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 9/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 7.9.1.1 EMERGENCY LIGHTING REQUIRED; Emergency lighting facilities for means of egress shall be provided in accordance with Section 7.9 for the following: (1) Buildings or structures where required in Chapters 11 through 43 (2) Underground and limited access structures as addressed in Section 11.7 (3) High-rise buildings as required by other sections of this code (4) Doors equipped with delayed-egress locks (5) Stair shaft and vestibule of smokeproof enclosures, for which of the following also apply: (a) The stair shaft and vestibule shall be permitted to include a standby generator that is installed for the smokeproof enclosure mechanical ventilation equipment (b) The standby generator shall be permitted to be used for the stair shaft and vestibule emergency lighting power supply (6) New access-controlled egress doors in accordance with 7.2.1.6.2 Emergency lighting throughout building needs to be working.	
<b>NFPA 88-3-6.5 APPROVED SAFETY CAN REQUIRED</b> ; An approved metal receptacle with a self-closing cover, used for the storage or disposal of oil soaked rags or clothes, is required. Rear loading dock storage of flamable liquids not in flamable locker	
CITY OF PORTLAND CODE CHAPTER 10- 21.5 HAZARDOUS MATERIALS  MANAGEMENT CABINET REQUIRED; Buildings required to comply with tier 2 shall provide a hazardous materials management cabinet on the exterior of the building. This shall also comply with Section 10-21.5 of Portland City Codes. See  www.portlandmaine.gov/citycode.htm.  55 gal. drums of cleaning agents stored on wooden pallets 3 high. Unsure if a containment device is needed. These are located in the bottling area. UNABLE TO LOCATE THIS AS A VIOLATION IN NFPA 101 OR UNDER HAZMAT REQUIREMENTS DUE TO THE PRODUCT AS OF THIS TYPE.	

Violation		Proposed Date of Completion
system shall have an accessible, member, or a listed gas convenie	<b>NNECTS BLOCKED</b> ; Each appliance connected to a piping approved manual shutoff valve with a nondisplaceable valve ence outlet. Appliance shutoff valves and convenience outlets ly and shall be installed in accordance with 9.6.4.1. t 36" from electrical pannel.	
FINAL DATE OF COMPLETED	VIOLATION(S)	//
FIRE PREVENTION BUREAU F	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
	to reject or modify any proposed plan of action, and may cal capacity to complete the proposed plan. Please contact ION	-
understand that I must contact is entirely within the Bureau's I further understand that it is	my responsibility to schedule a reinspection of my prope My failure to schedule a reinspection shall be deemed an	nest an extension, which rty once the violations
	reement, I understand that I am liable for penalties pursu §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be s	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	