STORMWATER DRAINAGE SYSTEM MAINTENANCE AGREEMENT

IN CONSIDERATION OF the site plan and subdivision approval granted by the Planning Board of the City of Portland to the proposed 70 Anderson Street Redevelopment shown on the Subdivision Plat recorded in the Cumberland County Registry of Deeds in Plan Book ____, Page ____ (the "Plan") and associated Grading, Drainage & Erosion Control Plan (Sheet C-30), dated 8/22/16 prepared by Acorn Engineering, Inc. of P.O. Box 3372, Portland, ME 04104 dated and pursuant to a condition thereof, Redfern Properties, LLC, a Maine limited liability company with a principal place of business in Portland, Maine, and having a mailing address of P.O. Box 8816, Portland, Maine 04101, the owner of the subject premises, does hereby agree, for itself, its successors and assigns (the "Owner"), as follows:

Maintenance Agreement

That it, its successors and assigns, will, at its own cost and expense and at all times in perpetuity, maintain in good repair and in proper working order the rain garden, roof dripline filter, storm drain pipes, and underdrain pipes (hereinafter collectively referred to as the "stormwater system") as shown on the Stormwater Maintenance Agreement Drainage Plan, Drawing EX-01, attached hereto as **Exhibit B** and in strict compliance with the approved Stormwater Inspection & Maintenance Plan and Stormwater Maintenance and Inspection Log, dated 8/22/16, copies attached as **Exhibit A and C** respectively and Chapter 32 of the Portland City Code.

Owner of the subject premises further agrees, at its own cost, to keep a Stormwater Maintenance and Inspection Log in the forms attached as **Exhibit C**. Such log shall be made available for inspection by the City of Portland upon reasonable notice and request.

Said agreement is for the benefit of the said City of Portland and all persons in lawful possession of the property and abutters thereto; further, that the said City of Portland or said persons in lawful possession may enforce this Agreement by an action at law or in equity in any court of competent jurisdiction; further, that after giving the Owner written notice and a stated time to perform, the said City of Portland, by its authorized agents or representatives, may, but is not obligated to, enter upon said premises to maintain, repair, or replace said stormwater system ,including but not limited to the rain garden, roof dripline

filter, storm drain pipes, underdrain pipes, and other drainage structures thereon in the event of any failure or neglect thereof, the cost and expense thereof to be reimbursed in full to the said City of Portland by the Owner upon written demand. Any funds owed to the City under this paragraph shall be secured by a lien on the property.

This Agreement shall not confer upon the City of Portland or any other person the right to utilize said stormwater system for public use or for the development of any other property, and the Owner shall bear no financial responsibility by virtue of this Agreement for enlarging the capacity of said system for any reason whatsoever.

This Agreement shall also not be construed to allow any change or deviation from the requirements of the subdivision and/or site plan most recently and formally approved by the Planning Board of the City of Portland.

This agreement shall bind the undersigned only so long as it retains any interest in said premises, and shall run with the land and be binding upon the Owner's successors and assigns as their interests may from time to time appear.

The Owner agrees to provide a copy of this Agreement to any successor or assign and to forward to the City an Addendum signed by any successor or assign in which the successor or assign states that the successor or assign has read the Agreement, agrees to all its terms and conditions and the successor or assign will obtain and forward to the City's Department of Public Works and Department of Planning and Urban Development a similar Addendum from any other successor or assign.


For the purpose of this agreement and release "Owner" is any person or entity who is a successor or assign and has a legal interest in part, or all, of the real estate and any building. The real estate shown by chart, block and lot number in the records on file in the City Assessor's office shall constitute "the property" that may be entered by the City and liened if the City is not paid all of its costs and charges following the mailing of a written demand for payment to the owner pursuant to the process and with the same force and effect as that established by 36 M.R.S.A. §§ 942 and 943 for real estate tax liens.

Any written notices or demands required by the agreement shall be complete on the date the notice is attached to one or more doors providing entry to any buildings or residential units and mailed by certified mail, return receipt requested or ordinary mail or both to the owner of record as shown on the tax roles on file in the City Assessor's Office.

If the property has more than one owner on the tax rolls, service shall be complete by mailing it to only the first listed owner. The failure to receive any written notice required by this agreement shall not prevent the City from entering the property and performing maintenance or repairs on the stormwater system, or any component thereof, or liening it or create a cause of action against the City.

Dated at Portland, Maine this	_ day of August, 2016.						
	REDFERN PROPERTIES, LLC A Maine limited liability company						
	Jonathon Culley, Manager						
STATE OF MAINE CUMBERLAND, ss.	Date:						
	med Jonathon Culley, Manager of Redfern egoing instrument to be his free act and deed in						
	Before me,						
	Notary Public/Attorney at Law						
	Print name:						
Exhibit A: Stormwater Inspection & Mainte	enance Plan						
Exhibit B: Stormwater Maintenance Agreen	nent Drainage Plan						

Exhibit C: Stormwater Maintenance and Inspection Log



POST CONSTRUCTION - STORMWATER INSPECTION & MAINTENANCE PLAN

Prepared For:


Redfern Properties, LLC 70 Anderson Street Redevelopment Portland, Maine 04101

Prepared By:

Acorn Engineering, Inc. PO Box 3372 Portland, Maine 04104



AUGUST 2016



RESPONSIBLE PARTY

The owner, Redfern Properties, LLC, and/or their successor shall be responsible for contracting with a qualified stormwater professional to implement the Inspection and Maintenance Plan. The qualified stormwater professional shall maintain a stormwater log (report) summarizing inspections, maintenance, and corrective action taken. The Qualified Stormwater Professional shall annually submit the Stormwater Log to the Department of Public Services prior to June 30th.

The following is an example of a qualified stormwater professional that the owner may contract through.

Organization: Will Savage, PE

Acorn Engineering, Inc

Portland, Maine

Phone: (207) 775-2655

Qualifications:

- Maine Professional Engineering License #11419
- Maine DEP Certified in Maintenance & Inspection of Stormwater BMP's Cert #14
- Certified Erosion, Sediment and Storm Water Inspector (CESSWI) Cert #0293
- Certified Professional in Erosion and Sediment Control (CPESC) Cert. #4620

The inspection and maintenance criteria is based upon the Maine DEP - Stormwater Management for Maine, Volume III: BMPs Technical Design Manual. Refer to the Grading, Drainage, & Erosion Control Plan, revised August 22^{nd} , 2016 or the latest version for the location of the BMPs.

PURPOSE

This Inspection and Maintenance Plan has been individually tailored to this parcel's stormwater infrastructure, site characteristics, and their respective opportunities and limitations related to reducing the pollutant load on the receiving watershed. The maintenance of a parcel's impervious surfaces and stormwater infrastructure is critical to extending the long term performance and effectiveness of Best Management Practices (BMPs). The Inspection and Maintenance Plan represents the parcel's minimum activities to meet the permit requirements. The parcel shall still be subject to any applicable Civil Site Plans, Permit Applications, Erosion and Sedimentation Control Plans Reports, Stormwater Management Plans, Inspection and Maintenance Manuals, and all Municipal, State, and Federal rules.

OPERATION AND MAINTENANCE ACTIVITY

Underdrained Bioretention Cell "Rain Garden":

The maintenance of the rain garden shall be in accordance with the following activities identified below and the most recent version of the Maine DEP Volume III BMPs Technical Design Manual Chapter 7.2 Underdrained Bioretention Cell BMP.

- ➤ The soil filter shall be inspected after every major storm within the first year to ensure the filter area is draining within a 48-hour period and no less than a 24-hour period, and that the plants are establishing. Thereafter, the filter should be inspected at least once every six months to ensure that is draining within a 48-hour period following a one-inch storm or greater.
- > Soil filter modification shall occur if the filter bed is draining in less than 24 hours. The top six inches of the filter shall be replaced with six inches of loam, per the most recent Maine DEP specification. Soil filter replacement shall be replaced with fresh material on a yearly basis
- > The filter area shall not be fertilized unless it is absolutely necessary.
- ➤ Harvesting and pruning of excessive growth shall be done occasionally. Weeding to control unwanted or invasive plants may be necessary and plants that are not thriving must be replaced.
- ➤ Inspect the overflow outlet at least annually to ensure it is in good working order and unobstructed from trash and debris. Removed sediments should be disposed of in an acceptable manner.

Roof Dripline Filter:

The maintenance of the roof dripline shall be in accordance with the following activities identified below and the most recent version of the Maine DEP Volume III BMPs Technical Design Manual Chapter 7.5 Roof Dripline Filtration BMP and Chapter 7.2 Underdrained Bioretention Cell BMP.

- > The stone reservoir layer shall be inspected after every major storm within the first year to ensure the filter area is draining within a 48-hour period and no less than a 24-hour period. Thereafter, the filter should be inspected at least once every six months to ensure that is draining within a 48-hour period following a one-inch storm or greater.
- Any debris must be removed from the reservoir course at any time. Weeding of any growth is to be done as necessary to keep the stone layer clear.
- ➤ Cleanout to be visually inspected for possible obstruction during periodic inspections. If more than one foot of standing water is observed, remove any sediments or obstructions and dispose of in an acceptable manner.
- ➤ No gutter may be installed on the roof line above the dripline.

Sweeping:

Annual sweeping of the parking lot and internal sidewalks following the snow melt for accumulated winter sand, if necessary. All material is to be appropriately disposed of.

Storm Drains:

The storm drain shall be annually inspected for the presence of accumulated sediment or debris. Any sediment shall be removed as required.

- > The equipment shall meet the following minimum specifications; power jet and water source for washing down the storm drain, vacuum attachment for catch basin cleaning, and a liquid handling method to dewater the material.
- ➤ Inspect and legally dispose of accumulated sediment and debris within the storm drains between basins. Liquids must be decanted on-site and returned to the catch basin.


Landscaped, Vegetated and Areas Adjacent to Retaining Walls:

Inspect all landscaped and or vegetated slopes and embankments on an annual basis. Vegetated areas with bare areas or sparse growth (< 90% coverage) shall be revegetated. Mulch shall be applied to landscaped areas, as necessary. Dead or decaying landscaping (ground cover, shrubs, trees etc.) shall be replanted in accordance with the contract documents.

If signs of rill erosion or scour are present within areas tributary to the retaining walls, Acorn Engineering should be immediately contacted to perform an inspection and/or to contact the appropriate professional. Periodic inspections of the retaining walls shall be performed, under separate contract, by a Professional Geotechnical Engineer.

INSPECTION AND MAINTENANCE TABLE

Inspection and Maintenance Frequency	Spring or Yearly	Summer	Fall	As Necessary
Rain Garden	X	X		X
Roof Dripline	X	X		X
Storm Drains		X		X
Sweeping	X			X
Landscaped/Vegetated/Wall Areas	X			X



BIORETENTION CELL "RAIN GARDEN" BMP:									
Location:	n: 70 Anderson Street, Portland ME 04101						43.665095		
70 Anderso	n Sireei, F	ortiand r	Longitude: -70.2547						
Description of Located Point:			Inspector:						
Center of Pr	onerty In	Retween	Ruildings	2	Date of Insp				
	operty, iii	DOWCON	Dallallige		Weather Co				
Days since last precipitation					MEDEP Perr		YES		
Quantity of last precipitation (in)					Design Drav	vings:			
	-	1	•		1				
Maintenance Items	Inspect In Spring	Inspect In Fall	Inspect As Necessary		Maintenance Requested (Date)	Maintenance Completed (Date)	Summary of Maintenance Required		
Underdrained Ditch, Vegetated Ur	nderdrain	Soil Filt	er, Bio-re	tention Ce	ell, etc.				
Soil filter retains the design volume for a drain down time greater than 24-hours and less than 48-hours	V	✓		Yes No N/A					
Permeability is between 2.4 and 4 in/hr		7		Yes No N/A					
Filter bed consists of at least 6 in of loam			>	Yes No N/A					
Filter bed planting height is no less than 6"			<	Yes No N/A					
Filter area is properly planted, showing no bare spots and free of unwanted vegetative growth		✓		Yes No N/A					
The outlet control structures (2) are in good working condition and free of debris		V		Yes No N/A					
Plantings are in good condition and do not show signs of rot or decay		✓		Yes No N/A					

Maintenance Items	Inspect In Spring	Inspect In Fall	Inspect As Necessary		Maintenance Requested (Date)	Maintenance Completed (Date)	Summary of Maintenance Required
General							
Access to facility is adequate		>		Yes No N/A			
Photographs of most recent site inspection are included		>					Photographs are attached.
Additional Comments:							

ROOF DRIPLINE FILTER BMP:								
Location: 70 Anderson Street, Portland ME 04101					Latitude:		43.665186	
70 Anderson	Ortiana n	Longitude:		-70.254877				
Description of Located Point:		Inspector:						
Along the rear of Building B to the northwest of the property					Date of Insp	ection:		
Along the real of Buildi	ng b to t	ie northy	vesi oi in	e property	Weather Co	Weather Conditions:		
Days since last precipitation					MEDEP Perr	nit#	YES	
Quantity of last precipitation (in)					Design Drav	vings:		
Maintenance Items	Inspect In Spring	Inspect In Fall	Inspect As Necessary		Maintenance Requested (Date)	Maintenance Completed (Date)	Summary of Maintenance Required	
Underdrained Ditch, Vegetated Und	derdrain	Soil Filt	er, Bio-re	etention Ce	ell, etc.			
Reservoir stone layer retains the design volume for a drain down time greater than 24-hours and less than 48-hours	7	✓		Yes No N/A				
Permeability is between 2.4 and 4 in/hr		7		Yes No N/A				
Reservoir stone is at least 12" deep			>	Yes No N/A				
Reservoir layer is free from growth			7	Yes No N/A				
The cleanout is free from obstruction and flowing freely, less than 1' of standing water is observed		∀		Yes No N/A				

Maintenance Items	Inspect In Spring	Inspect In Fall	Inspect As Necessary		Maintenance Requested (Date)	Maintenance Completed (Date)	Summary of Maintenance Required
General							
Access to facility is adequate		>		Yes No N/A			
Photographs of most recent site inspection are included		>					Photographs are attached.
Additional Comments:							

STORMWATER PIPE:									
Location:				Latitude: 43.66					
70 Anderson S	treet, Po	rtland ME	E 04101		Longitude		-70.244181		
Description of Located Point:			Inspector						
Ctownsustan Ducin	مد بامد ده	Municin	al Cuatan	_	Date of Ins	spection:			
Stormwater Drain	outlet to	wunicip	ai Systen	[]	Weather C	onditions:			
Days since last precipitation:					MEDEP Pe	ermit #:	N/A		
Quantity of last precipitation (in):					Design Dra	awings:	YES		
Maintenance Items	Inspect In Spring	Inspect In Fall	Inspect As Necessary		Maintenance Requested (Date)	Maintenance Completed (Date)	Summary of Maintenance Required		
Inlets, Outlets, & Storm Drains									
mioto, Gatioto, a Gtorm Braino				Yes					
Pipe is free of obstruction,			V	□No					
accumulated sediment and debris				□ N/A					
Pipe inlet and outlet is free of				Yes					
obstruction, accumulated sediment									
and debris	✓	✓		∐ No					
and debits				☐ N/A					
Pipe, inlet and outlet is free of				☐ Yes					
collapses and structural damage	✓	✓		∐ No					
				∐ N/A					
Outlet and inlet are properly		_		☐ Yes					
conveying stormwater and no erosion	√	✓		∐ No					
is visible				☐ N/A					
General			1		1				
				Yes					
Access to facility is adequate	✓	✓		☐ No					
				□ N/A					
Photographs of most recent site	4						Photographs are attached.		
inspection are included	~	✓					eteg.ap.ie are attached.		
Additional Comments:									

VEGETATED AREAS:								
Location:					Latitude: 43.665095			
70 Anderse	on Street	t, Portlan	d ME 041	101	Longitude: -70.254757			
Description of Located Point:				Inspector:				
Bordering the park	arracas	and withi	Date of Inspection:					
Dordening the pair	rden	and with	II UIC INAIII	Weather Conditions:				
	<u> </u>	14611			Design Draw	rings:	YES	
		ı	1		1	1		
Maintenance Items	Inspect In Spring	Inspect In Fall	Inspect As Necessary		Maintenance Requested (Date)	Maintenance Completed (Date)	Summary of Maintenance Required	
Embankments								
Slopes and embankments are				Yes				
in good condition.		✓		☐ No				
in good condition.				☐ N/A				
		7		Yes				
Site is free of rill erosion				☐ No				
				□ N/A				
General								
Site is free of locations with less				Yes				
than 90% vegetative cover			✓	☐ No				
than 50% vegetative cover				□ N/A				
Diantings are concluded				Yes				
Plantings are capable of withstanding concentrated flows			~	☐ No				
with standing concentrated nows				☐ N/A				
				Yes				
Access to facility is adequate		V		☐ No				
				□ N/A				
Photographs of most recent site inspection are included		V					Photographs are attached.	
Additional Comments:					•			