## iO500RD Addressable Fire Alarm System 161 Marginal Way Portland, Maine

## **SEQUENCE OF OPERATION MATRIX**

		Annunciate at Fire A.		Shutdown HIVA	Activate Appropriate	Record Event (	Supervisory Signal	Trouble Signal to Central Station Dicit.	
System Inputs	Α	В	С	D	E	F	G	Н	System Inputs
Manual Pull Station	x	x	х			х			Manual Pull Station
Smoke Detector	х	х	х			х			Smoke Detector
Heat Detector	х	х	х			х			Heat Detector
Duct Smoke Detector		х				х	х		Duct Smoke Detector
Elevator Smoke Detector	х	x	х		х	х			Elevator Smoke Detector
Elevator Heat Detector	х	х	х		х	х			Elevator Heat Detector
Fire Alarm - AC Failure		х				х		х	Fire Alarm - AC Failure
Fire Alarm - Low Battery		х				х		х	Fire Alarm - Low Battery
Signal Line Open Circuit		х				х		х	Signal Line Open Circuit
Signal Line Ground Fault		х				х		х	Signal Line Ground Fault
Horn/Strobe Circuit Open		х				х		х	Horn/Strobe Circuit Open
Horn/Strobe Circuit Ground		x				х		х	Horn/Strobe Circuit Ground
System Ground Fault		х				х		х	System Ground Fault
	Α	В	С	D	Е	F	G	Н	