



The 2 small service panels originally scheduled for this location per Ron G.'s 2/3/10 change request should be relocated to the opposite wall as shown.