

CONSTRUCTION DOCUMENTS

HAMPTON INN PARTIAL RENOVATION

209 FORE ST, PORTLAND, MAINE 04101

INDEX TO DRAWINGS

ARCHITECTURAL DRAWINGS

- COVER SHEET A0.0
- EXISTING OVERALL SECOND FLOOR PLAN A1.0
- SECOND FLOOR A1.1
- ENLARGED PLANS, ELEVATIONS, & SCHEDULES A1.2

INTERIOR DESIGN DRAWINGS

ID4.01 ENLARGED GUESTROOM PLANS

- **ID4.11 GUESTROOM ELEVATIONS**
- ID4.21 GUEST DETAILS

MECHANICAL AND PLUMBING DRAWINGS

M1.1 MECHANICAL PLANS E1.1 ELECTRICAL PLANS

BUILDING CODE DATA

APPLICABLE CODES:

2010 MAINE UNIFORM BUILDING AND ENERGY CODE CONSISTING OF:

2009 INTERNATIONAL BUILDING CODE (IBC) 2009 INTERNATIONAL EXISITNG BUILDING CODE (IEBC) 2009 INTERNATIONAL ENERGY CONSERVATION CODE (IECC) 2007 ASHRAE (62.1, 62.2. AND 90.1) E-1465-2006 STANDARD PRACTICE FOR RADON CONTROL OPTIONS

DRAWINGS HAVE BEEN DESIGNED AND WORK PERFORMED SHALL BE IN COMPLIANCE WITH THE 2010 MAINE UNIFORM BUILDING AND ENERGY CODE AND WITH THE CITY OF PORTLAND, MAINE MUNICIPAL CODE.


BUILDING CODE ANALYSIS:

122 EXISTING GUEST ROOMS

3 PROPOSED ADDITIONAL GUEST ROOMS IN REMODELED AREA WHERE EXISTING MEETING ROOM IS LOCATED.

LEVEL 2 ALTERATION (LESS THAN 50% OF EXISTING BUILDING AERA REMODELED) PER THE 2010 MAINE UNIFORM BUILDING CODE (MUBC).

EXISTING LEVEL OF FIRE PROTECTION AND MEANS OF EGRESS SHALL BE MAINTAINED.



15012.PMHR

AREA OF RENOVATION: 2ND FLOOR = 1385 SF

R-1 OCCUPANCY AT REMODEL AREA **EXISTING 6 STORY BUILDING EXISTING BUILDING HEIGHT: 65'-8" TYPE 1B NON-COMBUSTIBLE CONSTRUCTION** 1-HOUR FIRE PARITIONS WITH 45 MINUTE RATED OPENINGS BETWEEN GUEST ROOM AND ELEVATOR LOBBY AUTOMATIC SPRINKLER SYSTEM PER NFPA 13. OCCUPANT LOAD AT EACH GUEST ROOM IS 4, ALLOWING ONE EXIT PER TABLE 1015.1 7 EXISTING ACCESSIBLE GUEST ROOMS ARE PROVIDED IN THE HOTEL, 4 WITH ROLL-IN SHOWERS AND 3 WITH TUBS.

NFPA 101 CODE SUMMARY: AREA OF REMODEL - 2ND FLOOR = 1385 SF RESIDENTIAL OCCUPANCY

EXISITNG BUILDING MIXED SEPARATED OCCUPANCY 1ST FLOOR: ASSEMBLY - RESTAURANT 2ND - 4TH STORY: RESIDENTIAL - HOTEL 5TH - 6TH STORY: RESIDENTIAL - APARTMENTS

ORDINARY HAZARD CONTENTS

MEANS OF EGRESS: EXISTING REMAINS UNCHANGED

EMERGENCY LIGHTING PROVIDED AT REMODEL AREA PER MEP DRAWINGS.

FIRE ALARM SYSTEM: EXISTING REMAINS UNCHANGED

EXISITNG AUTOMATIC SPRINKLER SYSTEM PER NFPA 13

SITE INFORMATION

CBL: 029 L00100H

LEGAL DESCRIPTION: 29-L-1-2 FORE ST 221-237 MIDDLE ST 78 FRANKLIN ST HOTEL REST PORTSIDE RED CONDO HOTEL UNIT

EXISTING ON-SITE PARKING TO REMAIN.



FEBRUARY 27, 2015





Springfield, Missouri 65806 Phone: 417.521.6107

319 N. Main Ave., Suite 200

Colvin Jones Davis LLC Engineering | Energy | Innovation 2101 West Chesterfield Blvd., Suite B-105A, Springfield, MO 65807 ph: 417.877.1700 fx: 417.877.1701 www.colvinjonesdavis.com

INTERIOR DESIGN GROUP HAMPTON INN PART 209 FORE ST, PORTI 15012.PMHR FEBRUARY 27, 2015