SECTION 10005

MISCELLANEOUS SPECIALTIES

1 PART 1 GENERAL

1.1 RELATED DOCUMENTS

A. Drawings and general provisions of Contract including General and Supplementary Conditions and Division 1 specification sections apply to Work of this section.

1.2 SECTION INCLUDES

- A. Fire extinguishers.
- B. Fire extinguisher cabinets.
- C. Knox Boxes

1.3 SUBMITTALS

- A. Product Data: Provide data on Product, and accessories.
- B. Operating and Maintenance Instructions: Include relevant instructions. Include maintenance information.

1.4 QUALITY ASSURANCE

A. Fire Extinguishers: Conform to NFPA 10.

2 PART 2 PRODUCTS

2.1 FIRE EXTINGUISHERS

- A. Manufacturers:
 - 1. Allenco.
 - 2. Amerex.
 - 3. Ansul Fire Protection
 - 4. Bobrick Washroom Equipment.
 - 5. JL Industries.
 - 6. Larsen's Manufacturing Co.
 - 7. Potter-Roemer/Div. Smith Industries Inc.
 - 8. Walter Kidde/Div. Kidde Inc.
- B. Multi-Purpose Dry Chemical Type: Enameled steel tank, with pressure gage, 2A:10BC rating.
- C. Cabinets: Semi-recessed type, steel cabinet, full glass door with baked enamel finish.

- 1. Provide fire rated cabinet when installing in fire rated wall partition equal to rating of wall partition.
- D. Brackets: Manufacturer's standard surface mounted bracket for extinguishers not indicated to have a cabinet.

2.2 KNOX BOXES

A. Manufacturers: Knox Co. #3200 Series Rapid Entry System with Recessed Mounting Kit.

3 PART 3 EXECUTION

3.1 EXAMINATION AND PREPARATION

A. Verify that surfaces and internal wall blocking are ready to receive work and opening dimensions are as instructed by the manufacturer.

3.2 INSTALLATION - FIRE EXTINGUISHERS

- A. Install extinguishers in accordance with manufacturer's instructions.
- B. Mount units to conform to ADA requirements, with top less than 48" above floor.
- C. Install units level and plumb in wall openings.

3.3 INSTALLATION - KNOX BOXES

- A. Install knox boxes in accordance with manufacturer's instructions.
- B. Install units level and plumb.
- C. Install knox box at location indicated on drawings and as confirmed by local fire official.

...END OF SECTION