CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

April 20, 2017

HERBSIRA LLC 100 WILD FERN DR LONGWOOD FL 32779

Location	CBL	Inspection Date	
237 HIGH ST	036 G010001	4/2/2017	
Inspector	Inspection Type	Status	
Angela Calvo	FP Routine Inspection	Failed	

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 5/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation. doors on all units need unit numbers (paper sign above door, such as unit 2's, does not meet standard)	//
NFPA 101- 7.2.1.5.2 ILLEGAL LOCKS ON EXIT DOOR; Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. padlock on the exterior of the d-side cellar door must be removed	IMMEDIATELY remove or disable all illegal locks on exit doors. Your signature below indicates that the illegal locks have been removed or disabled and will not be replaced.
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements. smoke detector missing from first floor hallway, wires exposed	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 1 EXCESSIVE/DISORDERLY STORAGE; Reference NFPA 1 for excessive fuel-load. all storage must be removed from all hallways and stairways	//

Violation		Proposed Date of Completion
FINAL DATE OF COMPLET	ED VIOLATION(S)	//
FIRE PREVENTION BUREAU RE-INSPECTION OF COMPLETED VIOLATION(S)		//_
	ht to reject or modify any proposed plan of action, and manical capacity to complete the proposed plan. Please contaction	
understand that I must cont	tions listed within the timeframes provided. If I require actes the Fire Prevention Bureau prior to the deadline to resu's discretion to grant or deny.	1 1
v	is my responsibility to schedule a reinspection of my propo. My failure to schedule a reinspection shall be deemed medied.	
	agreement, I understand that I am liable for penalties purses $\S\S$ 1-15 and 10-25, and 30-A M.R.S. \S 4452 and may b	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		

Fire Prevention Bureau

Date