

<b>Greater Portland YMCA High Street Entry</b>						5/13/2005				
<b>WINDOWS SCHEDULE</b>										
<b>No.</b>	<b>Window Manufacturer</b>	<b>Unit Type</b>	<b>Model No.</b>	<b>Approx. Unit Width</b>	<b>Approx. Unit Height</b>	<b>Required Egress</b>	<b>Low "E" Insul-Glass (5)</b>	<b>Insect Screen</b>		
A	Andersen	Woodwright	Double-Hung	2'-8"	4'-8"	No	Yes	Yes		
B	Andersen	Woodwright	Picture	2'-8"	2'-8"	No	Yes	Yes		
C	Kawneer	Aluminum Storefront	EnCore	4'-0" diameter		No	No	No		
D		Hollow Metal		2'-8"	4'-0"	No	No	No		
E		Hollow Metal		3'-3"	4'-4"	No	No	No		
1. Verify rough openings and masonry openings prior to framing and the manufacturing of all window units.										
2. Insulate Between Window and Rough Opening as recommended by window manufacturer.										
3. Provide Safety Glazing as Required by CPSC Regulations.										
<b>The Contractor is asked to provide alternate pricing for four different window types.</b>										
<b>Type No. 1 - Andersen Woodwright - fibrex/wood</b>										