CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

July 18, 2017

Burnham Towers Annex LLC PO Box 2282 SCARBOROUGH ME 04070

Location	CBL	Inspection Date
207 HIGH ST	036 G026001	6/21/2017
Inspector	Inspection Type	Status
Edward Doughty	FP Routine Inspection	Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 8/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 7.2.2.4.2 HANDRAILS ARE NOT CONTINOUS ; Required guards and hardrails shall continue for the full length of each flight of stairs. At turns of new stairs, inside handrails shall be continuous between flights at landings.	
Handrails cannot be installed in such a manner that clothing, jewelry, personal bags, etc. can be caught in reagrds to emergency egrees from the building * Rear Stairwell	
NFPA 101- 7.2.1.8.1 DOORS SHALL BE SELF-CLOSING & SELF-LATCHING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise specified by 7.2.1.8.3. Apartment Doors, Basement Doors, and Exterior Doors	
NFPA 101-7.2.2.3.1.1 STAIRS MUST BE MAINTAINED SOLID; All stairs serving as required means of egress shall be of permanent fixed construction, unless they are stairs serving seating that is designed to be repositioned in accordance with Chapter 12 and 13. Basement Stairs need a Plan of Action for replacement	
NFPA 80- ANNEX D.4 1-HOUR FIRE DOORS ASSEMBLIES REQ; Listings are provided for floor fire door assemblies that are installed in fire-rated floor-ceiling or roof-ceiling assemblies that have been tested in accordance with the methods described in NFPA 288. The listing indicates the fire-rated assembly and the hourly rating (3 hours, 2 hours, 1.5 hours, 1 hour, .75 hours) for which the door can be permitted to be used so that access to the space above the ceiling or to the floor above can be provided without adversely affecting the fire resistance rating of the entire assembly. The listing provides limitations on the maximum size of an individual door opening and the total area of all door openings permitted for each 100 square feet of floor or ceiling. Basement needs a Fire Door for Protection to the second means of Egress	

Violation		Proposed Date of Completion
to require an access box(es) to a structure or area is difficult be type listed in accordance with U systems require Knox access.	RTMENT KNOX BOX REQ; The AHJ shall have the authority be installed in an accessible location where access to or within ecause of security. The access box(es) shall be of an approved JL 1037. Properties with fire alarm systems and fire supression	
in the Area of the Front Entry D		
MARKED ON BUILDING; 4.3.1 approaching from the main accilluminated or retro reflective on approved by the Fire Departme	ENT CHAPTER 10 4.3.1, 4.3.2 BUILDING ADDRESS NOT I Signs shall be located in a position readily visible as ess and approved by the Fire Department. Signs shall be a contrasting background and the letter(s) size shall be nt. 4.3.2 Street Address shall be clearly marked on the front of a approved by the Fire Department. In tof the Building worn	
FINAL DATE OF COMPLETE	D VIOLATION(S)	//
FIRE PREVENTION BUREAU	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
understand that I must contact is entirely within the Bureau I further understand that it is have been remedied to do so. violations have not been rem If I fail to comply with this as	ons listed within the timeframes provided. If I require addict the Fire Prevention Bureau <u>prior to the deadline</u> to requis discretion to grant or deny. Is my responsibility to schedule a reinspection of my proper My failure to schedule a reinspection shall be deemed an	nest an extension, which orty once the violations or admission that the ant to the City of
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	