© 2013 RYAN SENATOR ARCHITECTURE

RENOVATIO ADE

'PETRARCH' COMPOSITE PANEL

CENTER BLADE SIGN ON WINDOW ABOVE

CLEAN GRANITE BAND

FOR SIGN DETAILS SEE SHEET A2-1

COMPOSITE PANEL RETURN

THERMALLY BROKEN INSULATED

- 'T' INDICATES TEMPERED GLASS

'S' INDICATES SPANDREL GLASS

- BASE - 'PETRARCH' COMPOSITE PANEL

COLOR 'GRAPHITE', FINISH 'SMOOTH'

AT HEAD OF STOREFRONT

SEALANT JOINT COLOR

STOREFRONT SYSTEM

TO MATCH PANEL

COLOR - BLACK

3/8" PANEL CORNER JOINT ON INSIDE FACE

HOLD PANEL 1/4" UP FROM GRADE - DO NOT CAULK

OF RECESSED ENTRY - CAULKED

ON PT BLOCKING AND PLYWOOD

BUILDING 9 TRANI

RYAN SENATORE **ARCHITECTURE** GORHAM, MAINE 04038

207-650-6414 senatorearchitecture.com

CONSULTANTS:

REVISIONS:

JUNE 27, 201 PROJECT No.

DRAWN BY: CHECKED BY:

SCALE: AS NOTE SHEET TITLE:

STOREFRONT - 2 **DETAILS**

ELEVATION DETAIL

EQUAL

MAD WORLD

S

LED SIGN LIGHT ALL LOW VOLTAGE WIRING

REMOTE TRANSFORMER INSIDE BUILDING

4 A2-2

REMOVE STUCCO AT AREA BEHIND

FASTENED TO BUILDING FRAMING

| BLADE SIGN MOUNTING PLATE

INSTALL SOLID BLOCKING

CONCEALED, RUN TO

AS REQUIRED AND



INSTALL EXPOSED PANEL FASTENERS IN PATTERN SHOWN (DO NOT

CAP FLASHING WITH DRIP EDGE

STOREFRONT FILLER

COLOR TO MATCH STOREFRONT

SEAL ALL JOINTS BETWEEN PANELS

3'-0"X 7'-0" WIDE STILE STOREFRONT DOOR

WITH 1" DIA. EXTERIOR PULL, INTERIOR CLOSER AND

NEW 12X24 ANTI-SLIP TILE AT ENTRANCE RAMP

RESET BRICKS AT NEW TILE EDGE FOR FLUSH

FOR ACCESSIBLE SIDEWALK TOLERANCES

TRANSITION ADJUST BRICKS OUT AS REQUIRED

'PETRARCH' COMPOSITE PANEL WITH EXPOSED FASTENERS

INTERIOR PANIC HARDWARE

STOREFRONT CORNER MULLION

CUSTOM ANGLE DETAIL

EXCEED 24" O.C. MAXIMUM SPACING)

THERMALLY BROKEN SPANDREL GLASS STOREFRONT WITH SUBSILL EXISTING PLATFORM FRAMING SHIM, BACKER ROD AND SEALANT NEW 1/2" MDF PANEL BEHIND ALL PREFINISHED ALUMINUM FLASHING AREAS OF SPANDREL GLASS WITH 1/2" HEMMED DRIP EDGE AND PAINTED 'BLACK' BACK AND END DAMS EXISTING FLOOR / FOUNDATION WALL - COLOR MATCH STOREFRONT CONDITION, REMOVE AND PETRARCH COMPOSITE PANEL DAMAGED OR ROTTEN MATERIALS CLEAN REPAIR AND REPLACE S/S PAN HEAD FASTENERS SEAL FRAMING TO FOUNDATION WITH SEALANT 2X PT FRAMING FOR STOREFRONT BASE BITUMINOUS ADHERED SHEET FLASHING TO FRAMING AND 6" DOWN ONTO FOUNDATION REMOVE AND RESET BRICK SIDEWALK AS REQUIRED

(PROIVDE CONCRETE FASTENERS IF SUBSTRATE REQUIRES)



