CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

October 26, 2017

Location: Mainley Frames	CBL	Inspection Date	
541 CONGRESS ST	037 C01701B	8/30/2017	
Inspector	Inspection Type	Status	

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 11/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 8.7.3.1 AND 8.7.3.2 FUEL POWERED DEVICE STORED INSIDE; The storage and handling of flammable liquids or gases shall be in accordance with the following applicable standards: NFPA 30, Flammable and Combustible Liquids Code NFPA 54, National Fuel Gas Code NFPA 58, Liquefied Petroleum Gas Code (8.7.3.1). No storage or handling of flammable liquids or gases shall be permitted in any location where such storage would jeopardize egress from the structure, unless otherwise permitted by 8.7.3.1 (8.7.3.2) propane tank and heater in basement	
NFPA 54- 9.6.4 UTILITY DISCONNECTS BLOCKED; Each appliance connected to a piping system shall have an accessible, approved manual shutoff valve with a nondisplaceable valve member, or a listed gas convenience outlet. Appliance shutoff valves and convenience outlets shall serve a single appliance only and shall be installed in accordance with 9.6.4.1. In basement	
NFPA 10- 7.1.1 FIRE EXTINGUISHERS NEED ANNUAL SERVICE; The owner or designated agent or occupant of a property in which fire extinguishers are located shall be responsible for inspection, maintenance, and recharging. Extinguishers on site are expired	
NFPA 101- 37.3.1 PROTECTION OF VERTICAL OPENINGS (COMBINED MERCANTILE AND PARKING STRUCTURES); Any vertical opening shall be protected in accordance with Section 8.6, except under the following conditions: Refer to NFPA 101- 37.3.1 for continuation of this code. Penertrations in fire wall in basement	

Violation		Proposed Date of Completion
RETAIL BUILDINGS) ; Bulk mer approved, supervised automatic	chandising retail buildings shall be protected throughout by an sprinkler system in accordance with 9.7.1.1(1) and the wing: NFPA 1 NFPA 13 NFPA 30 NFPA 30B	-
Merchandise placed to close to s	sprinkler heads in basement	
deflector and the top of storage s	NKLER HEAD BLOCKED; The clearance between the shall be in 18 inch (457 mm) or greater. Where other unce to storage minimums, they shall be followed. sprinkler heads in basement	//
FINAL DATE OF COMPLETED	VIOLATION(S)	//
FIRE PREVENTION BUREAU I	RE-INSPECTION OF COMPLETED VIOLATION(S)	
understand that I must contact is entirely within the Bureau's I further understand that it is have been remedied to do so.	ns listed within the timeframes provided. If I require addit t the Fire Prevention Bureau <u>prior to the deadline</u> to require to discretion to grant or deny. my responsibility to schedule a reinspection of my proper My failure to schedule a reinspection shall be deemed an	est an extension, which ty once the violations
	died. reement, I understand that I am liable for penalties pursua §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be s	
Date	Responsible Party	
Date SEEN AND ACREED	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	