Dependable Hood & Duct Cleaning Company, LLC

424 Old Candia Road - Unit 1 Candia, NH 03034 603-483-0199

www.nhhoodcleaning.com Service@dependablehood.com

Account :Westin Portland HarborviewDate of Service :02/06/2020Location :Westin Portland HarborviewFrequency :90 daysLoc.Add :157 High StreetTech Name:Levi Amador

Portland, ME 04101

Date: 02/07/2020 **Cert:** EXHOOD310815

Phone: (207) 517-8830 **EXP Date:** 12/31/2022

Service	Options	Comments
1. Are the filters clean?	Yes	Filters have been thoroughly washed.
2. Do any filters need replacement?	No	
3. Is the grease load less than 2000 microns: (Horizontal)	Yes	
4. Is the grease load less than 2000 microns: (Vertical)	Yes	
5. Is the grease load less than 2000 microns: (Hood)	Yes	
6. Is the fan grease load less than 3175 microns?	Yes	
7. Last cleaning/inspection date:	11/26/2019	
8. Did you clean or inspect the systems?	Cleaned/Inspected	
9. Was a Certificate of Performance placed on the hood?	Yes	
10. If a wash system, is the main valve in the open position?	N/A	
11. Are all filters in place?	Yes	
12. Do the fans operate?	Yes	
13. Have the duct dampers been cleaned/inspected?	N/A	
14. Were the exhaust fans cleaned?	No	Inspected.
15. Were the hood grease cups cleaned?	Yes	
16. Does the system appear to be liquid tight?	Yes	
17. Have exhaust fan belts been inspected/are they working?	Yes	Customer maintains the operation of the fans.
18. Have horizontal ducts been cleaned or inspected?	Yes	
19. Have vertical ducts been cleaned or inspected?	Yes	
20. Are sufficient access panels provided?	Yes	
21. Is there proper signage on access panels?	Yes	
22. Are all areas of the systems accessible?	Yes	
23. Are hoods and exhaust systems free of obstructions?	Yes	Hood lights did not have waterproof screens on them. We were unable to spray the system with water. Washed the hoods by hand.
24. Cleaning complies with NFPA '96?	Yes	
25. Type of Cooking systems solid fuel, charbroil or Wok?	Char grill	Char Grill, Oven.
26. Are the frequencies adequate?	Yes	
27. Are the precipitators/pollution control clean?	N/A	
28. What condition is the rooftop surface in?	Good	
29. Are there deficiencies in these systems?	No	
30. Are grease containment systems sufficient?	Yes	
31. Are there Type II duct systems?	No	

List deficiencies or comments related:

All systems were cleaned/inspected and a C.O.P was placed on the appropriate hoods.