

584 Congress (Front)

The current design is not original. Present materials are deteriorated painted stucco surface with a small window. I would like to return it to look like a storefront, even though the tenant uses the space as a workroom that is not open to the public. The original design of the storefront had two entrances, one to access the upper floors and one to access the ground floor shop. This is not practical for its current use as the internal stairs have been moved to the back of the building. Proposed restoration is intended to bring storefront in line with similar buildings of the same period.

Existing



Proposed

- No recessed door front
- Materials will be combination of painted black metal and wood

