



WALL TYPES

- NOTES:
1. ALL HOLES, GAPS AND PENETRATIONS IN CEILINGS AND WALLS SHALL BE SEALED WITH 3M FIRE BARRIER SEALANT 1504 (MIN. 2 HOUR RATED) INCLUDING FLEX FRING CHASSES.
 2. ALL EXISTING WOOD METAL LATHE AND PLASTER SURFACES ON FIRE RATED WALLS AND CEILINGS SHALL BE PATCHED, OPENINGS & HOLES FILLED AND ALL PENETRATIONS SHALL BE SEALED WITH FIRE RATED SEALANT (SEE NOTE 1) TYP.
 3. CONTRACTOR SHALL CONFIRM EXISTING CEILING STRUCTURE IS CAPABLE OF SUSTAINING ADDITIONAL WEIGHT OF CEILING MATERIALS AS DESCRIBED. CONSULTATION WITH PROFESSIONAL STRUCTURAL ENGINEER (NOT IN NY CONTRACT) MAY BE NECESSARY TO VERIFY STRUCTURAL STABILITY.

REV.	DATE	STATUS
2-04-16	PERMIT SUBMISSION	
2-12-16	PERMIT RESUBMISSION	



PROPOSED SICHUAN KITCHEN - RESTAURANT
 612 CONGRESS STREET
 PORTLAND, MAINE
 WALL TYPES

1. See Drawing A1 for General Notes, especially note 22 regarding existing interior wall and ceiling surface patching and sealing requirements.

NOTES