



PROPOSED UPDATES

-  1/2" DRYWALL ON ALL EXTERIOR WALLS
-  EXPOSED BRICK AROUND FIREPLACE
- 1/4" DRYWALL ON CEILINGS