## **CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT**

**389 Congress Street** Portland, Maine 04101

## **Inspection Violations**

Owner/Manager		Inspector	Inspection Date	
STATEWAY APTS INC		Peter Merrow	08/30/2005	
Locatation	CBL	Status	Inspection Type	
59 STATE ST	044 B047001	Re-Inspect 30 Days	Housing-Inspection	

	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1)	6-108.2 Violation: Notes:	Interior Interior floors, walls, ceilings and doors Bathroom ceiling was wet from 4th floor ba	3 athroom leak	33	Bathroom	
2)	6-113.5 Violation: Notes:	Interior  Maintenance of lighting fixtures  Loose reciprocal in bed room	3	33	Bedroom	
3)	6-113.5 Violation: Notes:	Interior  Maintenance of lighting fixtures  wires hanging in front entrance to building	1		Entry Way	
4)	6-111.4 Violation: Notes:	Interior  Maintenance of plumbing fixtures.  Water leaking from above unit	3	33	Bathroom	
5)	6-108.3 Violation: Notes:	Exterior Exterior windows, doors and skylights Windows stuck in the open position	3	33	Various locati	ons
6)	6-116.5 Violation: Notes:	Interior Fire Protection Service upgrade not completed	basement		Basement	
7)	6-111.3 Violation: Notes:	Interior Water supply. Imprproper sizing of washing machine drain	Basemen		Basement	
8)	6-108.2 Violation: Notes:	Interior Interior floors, walls, ceilings and doors Floor is soft around toilet  Water damage to ceiling in bathroom above	3	33	Bathroom	

Comments:

Water damage to ceiling in bathroom above toilet, flooring around toilet was spongy. Loose recipritcal in bedroom. Laundry waist dumps sized to small and can't handle waist water. Service upgrade not yet finished.