

97 Danforth St
Portland, Me.

Judy,

I do not believe that the chimneys could be repointed. There is too much deterioration of the mortar joints. My intent is to rebuild the chimneys with the existing brick if possible. We would clean the mortar from the brick and reuse. It may not be possible to salvage enough for both. In that case we would use salvaged brick for one and new brick of the same type to match the old as close as possible. The chimneys would be rebuilt to the same dimensions and design. We would use the appropriate mortar to meet the preservation requirements. We are really only dealing with the two components of brick and mortar.

Thanks,

Ed

3/2013
T.F. Low, Inc., Masonry

Document 1
Narrative