Form # P 04

DISPLAY THIS CARD ON PRINCIPAL FRONTAGE OF WORK

CITY OF PORTLAND

Please Read Application And Notes, If Any, Attached

AT 52 GRAY ST

PERMI

lion a

PERMIT ISSUED

Hermit Number: 080364
2008

epting this permit shall comply with all

ctures, and of the application on file in

ances of the City of Portland regulating

CITY OF PORTLAND

This is to certify that HATHAWAY BARBARA IN THOMAS W THOMSEN J. Bob

rm or

ine and of the

of buildings and

has permission to _____Additon of Shed Dormer - 7' (o-

-044 H006001

provided that the person or persons, of the provisions of the Statutes of I the construction, maintenance and I

this department.

Apply to Public Works for street line

and grade if nature of work requires

n and wen permit on procuble re this ding or the osed-in.

H JR NOTICE IS REQUIRED.

A certificate of occupancy must be procured by owner before this building or part thereof is occupied.

OTHER REQUIRED APPROVALS

Fire Dept. _____

Health Dept. ______Appeal Board _____

Other _____ Department Name

such information.

Director - Building & Inspection Services

PENALTY FOR REMOVING THIS CARD

City of Portland, Maine	•			Issue Date:	CBL:	
389 Congress Street, 04101	Tel: (207) 874-8703	3, Fax: (207) 874-87	16 08-0364		044 H0	06001
Location of Construction:	Owner Name:		Owner Address:		Phone:	
52 GRAY ST /5 417 60%	HATHAWAY	BARBARA E & TH	163 DANFORTH	I ST		
Business Name:	Contractor Name	::	Contractor Address:		Phone	
	Bobs Coastal	Contracting LLC / Ro	PO Box 2323 So	uth Portland	20740069	24
Lessee/Buyer's Name	Phone:		Permit Type: 1/2	u ton	•	Zone:
			Additions - Dup	lex		RY
Past Use:	Proposed Use:		Permit Fee:	Cost of Work:	CEO District:	7
2 Family Home	2 Family Horr	e - Additon of Shed	\$170.00	\$14,950.00) 2	
•	Dormer 17	116	FIRE DEPT:	Approved INS	PECTION:	
	1 ''	16.	ļ	Denied	Group: R-3	Type.
		V	-			
			1	ł	IRC-20	03
Proposed Project Description:	· · · · · · · · · · · · · · · · · · ·		7	j	0.0	, /
Additon of Shed Dormer (7 long	4 -	Signature:	Sign	nature: XMB	6/201
	471	IdFL Buth	PEDESTRIAN ACT	IVITIES DISTRIC	T (P.A.D.)	11
Addition of Shed Dormer on +	#17 cido	enadal +	Action: Appro	ved Approved	d w/Conditions	Denied
()0110000	1/3/00	errought the				
			Signature:		Date:	
Permit Taken By:	Date Applied For:	30	Zoning	g Approval		
ldobson	04/17/2008 S./·					
1. This permit application d	loes not preclude the	Special Zone or Rev	iews Zoni	ng Appeal	Historic Pres	ervation
Applicant(s) from meetin	g applicable State and	Shoreland A	LZ/ Variand	e	Not in Distric	t or Landr
Federal Rules.		US-7 14	11 11 11		ļ	
2. Building permits do not i	nclude plumbing,	Shoreland 14 1 Wetland 80% A	Miscell	aneous	Does Not Red	quire Revie
septic or electrical work.	1 3	only using 1	3,456		į.	
3. Building permits are void	d if work is not started	Flood Zone		onal Use	Requires Rev	iew
within six (6) months of t						
False information may in	_	Subdivision	[Interpre	tation	Approved	10 B
permit and stop all work.	•				as out	T.1 - (0)
		Site Plan	Approv	ed	Apploved w/	Contrilions
		}				1,
	1	Maj Minor Minor Mi	M Denied		Denied	1
PERMIT IS	SSUED	lake The	this		1 -1.7	1-0
		Date: Klun M. Ca	Date:		Date: 3/19	100
JUN 2 0	2002	9 5/12	108		(1
JUN 2 U	2003	/ //	100			•
CITY OF POI	CAN ITS					
	The state of the s					
		CERTIFICAT				
I hereby certify that I am the o						
I have been authorized by the quirisdiction. In addition, if a p						
shall have the authority to ente						
such permit.		r		F 12-31	(s) #P	
CICNATURE OF ARREST						
SIGNATURE OF APPLICANT			an a	D + m2		N I I'm
SIGNATURE OF ALTERANT		ADDRE	SS	DATE	РНО	NE
SIGNATURE OF ALL ECANT		ADDRE	SS	DATE	РНО	NE

Permit No: Date Applied For: CBL: City of Portland, Maine - Building or Use Permit 04/17/2008 08-0364 044 H006001 389 Congress Street, 04101 Tel: (207) 874-8703, Fax: (207) 874-8716 Location of Construction: Owner Name: Owner Address: Phone: 52 GRAY ST HATHAWAY BARBARA E & TH **163 DANFORTH ST** Business Name: Contractor Name: Contractor Address: Phone Bobs Coastal Contracting LLC / Rob PO Box 2323 South Portland (207) 400-6924 Lessee/Buyer's Name Permit Type: Phone: Alterations - Duplex **Proposed Project Description:** Proposed Use: 2 Family Home - Additon of Shed Dormer Additon of Shed Dormer -17' long 05/13/2008 Dept: Historic Status: Approved with Conditions Reviewer: Deborah Andrews Approval Date: Ok to Issue: Note: 1) Approved as per Historic Preservation Board decision 05/12/2008 Reviewer: Marge Schmuckal **Approval Date:** Dept: Zoning **Status:** Approved with Conditions Ok to Issue: Note: 1) The 17' dormer expansion is allowed under 14-436 which for this property only allows an 80% expansion once during the lifetime of the building. This expansion is using only 8.45% (85 sq ft). Future expansions will be limited based on this current permit. 2) This is NOT an approval for an additional dwelling unit. You SHALL NOT add any additional kitchen equipment including, but not limited to items such as stoves, microwaves, refrigerators, or kitchen sinks, etc. Without special approvals. 3) This property shall remain a two (2) family dwelling. Any change of use shall require a separate permit application for review and approval. 4) This permit is being approved on the basis of plans submitted. Any deviations shall require a separate approval before starting that work. 06/20/2008 Dept: Building **Status:** Approved with Conditions Reviewer: Jeanine Bourke **Approval Date:** Ok to Issue: Note: 1) This approves the waiver request for a reduction in headroom based on the existing conditions of the finished attic space and restrictions by historic preservation on the dormer height to not exceed the existing ridge. 2) All penetrations between dwelling units and dwelling units and common areas shall be protected with approved firestop materials, and recessed lighting/vent fixtures shall not reduce the (1 hour) required rating. 3) There must be a 2" clearance maintained between the chimney and any combustible material, with draft stopping per code at each 4) Permit approved based on the plans submitted and reviewed w/owner/contractor, with additional information as agreed on and as noted on plans.

Comments:

4/17/2008-Idobson: Need floor plan change, need window detail (egress) etc

5) Separate permits are required for any electrical, plumbing, or HVAC systems. Separate plans may need to be submitted for approval as a part of this process.

5/1/2008-lmd: Received floor plan and window detail,

5/5/2008-ldobson: Moved on to Zoning 5/5/2008 New date of app 05/01/2008

Location of Construction:	Owner Name:		Owner Address:	Phone:
52 GRAY ST	HATHAWAY BARB	ARA E & TH	163 DANFORTH ST	1
Business Name:	Contractor Name:		Contractor Address:	Phone
	Bobs Coastal Contract	ting LLC / Rob	PO Box 2323 South Portland	(207) 400-6924
Lessee/Buyer's Name	Phone:		Permit Type:	
			Alterations - Duplex	

5/12/2008-mes: using section 14-436 allowing no more than 80% expansion - this 17' dormer is only using 8.45% (for 85 sq ft)

5/16/2008-jmb: Spoke to Bob G. This is an attic space and historic will not allow to bump up the roof to meet headroom code. Other required details, headroom not adequate, need existing stair details, structural beam, fasteners, lumber dimensions, load of existing attic floor. Bob says they are sistering the floor joists to create a 100 psf load...need details. Doesn't look hopeful for approval per code.

5/20/2008-jmb: Barbara Ward called to discuss the permit. The work has already started, the dormer walls are installed. The contractor thought the permit was issued. I will place a stop work order on the property and inspect. Barbara claims the attic had been used for living space for many years, I explained that it probably did not have approvals to do so.

5/27/2008-jmb: I met with Deb Andrews to discuss historic approval process and this job. See printed email of her comments. See Bob G. Email and my response.

5/29/2008-jmb: Bob G. Came in with more narrative and photos, I asked that detailed drawings be submitted for review of items discussed previously. He also had historic approval drawings for the granite side entry, but I advised this will require a separate permit to review.

5/30/2008-jmb: Bob G dropped off another written description of details and said drawings would be submitted on Monday.

6/20/2008-jmb: Bob G. Came in with drawings and details, ok to issue

BUILDING PERMIT INSPECTION PROCEDURES

Please call 874-8703 or 874-8693 (ONLY)

to schedule your inspections as agreed upon

Permits expire in 6 months, if the project is not started or ceases for 6 months.

The Owner or their designee is required to notify the inspections office for the following inspections and provide adequate notice. Notice must be called in 48-72 hours in advance in order to schedule an inspection:

By initializing at each inspection time, you are agreeing that you understand the inspection procedure and additional fees from a "Stop Work Order" and "Stop Work Order Release" will be incurred if the procedure is not followed as stated below.

A Pre-construction Meeting will take place upon receipt of your building permit.

X Framing/Rough Plumbing/Electrical: Prior to Any Insulating or drywalling

X Final inspection required at completion of work.

Certificate of Occupancy is not required for certain projects. Your inspector can advise you if your project requires a Certificate of Occupancy. All projects <u>DO</u> require a final inspection.

If any of the inspections do not occur, the project cannot go on to the next phase, REGARDLESS OF THE NOTICE OR CIRCUMSTANCES.

CERIFICATE OF OCCUPANICES MUST BE ISSUED AND PAID FOR, BEFORE THE SPACE MAY BE OCCUPIED.

Signature of Applicant/Designee

Signature of Inspections Official

_6/

CBL: 044 H006001

Building Permit #: 08-0364

General Building Permit Application

If you or the property owner owes real estate or personal property taxes or user charges on any property within the City, payment arrangements must be made before permits of any kind are accepted.

Total Square Footage of Proposed Structur	re/Area Square Footage of Lot	
Tax Assessor's Chart, Block & Lot	Applicant *must be owner, Lessee or Bu	yer* Telephone:
Chart# Block# Lot#	Name BAXBARA WARD	-00
44-14-6	Address 163 DANFORTH S'	T 879-8754
	City, State & Zip Portifo	14950
Lessee/DBA (If Applicable)	Owner (if different from Applicant)	Cost Of
. / <u>/</u>	Name A	Work: \$ 202400
79/1	Address ///	C of O Fee: \$
	City, State & Zip	Total Fee: \$
Current legal use (i.e. single family)	TWO FAMILY	
Current legal use (i.e. single family) If vacant, what was the previous use?	\mathcal{L}/A	
Proposed Specific use:		
	If yes, please name	~1/
Froject description. ADDID IN E	OF SHEP DORMER	11' long
a ,		
Contractor's name: 20327	FRAHM - BOBS COASTA	COMMANNEZ
Address: PO BOX 2323		
City, State & Zip S. PURTLAN	0 ME 0444-2323	Telephone: 400-6924
7	ready: ME	-
	·	


do so will result in the automatic denial of your permit.

In order to be sure the City fully understands the full scope of the project, the Planning and Development Department may request additional information prior to the issuance of a permit. For further information or to download copies of this form and other applications visit the Inspections Division on-line at www.portlandmaine.gov, or stop by the Inspections Division office, room 315 City Hall or call 874-8703.

I hereby certify that I am the Owner of record of the named property, or that the owner of record authorizes the proposed work and that I have been authorized by the owner to make this application as his/her authorized agent. I agree to conform to all applicable laws of this jurisdiction. In addition, if a permit for work described in this application is issued, I certify that the Code Official's authorized representative shall have the authority to enter all areas covered by this permit at any reasonable hour to enforce the provisions of the codes applicable to this permit.

Signature:		Date:	4-17-0	8	,

This is not a permit; you may not commence ANY work until the permit is issue





This page contains a detailed description of the Parcel ID you selected. Press the **New Search** button at the bottom of the screen to submit a new query.

Current Owner Information

Card Number 1 of

 Parcel ID
 044 H006001

 Location
 52 GRAY ST

 Land Use
 TWO FAMILY

Owner Address HATHAWAY BARBARA E & THOMAS W THOMSEN JTS 163 DANFORTH ST

PORTLAND ME 04102

Book/Page 20858/018 Legal 44-H-6

44-H-6 GRAY ST 52-54 WINTER ST 15-19 3444 SF

Current Assessed Valuation

 Land
 Building
 Total

 \$143,200
 \$191,100
 \$334,300

Property Information

Year BuiltStyleStory HeightSq. Ft.Total Acres1875Colonial222370.079

BedroomsFull BathsHalf BathsTotal RoomsAtticBasement26Full FinshFull

Outbuildings

Type Quantity Year Built Size Grade Condition

Sales Information

Date Type Price Book/Page 02/11/2004 LAND + BLDING \$316,000 20858-18 09/01/2002 LAND + BLDING \$287,500 18159-251 09/25/2000 LAND + BLDING \$170,000 15746-063

Picture and Sketch


Picture Sketch Tax Map

Click here to view Tax Roll Information.

Any information concerning tax payments should be directed to the Treasury office at 874-8490 or emailed.

New Search!





City of Portland Inspection Services RETURN OF SERVICE

On the 20th day of May, 2008 I made service of the stop work order no building permit

upo	n, Ron & Barbara Ward, at 52 Gray ST (15-17 Winter
X B	y delivering a copy in hand.
	y leaving copies at the individual's dwelling house or usual place of abode with a person of nitable age or discretion who resides therein and whose name is
	y delivering a copy to an agent authorized to receive service of process, and whose ame is
B	y (describe other manner of service)
_	
	Signature of Person Making Service
DATED:	5/21/08 Jeanne Bornke
	received the above referenced documents
Person	Receiving Service
X	T. d. d.
	Refused to sign
	Unable to sign



Strengthening a Remarkable City, Building a Community for Life • www.portlandmaine.gov

Lee Urban- Director of Planning and Development Jeanie Bourke - Inspections Division Director

May 21, 2008

HATHAWAY BARBARA E & 163 DANFORTH ST PORTLAND, ME 04102

CBL: 044 H006001 Located at 52 GRAY ST

Hand Delivery

Dear DEAR MRS. WARD,

STOP WORK ORDER

An evaluation of the above-referenced property on 05/21/2008 revealed that building construction was being conducted without benefit of a valid building permit as required by Section 105.1 of the 2003 International Building Code and the 2003 International Residential Code of the City of Portland.

Appropriate permitting has not been issued for the property listed above, therefore all construction activity at that property must STOP immediately. This is a STOP WORK ORDER pursuant to Section 114. of 2003 International Building Code and the 2003 International Residential Code of the City of Portland.

You may resume construction activity only after issuance of the appropriate building permit and the subsequent lifting of this order. Building Permit Applications are available in this office, Room 315 at Portland City Hall, from 8:00 a.m. to 4:00 p.m. weekdays except holidays.

Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code and in Title 30-A of M.R.S.A. Section 4452. This constitutes an appealable decision pursuant to Section 112 of the City of Portland Building Code.

If you wish to discuss this matter, or you have any questions, please feel free to contact me.

Sincerely,

Jeanie Bourke @ (207) 874-8715


Inspections Division Director


6-3 6-74 MIS IS a Rated wall <36 between buildings アーのメ 424 0.4 Not allowed 9-4-HH 232 15 & 17 winson WINDOW SCHEDULE 241×34 CXWX35 AR 3


dectric atter MAY 21 2008

cable outlet MAY 21 2008









MAY 29 2008

Jeanie Bourke - FW: PERMIT FOR 15/17 WINTER ST

From: Bob Graham <graham963@hotmail.com>

To: <jmb@portlandmaine.gov> **Date:** 5/27/2008 8:42:12 AM

Subject: FW: PERMIT FOR 15/17 WINTER ST

Jeanie--Hope u had a fun w/e--I am "forwarding" this because when I started--i couldnt finish composing in my drafts---(village idiot here)--so this was done after we met--it isnt complets--as I will finish today--tues--I was hugely sick from sat till last nite--so thanks for ur patience--Bob Graham

From: graham963@hotmail.com To: parker_1@hotmail.com

Subject: PERMIT FOR 15/17 WINTER ST Date: Thu, 22 May 2008 18:04:54 +0000

JEANIE--FIRST AND FOREMOST I WANTED TO LET YOU KNOW HOW MUCH I APPRECIATED YOUR TIME YESTERDAY HELPING TO BRING THIS PERMIT TO A REALITY. AS YOU MAY OR MAY NOT KNOW I HAVE BEEN DOING BUSINESS AS BOBS COASTAL CONTRACTING SINCE 1989. I AM A REGISTERED LLC W/THE STATE OF MAINE NH AND VT. I RELOCATED "BACK" TO MAINE ABOUT A YEAR AGO AFTER BUING IN VT FOR SOME 2 YEARS. DURING THAT TIME I BUILT (BY MYSELF) 2 LOG HOMES, 1 IN VT THE OTHER IN NY. I REALLY ENJOY MY WORK, AND EVEN THOUGH I AM APPROACHING 20 YEARS AS A BUILDER, I LOOK FORWARD TO EVERY DAY. WHAT REALLY MAKES MY DAY IS A HAPPY CLIENT--ON A DAILY BASIS, AND RON AND BARBARA WARD ARE SO FAR VERY HAPPY, AND I LOOK FORWARD TO MANY SUCCESS STORIES IN THE FUTURE.

NOW FOR THE PERMIT REG'S WE SPOKE OF TODAY AND AT THE MEETING ON WEDS I WILL EXPLAIN IN DETAIL WHAT I HAVE DONE THUS FAR TO ENSURE A SAFE, STABLE AND UP TO CODE BUILDING AT 15 AND 17 WINTER ST.

SHED DORMER----UPON INSPECTION OF THE EXISTING FLOOR JOISTS, AND NOTING THAT THE FLOOR ITSELF SLOPED 1.5 " FROM THE EXT WALL TO THE CENTER OF THE ROOM--MUCH THE SAME ON THE OTHER SIDE. HENCE I MADE THE DECISION TO RESUPPORT THE FLOOR, AND GAVE BARBARA AB\ND RON A CHANGE ORDER TO DO SO. I BELIEVE THEY WERE GONE, SO I WENT AHEAD AND COMMENCED THE WORK TAKING PICS AS I WENT. I HAD 2 SUBS DOING THIS WITH ME, AND AFTER "FLOATING" THE FLOOR WITH A LASER LEVEL IN THE MIDDLE OF THE FLOOR I MARKED FROM EAST TO WEST THE TOTAL SLOPE TO THE CENTER OF THE ROOM. I DID THE SAME FROM WEST TO EAST. IT WAS DETERMINED THAT I NEEDED TO "REBLOCK" THE FLOOR AND SET F.G. SO TO SPEAK AT ZERO ON FAR EAST AND WEST AXIS. UPON LAYING A STRING FROM EAST TO WEST THE DEFLECTION AVERAGED 1.5 ". THERE IS SIGNIFICANT "BOTTOM PLATE" TIMBERS THAT ARE LOG TYPE, ROUNDED ON THE EXTERIOR AND SQUARED OFF ON OTHER EDGES. THE THICKNESS IS ABOUT 6-8". THE FLOOR CAVITY IS ABOUT 10 " AND AFTER SISTERING THE LOG BOTTOM PLATE AND THEN RUNNING PERPENDICULAR TO THAT W/OTHER DIM LUMBER I FOULD THAT THE FLOOR WAS FINALLY LEVEL FOR THE FIRST TIME IN PROBABLY 60 YEARS. I HAVE PICS FOR ALL OF THIS, AND THE INSULATION IF CELLULOSE, AND IS STATED TO HAVE AN R-FACTOR OF ABOUT 22. THE SUBFLOOR IS 3/5 " ADVANTECH T@G AT RIGHT ANGLE TO THE JOISTS, AND SECURED W/PL400 ADHESIVE NAILED W/PNEUMATIC NAILER USING RING SHANK NAILS 2.75" LONG WITH A NAILING PATTERN OF 6 " OR BETTER. THE THREE OF US JUMPED ON THE MIDDLE OF THE FLOOR--AND IT DIDNT DEFLECT A MILLIMETER

RIDGE----AFTER TEARING OUT THE FOOR I FOUND THAT THERE WAS VERY LITTLE RIDGE IS ANY, AND THE ROOF RAFTERS WERE ATTACHED TO THAT. I REMOVED ALL OF THAT--ATTACHED A NEW RIDGE BEAM OF 2X8 AND SCREWED IT TO THE ENDS OF THE RAFTERS AT THE RIDGE. I THEN CALCULATED THE RAFTER LENGTH W/OUT A TAIL AS I DIDNT WANT ANY WOOD CUT FROM THE RAFTERS. OF COURSE SOME OF THE RAFTERS WERE A LITTLE LONGER/SHORTER THAN OTHERS BUT I COULDN'T CHANGE THAT. I ATTACHED USING SIMPSON STRONG TIES AS WIND BLOWOFF PROTECTION, AND FASTENED W/SCREWS TO THE TOP PLATES AND HEADERS. THE SIDE WALL ON THE NORTH WALL WAS ALREADY THERE, AS WAS THE OPENING, IF NOT W/IN 6" OF WHERE IT IS NOW. THE WALL PLATE SITS SQUARE ON TOP OF ONE OF THE SISTERED FLOOR JOISTS.

Keep your kids safer online with Windows Live Family Safety. Help protect your kids.

Make every e-mail and IM count. Join the i'm Initiative from Microsoft.

BOB'S COASTAL CONTRACTING, LLC.

Established 1989

JENNE: 5/29

Needsmendmen ENCLOSED PLEKE PIND PHE ONIGINAL "APPROVED DRYWING BY THE HP'S MTG ON 3/19. AS WE SPOKES OF, I MAS MT MED A RAIGHT BUT WILL PROVIDE IP REQUED, ALSO D'VE ENCIOSED THE FRAMING OF THE 3MP PROOR. WHATS GOOD ABOUT THE EXISTING PRAMING IS THAT IT 15 OF 166 THE RUNNING EAST-WEST (8-9 " DIA) PUNNING North - SOUTH ANE 4X5'S APPROX 24" OC, SOME MONE Some LOSS THAN. THE PUSOR SLOPED EAST TO WEST ABSOT 1,25°50 I SISTERON THE "LOF BEAMS" AND RAW AGN PLOW

JUSTS PERPENDULARTO THAT. I TIED THAT AU NOSETHER W/ CONST. ADH. of 3/4 "T & 6 ADVANTELH, JOIST HAMBERS WERE & pre NOT. - I'M GETTING SKY LITES SIZED & THE NORTH GYBLE GOOWAL

51200 Por E 612095

Surement Boll EMM

MAY 25 200

From:

Deb Andrews

To:

Barbara Hathaway 5/27/2008 3:52:41 PM

Date: Subject:

Re: 15-17 Winter AHHHHHHHHH

Barbara:

Jeanie Bourke and I have met to discuss the identified life safety requirements as they affect your recent Historic Preservation Board approval. This is what we have determined would satisfy both approval processes:

- 1. Skylights. You are free to return to your previous approval to install skylights in lieu of the windows.
- 2. <u>Egress for 3rd floor bedroom, south end</u>: The existing skylight on the Winter St.-facing roof plane can be replaced with an egress skylight, provided the size of the skylight is not increased. Jeanie thought that the existing size might meet the requirement, but this will have to be confirmed.
- 3. <u>Egress for 3rd floor bedroom, north end</u>: The existing gable window facing Gray Street may be replaced with a casement window that matches the divided-light appearance of the rest of the windows on the building. Your contractor will need to provide a catalogue cut or measured drawing of the proposed window. He should also provide a measured drawing of the existing window, for comparison purposes.

All of these revisions could be reviewed and approved by staff.

Hope this is helpful.

Deb Andrews

>>> Barbara Hathaway <<u>parker_1@hotmail.com</u>> 5/22/2008 9:04:16 AM >>> Good Morning Deb,

I hope all is well.

Update: According to Jeanie Bourke in Inspections we have some issues that link us back to your department. Despite Bob's best intention and conversations with Inspections prior to our submission to HP, a few points were missed. We cannot have operable windows on the east facade of the new dormer, and we cannot have an egress window in the bathroom. (Any window needs to be fire rated and inoperable, due to the proximity of the adjacent building.) We hope to have operable windows to provide ventilation...that brings back to skylights.

We are hopeful that because skylights had previously been approved that this can be handled by an administrative decision. We would like somewhat smaller skylights but are concerned that any significant change from the previous approval would result in a time delay. Inspections has also raised, and may insist, that we have an egress window put in the gable end bedroom...because it was used as a pre-existing bedroom, (not new construction), and is on a principal street facade in an Historic district, we are hoping that can be grandfathered. Our alternative would be to install a casement window that looks like and fits the same opening as the existing double hung. If we need to replace the existing window with an egress window would that require an HP Hearing?

This email is also a follow up to the letter we received from HP dated 4.4.08, signed by Scott Hanson, granting approval of our application. The address is correct but the scope of work is for another property.

Please let me know how we should proceed.

One day soon we'll get this right!

Jeanie Bourke - Re: FW: PERMIT FOR 15/17 WINTER ST

From: Jeanie Bourke **To:** Bob Graham

Date: 5/27/2008 5:00 PM

Subject: Re: FW: PERMIT FOR 15/17 WINTER ST

Thanks Bob....I will take a look at this, but the drawings will be most helpful. I'm not sure what your experience obtaining building permits is in other states/cities, but here in Portland, we require very detailed plans showing all phases of the work. In this instance some of the code issues may have been realized early in the process if a design professional had been involved.

Also, when a permit is approved and issued, you will be called to come in a pick it up. A building "B" Card is issued and we review with you when to call for the required inspections. Thanks

Jeanie Bourke Inspection Services Division Director

City of Portland
Planning & Development Dept./ Inspections Division
389 Congress St. Rm 315
Portland, ME 04101
jmb@portlandmaine.gov
(207)874-8715

>>> Bob Graham <graham963@hotmail.com> 05/27 8:41 AM >>>

Jeanie--Hope u had a fun w/e--I am "forwarding" this because when I started--i couldnt finish composing in my drafts---(village idiot here)--so this was done after we met--it isnt complets--as I will finish today--tues--I was hugely sick from sat till last nite--so thanks for ur patience--Bob Graham

From: graham963@hotmail.com
To: parker_1@hotmail.com

Subject: PERMIT FOR 15/17 WINTER ST Date: Thu, 22 May 2008 18:04:54 +0000

JEANIE--FIRST AND FOREMOST I WANTED TO LET YOU KNOW HOW MUCH I APPRECIATED YOUR TIME YESTERDAY HELPING TO BRING THIS PERMIT TO A REALITY. AS YOU MAY OR MAY NOT KNOW I HAVE BEEN DOING BUSINESS AS

BOBS COASTAL CONTRACTING SINCE 1989. I AM A REGISTERED LLC W/THE STATE OF MAINE NH AND VT. I RELOCATED "BACK" TO MAINE ABOUT A YEAR AGO AFTER BUING IN VT FOR SOME 2 YEARS. DURING THAT TIME I BUILT (BY MYSELF) 2 LOG HOMES, 1 IN VT THE OTHER IN NY. I REALLY ENJOY MY WORK, AND EVEN THOUGH I AM APPROACHING 20 YEARS AS A BUILDER, I LOOK FORWARD TO EVERY DAY. WHAT REALLY MAKES MY DAY IS A HAPPY CLIENT-ON A DAILY BASIS, AND RON AND BARBARA WARD ARE SO FAR VERY HAPPY, AND I LOOK FORWARD TO MANY SUCCESS STORIES IN THE FUTURE.

NOW FOR THE PERMIT REG'S WE SPOKE OF TODAY AND AT THE MEETING ON WEDS I WILL EXPLAIN IN DETAIL WHAT I HAVE DONE THUS FAR TO ENSURE A SAFE, STABLE AND UP TO CODE BUILDING AT 15 AND 17 WINTER ST.

SHED DORMER----UPON INSPECTION OF THE EXISTING FLOOR JOISTS, AND NOTING THAT THE FLOOR ITSELF SLOPED 1.5 " FROM THE EXT WALL TO THE CENTER OF THE ROOM--MUCH THE SAME ON THE OTHER SIDE. HENCE I MADE THE DECISION TO RESUPPORT THE FLOOR, AND GAVE BARBARA AB\ND RON A CHANGE ORDER TO DO SO. I BELIEVE THEY WERE GONE, SO I WENT AHEAD AND COMMENCED THE WORK TAKING PICS AS I WENT. I HAD 2 SUBS DOING THIS WITH ME, AND AFTER "FLOATING" THE FLOOR WITH A LASER LEVEL IN THE MIDDLE OF THE FLOOR I MARKED FROM EAST TO WEST THE TOTAL SLOPE TO THE CENTER OF THE ROOM. I DID THE SAME FROM WEST TO EAST. IT WAS DETERMINED THAT I NEEDED TO "REBLOCK" THE FLOOR AND SET F.G. SO TO SPEAK AT ZERO ON FAR EAST AND WEST AXIS. UPON LAYING A STRING FROM EAST TO WEST THE DEFLECTION AVERAGED 1.5 ". THERE IS SIGNIFICANT "BOTTOM PLATE" TIMBERS THAT ARE LOG TYPE, ROUNDED ON THE EXTERIOR AND SQUARED OFF ON OTHER EDGES. THE THICKNESS IS ABOUT 6-8". THE FLOOR CAVITY IS ABOUT 10 " AND AFTER SISTERING THE LOG BOTTOM PLATE AND THEN RUNNING PERPENDICULAR TO THAT W/OTHER DIM LUMBER I FOULD THAT THE FLOOR WAS FINALLY LEVEL FOR THE FIRST TIME IN PROBABLY 60 YEARS. I HAVE PICS FOR ALL OF THIS, AND THE INSULATION IF CELLULOSE, AND IS STATED TO HAVE AN R-FACTOR OF ABOUT 22. THE SUBFLOOR IS 3/5 " ADVANTECH T@G AT RIGHT ANGLE TO THE JOISTS, AND SECURED W/PL400 ADHESIVE NAILED W/PNEUMATIC NAILER USING RING SHANK NAILS 2.75" LONG WITH A NAILING PATTERN OF 6 " OR BETTER. THE THREE OF US JUMPED ON THE MIDDLE OF THE FLOOR--AND IT DIDNT DEFLECT A MILLIMETER

RIDGE----AFTER TEARING OUT THE FOOR I FOUND THAT THERE WAS VERY LITTLE RIDGE IS ANY, AND THE ROOF RAFTERS WERE ATTACHED TO THAT. I REMOVED ALL OF THAT--ATTACHED A NEW RIDGE BEAM OF 2X8 AND SCREWED IT TO THE ENDS OF THE RAFTERS AT THE RIDGE. I THEN CALCULATED THE RAFTER LENGTH W/OUT A TAIL AS I DIDNT WANT ANY WOOD CUT FROM THE RAFTERS. OF COURSE SOME OF THE RAFTERS WERE A LITTLE LONGER/SHORTER THAN OTHERS BUT I COULDN'T CHANGE THAT. I ATTACHED USING SIMPSON STRONG TIES AS WIND BLOWOFF PROTECTION, AND

FASTENED W/SCREWS TO THE TOP PLATES AND HEADERS. THE SIDE WALL ON THE NORTH WALL WAS ALREADY THERE, AS WAS THE OPENING, IF NOT W/IN 6" OF WHERE IT IS NOW. THE WALL PLATE SITS SQUARE ON TOP OF ONE OF THE SISTERED FLOOR JOISTS.

Keep your kids safer online with Windows Live Family Safety. <u>Help protect your kids.</u>

Make every e-mail and IM count. Join the i'm Initiative from Microsoft.

BOB'S COASTAL CONTRACTING L.L.C.

D: JEANE BORGUE

MAY 3 0 2008

CHERLIST POR 15 & 17 WINTER ST.

(DINSULTION FOR PURMON LICILING PLANCED IS R-19

@ pasiATION For Donmer who is R-19.

(3) ALL PLOOR JACTIONS WHETHER 2x6 OR 2X8 HAVE JUST HAVEERS

(4) EXISTING GABLE AD (N) WINDOW IS A DOUBLE HAT AD IS 85F. 18 UP

(3) EXISTRAL (U) SKYLPE B 6 SF AND 15 51" UP, I WILL MAKE A
PERMANENT BENCH OF 18" TO THE SENT SO THAT HIT WILL BE G1-18 OR 33"

O RIDGE PASTENCES ARE HURKICHE RAMED WIND STRAP W/6-8 POINTS OF ATTACHMENT. MSO USED EXT. WAR of THE HOLD THE RAFTED TO THE HEADON.

(1) THE WAN SAPARATION ON THE 2ND PROVIN FOR 15\$ A 15 AS FOCKONS,

PERE RESISTANT 5/8" GYPSIM - "TOUGHRUGE" - FIRE PATED FOR I HAR
PER SIPE.

(8) SMOKE PATEGORS. BE GASKE BORM, (1) CMAN SLEEPING AFEA (5) QUE
HAWAYE GASKE END BORM DOOK.

DIMMENER of 8' O.C., OVERLAPPING THE END N'TS LOGS BY MURSE of TOWN, I SISTEMAN BOTH SIDES OF THISE of MY LOWGEST PLOW TUST 15 7-4" of MOT OF THISE ME" SISTEMAN FORT OF THE PLOW SISTEMAN SOUTH PORTLAND TO THE PLOW THE AND THE PLOW THE MOST OF THISE ME" SISTEMAN TO STEPS.

YET TO PROVIDE OF EXT. SHEATHING OF CAPALOT CUTS POR WINDOWS

(3) AFRAN VIEW FOR #16 BONY

Jeanie Bourke - 15-17 Winter Street

From: "The Danforth Inn" <danforth@maine.rr.com>

To: <JMB@portlandmaine.gov>

Date: 6/16/2008 6:21 AM **Subject:** 15-17 Winter Street

CC: "Barbara Hathaway" <parker_1@hotmail.com>

Good Morning Jean,

Attached please find the request for a waiver regarding the ceiling height on the dormer. Please let me know if there is anything else you need in order to process the permit. If you could offer a time frame when the permit would issue it would be helpful.

Thank you for working with us.

Barbara Ward

163 DANFORTH STREET PORTLAND, ME 04102

June 15, 2008

Inspections Department
City of Portland
Portland City Hall
489 Congress Street
Portland, ME 04101
ATTN: Jean Bourke, Director

RE: 15-17 Winter Street

Ladies and Gentlemen:

Please consider this my request for a waiver relating to the above-captioned premises. Specifically, we are requesting a waiver for the ceiling height for the bathroom being added to the third floor dormer to allow that ceiling height to remain at its currently-framed height which apparently falls short of the code requirements by 1-2 inches. The restraining condition prompting this situation is the terms of the approval by the Historic Preservation Committee limiting the height of the roof and the achievable slope for the dormer.

Any construction details should be directed to the contractor, Bob Graham.

Thank you for your consideration of this request.

Sincerely,

Barbara H. Ward

BHW:kjl

cc: Bob Graham

SHED DORMAN ITS STRUCTURAT DETAILS & WHAT I DID RESTHE PLOSE BEAM.

JUN 19 2003

Note: 5/8" typex of 5/8" Faire rated Sheathing will equal I'm assembly I will BE INSTAUND, AT A MINIMUM.

5/8 " I HOUR PLATED PLYWOOD ONTHE EXT.

LONG WHERE & SHOOT WAS. THE

INSIDE WILL BE 5/8" I HOUR RATING (GYPSUM)

DRYWAA. THE EXTENSE TRIN WILL BE

AS EXISTING CLAPS ON THE SIDE of

HORIZINGAL TO GE IX 6'S ON THE EAST

SIDE.

THE PRODUT FOR THE SHEATHING WILL BE

TO THE VOILLE SUPERE WITH DOINTS

OVER SUPES. Z'/4" #6 TYPES DRIWALL

SCRAWS FORTHE DRIWALL & GO COMMON

NAIS C 6" ED65.

THE # 15 ENGRY STEDS WILL BE CHANTE-S'
WIDE AS THE CASH MAIN S ON THE CEPT

E>3' From CESSER SO 6' WENT BE EQUI
DISTAGE.

JUN 19 2008

THE INSULATION CAN BE MADE TO
APPRIX R 23-R27 BY INSTAULING MOVE
THEN IS RECOMMENDED & AS YOU KNOW
THERE WONT BE ANY "RIDGE VENTING"
SO RAPTER MATES "ARE NOT AN ISSUE,
THE SOPERTS WILL BE SOUTD SINCE THEY
ARE ATTRIKED SOPRATELY ON THE STHEM
SIDE OF THE HEADON THE SHEATHING
HOWEVER HEAS INSTAUCO PROM
FASUA TO RIDGE SO THAT, IN APPETT,
THE SUPPLE ACTS AS ONE & IS TIED IN"
TO THE REST SPITHEROUF.

I will GETYWAN UPDATED PERMET FOR #15 & 1250 WILL SUPPLY WINDOW CATALOG CUTS THAT WAS DELIVED TO HP SOME TIME 160.

THANKS FOR YOUR PATIENCE WITH THIS PROJECT.

BOB ERAHAM MEMBOR, BOBS COASTAL CONTRAGING LCC

THE - THE SOP. BARRION IN THE WAUS WHUBE 5/8 "GYPSVM (I HOUR RATING) W/2 14# 6 TYPE 5 SUPENS.

21 June 2008

FROM: BOB GRAHAM

GOVIE - PER YOUR REQUEST.

(B) UPON CONSULT W/SHAWN WASON OF

QUALITY INSULATION ME STATES.

"YOU CAN EASILY BET R-38 IN A

7X6 CAUMY SPAED 16 O.C. I WOLL

USE K-WOOL REFERENCEN INSULATION

HED IN W/A NYLON NETTING.

DRAWINGS ATTACHED.

(1) ZAD PROSER BORM FIRE SEP.

DETAL (#17)

(2) DETAL OF REBUILD OF 200

FLOOR BATHIN UNIT 17.

8.75 SF COLLIALOG CUTS FOR GRAY ST 2-8"WX36 ABLE END EGRESS WINDOW.

9.959 'CHALOG CUTS FOR EXISTING 320 FLOOR
SLXVIGHT W/MEHANISMS. SIZED 30"WX.

S OPENS A FULL 25" OR 90°

SPRING COMMENT W/RREAST LANGE F

CLOSURE

Product Sizes

Velux w/Egress hardware

To assist you in your planning, these charts provide the data useful in specifying and installing your VELUX skylights. Each model is shown with the available size measurements and other necessary information.

Models VSE and VS


						-					
Size code:		101	104	106	108	156	304	306	308	601	606
Outside frame	in.	21½ x 27¾8	21½ x 38¾	21½ x 46¾	21½ x 54½/16	235/16 x 463/8	30°/16 x 38³/8	30 ⁹ / ₁₆ x 46 ¹ / ₄	30°/16 x 54 ¹⁵ /16	44³/ ₄ x 27³/ ₈	44³/ ₄ x 46¹/ ₄
Finished framing	in.	20³/8 x 26³/16	20% x 37%	20³/8 x 45¹/16	20 ³ / ₈ x 53 ³ / ₄	22 ¹ / ₂ x 45 ⁵ / ₁₆	29 ⁷ / ₁₆ x 37 ³ / ₁₆	29 ⁷ / ₁₆ x 45 ¹ / ₁₆	29 ⁷ / ₁₆ x 53 ³ / ₄	435/8 x 263/16	435/8 x 451/16
Rough opening*	in.	21½ x 27 ⁷ /8	21½ x 38¾,	21½ x 46¾	21½ x 55½,	22½ x 455/16	30 ⁹ / ₁₆ x 38 ⁷ / ₈	30 ⁹ /16 х 46 ³ /4	30°/16 x 55 ⁷ /16	44 ³ / ₄ x 27 ⁷ / ₈	44 ³ / ₄ x 46 ³ / ₄
Daylight area (glass) in.	$16^{3}/_{4} \times 20^{13}/_{16}$	16³/4 x 31³/8	16³/4 x 39³/4	16³/ ₄ x 48³/ ₈	$18^{1}/_{2} \times 39^{3}/_{4}$	25 ⁷ /8 x 31 ⁷ /8	25 ⁷ /8 x 39 ³ /4	25 ⁷ / ₈ x 48 ³ / ₈	40 x 20 ¹³ / ₁₆	40 x 39 ³ / ₄
Ventilation area	sq. ft.	1.37	3.63	4.16	4.77	4.27	4.27	4.80	5.41	2.18	5.82
Net wt (Lam. glass)	VSE/VS Ibs.	41/38	50/47	59/55	65/64	62/58	64/57	73/71	82/80	65/65	96/93

Model FS

Size code		056	101	104	106	108	112	150	156	302	304
Outside frame	in.	15½ x 46¼	21½ x 27¾8	21 ¹ / ₂ x 38 ³ / ₈	21½ x 46¼	21½ x 54½/16	21½ x 70¾	235/16 x 239/16	235/16 x 46 ³ /8	30 ⁹ / ₁₆ x 30 ¹ / ₂	30 ⁹ /16 x 38 ³ /8
Finished framing	in.	14³/8 x 45¹/16	20³/8 x 26³/16	20³/8 x 37³/16	20³/8 x 45¹/16	20³/8 x 53³/4	20³/ ₈ x 69³/ ₄	22½ x 22½	22½ x 455/16	29 ⁷ / ₁₆ x 29 ⁵ / ₁₆	29 ⁷ /16 x 37 ³ /16
Rough opening	in.	143/8 x 463/4	21¹/2 x 27³/8	21½ x 38¾	21 ¹ / ₂ x 46 ³ / ₄	21½ x 55½,16	21½ x71¼	22 ¹ / ₂ x 22 ¹ / ₂	22½ x 45 ⁵ /16	30 ⁹ /16 x31	30 ⁹ / ₁₆ x 38 ⁷ / ₈
Daylight area (glass)	in.	12 x 4215/16	$18^{3}/_{16} \times 24^{1}/_{16}$	18 ³ /16 x 35 ¹ /16	$18^{3}/_{16} \times 42^{15}/_{16}$	18³/16 x 515/8	$18^{3}/_{16} \times 67^{7}/_{16}$	$19^{15}/_{16} \times 20^{1}/_{8}$	19 ¹⁵ / ₁₆ x 42 ¹⁵ / ₁₆	27 ¹ /4 x 27 ³ / ₁₆	27 ¹ / ₄ x 35 ¹ / ₁₆
Net wt (w/ temp. glass)	lbs.	33	28	37	43	49	63	26	46	41	48

Model FS (continued)

Model GPL



Model VSE, VS and FS sizes that fit perfectly between roof trusses. (see page 20 for additional information)

 $\mbox{*}$ Rough opening for type EDL, EDM, EDW flashings.

Model GDL

Size code Outside frame 305/8 x 55 $44^3/_4 \times 46^3/_8$ Rough opening 311/4 x 551/2 451/4 x 467/8 Daylight area (glass) 233/4 x 451/4 37¹⁵/₁₆ x 36⁵/₈ Ventilation area (opening) sq. ft. 11.34 11.64 47.81 Ventilation area (flap) 30.00 123 Net wt (w/ Lam. glass) 111

Size code		P19
Outside frame	in.	37 ¹ / ₁₆ x 99 ¹ / ₄
Rough opening	in.	39³/ ₈ x 101
Daylight area (upper section)	in.	30 x 53 ¹ / ₄
Daylight area (lower section)	in.	30 x 28 ³ / ₄
Ventilation area (upper section)	sq. ft.	22.5
Ventilation area (flap)	sq. in.	36.7
Net wt (w/ Lam. glass)	lbs.	160



casement Window Opening Specifications - Teplacement of Galole window

Clear Open Clear Open Clear Open Straight Arm Spit Arm			e e			21 0-						10	1 6	716	لدع	1		1	
Straight Arm Sqirk Arm S			proper.		-		_	_	Position			1						Cont.	
Sq. Ft. (m²) Sq. Ft. (m³) Inches (mm) Inches (mm) Inches (mm) Sq. Ft. (m²) Lineal Ft. (mm) Sq. Ft. (m²) Sq. Ft. (m²) Inches (mm) Sq. Ft. (m²) 4.9 (455) 4.0 (372) 22 ½ ½ 567) 18 ½ (475) 31 ½ ½ (789) 15.6 (1.449) 20° 6 ½ (6258) 9.8 (910) 9.6 (892) 48 ½ (1238) 21.1 (1.962) 2.7 (1.	Clea	r Opg.	WELL SEE				100000000000000000000000000000000000000		1			200000	000000000000000000000000000000000000000			1000 000	- CONTRACTOR	2570/18/07/08	
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	Straig	ght Arm	200		200000		0.000					5 20		1					
1.5 1.5 1.5 1.5 1.6	Sq. Ft.	(m ²)	Sq. Ft.	(m ²)	Inches	(mm)			Inches (mm)	Sq. Ft. (m ²)	Lineal Ft. (mm)	Sq. Ft.	(m ²)	Sq. Ft.	_(m²)	Inches	(mm)	Sq. Ft.	(m ²)
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	4.9	(.455)	4.0	(.372)	22 9/16"	(567)	18 11/16"	(475)	31_1/16" (789)	15.6 (1.449)	20' 6 3/8" (6258)	9.8	(.910)	9.6	(.892)		(1238)	21.1	(1.962)
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	- 5.7	(.530)	5.1	(.474)			20"	(508)	36 ³ / ₈ " (924)	18.0 (1.672)	22' 1 ⁷ / ₈ " (6753)	11.4	(1.059)	11.1	(1.031)		(1114)	24.0	(2.228)
8.6 (.799) 7.6 (.706) $29 \frac{9}{16}$ (.657) 20° (.658) 55° (.1297) $2.7.6$ (2.564) 29.6 (.8690) 17.2 (1.598) 16.7 (1.551) $24 \frac{19}{16}$ (.630) 35.2 (3.269) 4.2 (3.88) 3.5 (3.30) $25 \frac{11}{16}$ (.653) $21 \frac{19}{16}$ (.653) $21 \frac{19}{16}$ (.654) $23 \frac{9}{16}$ (.659) 5.9 (.442) 9° (.2696) (.2896) 4.2 (3.88) 4.1 (3.80) $55 \frac{9}{16}$ (1.432) $6.5 \frac{9}{16}$ (1.432) $6.5 \frac{9}{16}$ (.442) 9° (.2696) 9° (.2692) 9° (.2692) 9° (.551) 9° (.650) 9° (.442) 9° (.2692) 9° (.2692) 9° (.551) 9° (.650) 9° (.442) 9° (.2692)	6.0	(.632)	6.0	(.557)			20"	(508)	43 1/8" (1095)	21.6 (2.007)	24' 6 ⁵ / ₈ " (7483)	13.6	(1.263)	13.1	(1.217)	36 11/16"	(932)	28.2	(2.621)
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	7.5	(.697)	6.7	(.622)	22 9/16"	(567)	20"	(508)	47 15/16" (1218)	24.0 (2.230)	26' 1 ⁷ / ₈ " (7972)	15.0	(1.394)	14.6	(1.356)	31 7/8"	(810)	31.0	(2.883)
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	8.6	(.799)	7.6	(.706)	22 9/16"	(567)	20"	(508)		27.6 (2.564)	28' 6 ¹ / _{8"} (8690)	17.2	(1.598)	16.7	(1.551)	24 13/16"	(630)	35.2	(3.269)
6.4 $(.596)$ 5.4 $(.505)$ 5.5 $(.507)$ 26 $(.507)$ 25 $(.507)$ 26 $(.507)$ 25 $(.507)$ 26 $(.507)$ 27 $(.507)$ 27 $(.507)$ 27 $(.507)$ 28 $(.507)$ 29	4.2	(.388)	3.5	(.330)	25 11/16"	(653)			23 7/16" (595)	4.4 (.412)	9' 6" (2896)	4.2	(.388)	4.1	(.380)	56 ³ / ₈ "	(1432)	6.2	(.577)
7.7 (715) 6.5 (607) $25^{11}/_{16}^{*}$ (653) $21^{13}/_{16}^{*}$ (654) $43^{1}/_{16}^{*}$ (1095) 8.1 (755) $12^{19}9^{1}/_{16}^{*}$ (3901) 7.7 (715) 7.6 (703) $36^{11}/_{16}^{*}$ (932) 10.5 (975) 8.6 (795) 8.6 (795) 7.3 (674) $25^{11}/_{16}^{*}$ (653) $21^{13}/_{16}^{*}$ (554) $47^{1}/_{16}^{*}$ (1218) 9.0 (839) 13 7 $1/_{16}^{*}$ (1415) 8.6 (795) 8.4 (781) 31 $1/_{16}^{*}$ (810) 11.6 (1.073) 9.8 (912) 8.3 (774) $25^{11}/_{16}^{*}$ (653) $21^{13}/_{16}^{*}$ (554) 55^{*} (1397) 10.4 (963) $11^{9}9^{*}/_{16}^{*}$ (4511) 9.8 (912) 9.7 (897) 10.5 (978) 19 $1/_{16}^{*}$ (630) 13.1 (1.217) 10.7 (993) 9.1 (843) $25^{11}/_{16}^{*}$ (653) $21^{13}/_{16}^{*}$ (554) $59^{1}/_{16}^{*}$ (1522) 11.3 (1.049) 15 7 $1/_{16}^{*}$ (4551) 10.7 (993) 10.5 (978) 19 $1/_{16}^{*}$ (305) 14.2 (1.317) 12.0 (1.111) 10.1 (942) $25^{11}/_{16}^{*}$ (653) $21^{13}/_{16}^{*}$ (554) 47^{*} (478) 11.7 (1.088) 21.7 $1/_{16}^{*}$ (554) 11.7 (1.088) 11.7 (1.	5.5	(.515)	4.7	(.437)	25 11/16"	(653)	21 13/16"	(554)		5.9 (.544)	10' 9 5/8" (3292)	5.5	(.515)	5.4	(.505)	48 3/4"	(1238)	7.9	(.730)
8.6 $(.795)$ 7.3 $(.674)$ 25 ${}^{11}/_{16}{}^{**}$ (653) 21 ${}^{11}/_{16}{}^{**}$ (554) 47 ${}^{15}/_{16}{}^{**}$ (1218) 9.0 $(.839)$ 13 7 13 7 (4145) 8.6 $(.795)$ 8.4 $(.781)$ 31 ${}^{7}/_{8}{}^{**}$ (810) 11.6 (1.073) 9.8 $(.912)$ 8.3 $(.774)$ 25 ${}^{11}/_{16}{}^{**}$ (653) 21 ${}^{11}/_{16}{}^{**}$ (554) 55 ** (1397) 10.4 $(.963)$ 14 9 2 ** (4511) 9.8 $(.912)$ 9.7 $(.897)$ 24 ${}^{13}/_{16}{}^{**}$ (630) 13.1 (1.217) 10.7 $(.993)$ 9.1 $(.843)$ 25 ${}^{11}/_{16}{}^{**}$ (653) 21 ${}^{11}/_{16}{}^{**}$ (554) 59 ${}^{15}/_{16}{}^{**}$ (1522) 11.3 $(.049)$ 15 7 2 7 (4755) 10.7 $(.993)$ 10.5 $(.978)$ 19 ${}^{7}/_{18}{}^{**}$ (650) 14.2 (1.317) 12.0 (1.111) 10.1 $(.942)$ 25 ${}^{11}/_{16}{}^{**}$ (653) 21 ${}^{11}/_{16}{}^{**}$ (554) 67 ** (1702) 12.6 (1.172) 16 9 5 ${}^{/*}$ (5594) 11.1 (1.030) 10.9 (1.010) 48 ${}^{7}/_{16}{}^{**}$ (325) 15.7 (1.461) 55 $(.515)$ 4.7 $(.437)$ 25 ${}^{11}/_{16}{}^{**}$ (653) 21 ${}^{11}/_{16}{}^{**}$ (554) 35 ${}^{15}/_{16}{}^{**}$ (1912) 13.6 (1.259) 23 2 ${}^{13}/_{16}{}^{**}$ (7011) 12.8 (1.191) 12.6 (1.170) 43 ${}^{7}/_{16}{}^{**}$ (1114) 17.8 (1.652) 7.7 $(.715)$ 6.5 $(.607)$ 25 ${}^{11}/_{16}{}^{**}$ (653) 21 ${}^{11}/_{16}{}^{**}$ (554) 43 ${}^{1}/_{16}{}^{**}$ (1195) 16.3 (1.510) 25 ${}^{17}/_{16}{}^{**}$ (8021) 17.1 (1.688) 21.5 (1.430) 15.1 (1.405) 36 ${}^{11}/_{16}{}^{**}$ (9122) 3.3 $(.774)$ 25 ${}^{11}/_{16}{}^{**}$ (653) 21 ${}^{11}/_{16}{}^{**}$ (554) 43 ${}^{1}/_{16}{}^{**}$ (1195) 16.3 (1.510) 25 ${}^{17}/_{16}{}^{**}$ (1303) 15.4 (1.430) 15.1 (1.405) 36 ${}^{11}/_{16}{}^{**}$ (1114) 17.8 (1.652) 37.7 $(.715)$ 3.6 $(.697)$ 3.6 $(.697)$ 3.7 $(.676)$ 3.2 $(.714)$ 25 $(.7$	6.4	(.596)	5.4	(.505)	25 11/16"	(653)	21 13/16"	(554)	35 15/16" (913)	6.8 (.629)	11' 7 1/4" (3536)	6.4	(.596)	6.3	(.585)		(1114)	8.9	(.829)
9.8 (912) 8.3 (.774) 25 11 / _{16*} (653) 21 13 / _{16*} (554) 55 10 (1397) 10.4 (.963) 14 1 9 9 / ₈ (4511) 9.8 (.912) 9.7 (.897) 24 13 / _{16*} (630) 13.1 (1.217) 10.7 (.993) 9.1 (.843) 25 11 / _{16*} (653) 21 13 / _{16*} (554) 59 15 / _{16*} (1522) 11.3 (1.049) 15 7 7 1 / ₈ (4755) 10.7 (.993) 10.5 (.978) 19 7 / _{8*} (505) 14.2 (1.317) 12.0 (1.111) 10.1 (.942) 25 11 / _{16*} (653) 21 13 / _{16*} (554) 31 13 / _{16*} (555) 4.7 (.437) 25 11 / _{16*} (653) 21 13 / _{16*} (554) 35 15 / _{16*} (913) 13.6 (1.259) 23 12 2 13 / _{16*} (7071) 12.8 (1.191) 12.6 (1.170) 43 7 / _{16*} (1114) 17.8 (1.652) 17.7 (.715) 6.5 (.607) 25 13 / _{16*} (653) 21 13 / _{16*} (554) 43 16 / _{8*} (1198) 16.3 (1.510) 25 7 1 / _{4*} (7803) 15.4 (1.430) 15.1 (1.405) 36 11 / _{16*} (932) 20.9 (1.943) 18.6 (.795) 73 (.674) 25 11 / _{16*} (653) 21 13 / _{16*} (554) 43 16 / _{8*} (1218) 18.1 (1.678) 27 27 / ₈ (8291) 17.1 (1.589) 16.8 (1.563) 31 17 / _{8*} (810) 23.0 (2.138) 19.8 (.795) 83 (.912) 83 (.774) 25 11 / _{16*} (653) 21 13 / _{16*} (657) 35 13 / _{16*} (657) 35 13 / _{16*} (657) 35 13 / _{16*} (657) 37 13 / _{16*} (1218) 18.1 (1.678) 27 27 / _{16*} (8291) 17.1 (1.589) 16.8 (1.563) 31 17 / _{16*} (810) 23.0 (2.138) 19.8 (1.794) 27 13 / _{16*} (130) 13.0 (1.281) 19.8 (1.1078) 19.8 (1.1078) 19.7 (1.1078) 19.7 (1.1078) 19.7 (1.1078) 19.7 (1.1078) 19.7 (1.1079) 19.8 (1.1079) 19.8 (1.1078) 19.8 (1.1078) 19.8 (1.1078) 19.9 (1.1088) 19.9 (1.1088) 19.9 (1.1088) 19.9 (1.1088) 19.9 (1.108	7.7	(.715)	6.5	(.607)	25 11/16"	(653)	21 13/16"	(554)	43 1/3" (1095)	8.1 (.755)	12' 9 ⁵ / ₈ " (3901)	7.7	(.715)	7.6	(.703)	36 11/16"	(932)	10.5	(.975)
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	8.6	(.795)	7.3	(.674)	25 11/16"	(653)	21 13/16"	(554)	47 15/16" (1218)	9.0 (.839)	13' 7 1/4" (4145)	8.6	(.795)	8.4	(.781)	31 7/8"	(810)	11.6	(1.073)
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	9.8.	(.912)	8.3	(.774)	25 11/16"	(653)	21 13/16"	(554)	55" (1397)	10.4 (.963)	14' 9 5/8" (4511)	9.8	(.912)	9.7	(.897)	24 13/16"	(630)	13.1	(1.217)
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	10.7	(.993)	9.1	(.843)	25 11/16"	(653)	21 13/16"	(554)	59 15/16" (1522)	11.3 (1.049)	15' 7 1/4" (4755)	10.7	(.993)	10.5	(.978)		(505)	14.2	(1.317)
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	12.0	(1.111)	10.1	(.942)	25 11/16"	(653)	21 13/16"	(554)	67" (1702)	12.6 (1.172)	16' 9 5/8" (5121)	12.0	(1.111)	11.8	(1.094)	12 13/16"	(325)	15.7	(1.461)
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	5.5	(.515)	4.7	(.437)	25 11/16"	(653)	21 13/16"	(554)	31 1/16" (789)	11.7 (1.088)	21' 7 1/4" (6584)	11.1	(1.030)	10.9	(1.010)	48 3/4"	(1238)	15.7	(1.455)
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	6.4	(.596)	5.4	(.505)	25 11/16	(653)	21 13/16"	(554)	35 15/16" (913)	13.6 (1.259)	23' 2 3/8" (7071)	12.8	(1.191)	12.6	(1.170)		(1114)	17.8	(1.652)
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	7.7	(.715)	6.5	(.607)	25 11/16"	(653)	21 13/16"	(554)	43 1/8" (1095)	16.3 (1.510)	25' 7 1/4" (7803)	15.4	(1.430)	15.1	(1.405)	36 11/16"	(932)	20.9	(1.943)
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	8.6	(.795)	7.3	(.674)			21 13/16"	(554)	47 15/16" (1218)	18.1 (1.678)	27' 2 3/8" (8291)	17.1	(1.589)	16.8	(1.563)	31 7/8"	(810)	23.0	(2.138)
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	9.8	(.912)	8.3	(.774)	25 11/16"	(653)	21 13/16"	(554)	55" (1397)	20.7 (1.925)	29' 7 1/4" (9022)	19.6	(1.823)	19.3 ((1.794)	24 13/16"	(630)	26.1	(2.424)
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	6.5	(.604)	5.6	(.526)	30 1/8"	(765)	26 1/4"	(667)		6.8 (.632)	11' 6 5/16" (3513)	6.5	(.604)	6.1	(.567)	48 3/4"	(1238)	9.0	(.836)
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	7.5	(.697)	6.6	(.613)	30 1/8"	(765)	26 1/4"	(667)	35 15/16" (913)	7.9 (.734)	12' 4 1/16" (3761)	7.5	(.697)	7.0	(.650)	43 7/8"	(1114)	10.2	(.948)
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	9.0	(.836)	7.9	(.734)	30 1/8"	(765)	26 1/4"	(667)	43 1/8" (1095)	9.5 (.883)		9.0	(.836)	8.4	(.780)	36 11/16"	(932)	12.0	(1.115)
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	10.0	(.929)	8.8	(.818)	30 1/8"	(765)	26 1/4"	(667)	47 15/16" (1218)	10.5 (.975)	14' 4 1/16" (4371)	10.0	(.929)	9.4	(.873)	31 1/8"	(810)	13.2	(1.226)
$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$	11.5	(1.068)	4 —	-	30 1/8"	(765)	-	-		12.1 (1.124)	15' 6 13/16" (4729)	11.5	(1.068)	-	-	24 13/16"	(630)	14.9	(1.384)
$\begin{array}{ c c c c c c c c c c c c c c c c c c c$	12.6	(1.171)		-	30 1/8"	(765)	_		59 ¹⁵ / ₁₆ " (1522)	13.1 (1.217)	16' 4 1/16" (4980)	12.6	(1.171)		-		(505)	16.2	(1.505)
$\begin{array}{ c c c c c c c c c c c c c c c c c c c$	14.0	(1.301)	_	_	30 1/8"	(765)	-	-	67" (1702)	14.7 (1.366)	17' 6 13/16" (5339)	14.0	(1.301)	_	-	12 13/16"	(325)	17.9	(1.663)
$\begin{array}{ c c c c c c c c c c c c c c c c c c c$	6.5	(.604)	5.6	(.526)	30 1/8"	(765)	26 1/4"	(667)	31 1/16" (789)	13.6 (1.263)	23' 0 5/8" (7026)	13.0	(1.208)	12.2	(.567)	48 3/4"	(1238)	17.9	(1.661)
10.0 (.932) 8.7 (.811) 30 ½, (765) 26 ½, (667) 47 ½, (1218) 21.0 (1.951) 28 8 ½, (8738) 20.0 (1.858) 18.8 (.567) 31 ½, (810) 26.3 (2.440)	7.5	(.699)	6.5	(.608)	30 1/8"	(765)	26 1/4"	(667)	35 5/16" (913)	15.8 (1.468)	24' 8 1/8" (7522)	15.0	(1.394)	14.0	(.567)			20.3	(1.886)
10.0 (.932) 8.7 (.811) 30 ½, (765) 26 ½, (667) 47 ½, (1218) 21.0 (1.951) 28 8 ½, (8738) 20.0 (1.858) 18.8 (.567) 31 ½, (810) 26.3 (2.440)	9.0	(.838)	7.9	(.730)	30 ½"	(765)	26 1/4"	(667)	43 1/8" (1059)	19.0 (1.765)	27' 0 ⁷ / ₈ " (8252)	18.0	(1.672)	16.8	(.567)	36 11/16"	(932)	23.9	(2.218)
$11.5 (1.069) - - 30 \frac{1}{8} (765) - - 55 (1397) 24.2 (2.248) 31 1 \frac{9}{8} (9490) 23.0 (2.137) - - 24 \frac{13}{16} (630) 29.8 (2.767) (2$	10.0	(.932)	8.7	(.811)	30 1/8"	(765)	26 1/4"	(667)	47 15/16" (1218)	21.0 (1.951)	28' 8 1/8" (8738)	20.0	(1.858)	18.8	(.567)	31 7/8"		26.3	(2.440)
	11.5	(1.069)			30 1/8"	(765)		-	55" (1397)	24.2 (2.248)	31' 1 5/8" (9490)	23.0	(2.137)	=	=	24 13/16"	(630)	29.8	(2.767)

These units meet or exceed the following dimensions: Clear Openable Area of 5.7 sq. ft., Clear Openable Width of 20" and Clear Openable Height of 24, when appropriate hardware (straight arm or split arm) is specified.

NOTE: Floor to sill heights are calculated based upon a structural header height of 6' 10-1/2."

ARM SMALL TOTAL OPENABLE WITH THE PROPRIES OF THE

Picture Square Feet Glass/Unit Area

10000	Class		Overell Unit Asse
		s Area t. (m²)	Overall Unit Area
100	sq. ft		sq. ft. (m²)
the state of	6.8	(.632)	9.0 (.836)
1525	7.8	(.725)	10.2 (.948)
	9.4	(.873)	12.0 (1.115)
At a	10.4	(.966)	13.2 (1.226)
	12.0	(1.115)	14.9 (1.384)
	13.0	(1.208)	16.2 (1.505)
	14.6	(1.356)	17.9 (1.663)
	7.8	(.725)	10.2 (.948)
	9.0	(.836)	11.6 (1.078)
	10.8	(1.003)	13.6 (1.263)
_202	12.1	(1.124)	15.0 (1.394)
iv.	13.8	(1.282)	17.0 (1.579)
	15.1	(1.403)	18.4 (1.709)
14	16.8	(1.561)	20.4 (1.895)
la l	9.4	(.873)	12.0 (1.115)
\$4.50 m	10.8	(1.003)	13.6 (1.263)
mattery .	13.0	(1.208)	16.0 (1.486)
E.	14.5	(1.347)	17.6 (1.635)
Estate .	16.6	(1.542)	20.0 (1.858)
	18.1	(1.682)	21.6 (2.007)
5029Nz	20.2	(1.877)	24.0 (2.230)
	10.4	(.966)	13.2 (1.226)
2.65	12.1	(1.124)	15.0 (1.394)

SOLITA 6-4 Transom Square Feet Glass/Unit Area

	Glass Area	Overall Unit Area	
Henri Plefenioner	sq. ft. (m²)	sq. ft. (m ²)	
94546	14.5 (1.347)	17.6 (1.635)	
#12KS#157	16.1 (1.496)	19.4 (1.802)	
estano.	18.4 (1.709)	22.0 (2.044)	
BALLY SEE	20.1 (1.867)	23.8 (2.211)	
111160	22.4 (2.081)	26.4 (2.453)	
rSjeres	12.0 (1.115)	14.9 (1.384)	
talinaka)	13.8 (1.282)	17.0 (1.579)	
2556400	16.6 (1.542)	20.0 (1.858)	
esions.	18.4 (1.709)	22.0 (2.044)	
(2.5(r/ 5)()	21.1 (1.960)	24.9 (2.313)	
aps., region.	23.0 (2.137)	26.9 (2.499)	
(*************************************	25.7 (2.388)	29.9 (2.778)	
15/500)	13.0 (1.208)	16.2 (1.505)	
15-6-95	15.1 (1.403)	18.4 (1.709)	
641/240	18.1 (1.682)	21.6 (2.007)	1
101705	20.1 (1.867)	23.8 (2.211)	17
150000	23.0 (2.137)	26.9 (2.499)	
cargory	14.6 (1.356)	17.9 (1.663)	,
PRIS.	16.8 (1.561)	20.4 (1.895)	-/
319 H.	20.2 (1.877)	24.0 (2.230)	/
产业性	22.4 (2.081)	26.4 (2.453)	/
#1013 M	25.7 (2.388)	29.9 (2.778)	٠,

	Glass	Area	Overal	Unit Area
Khite (rigera hiz)	sq. ft.	(m ²)	sq. ft.	(m ²)
	0.7	(.065)	1.4	(.130)
	0.8	(.074)	1.7	(.158)
	1.0	(.093)	2.0	(.186)
	1.2	(.111)	2.4	(.223)
	1.4	(.130)	2.6	(.242)
(0.91 th 20-10)	1.6	(.149)	3.0	(.279)
SELECTION.	1.5	(.139)	2.8	(.260)
graduti.	1.8	(.167)	3.4	(.316)
regular et au	2.2	(.204)	4.0	(.372)
of high thy	2.6	(.242)	4.7	(.437)
et li	2.9	(.269)	5.2	(.483)
#25 (con	3.4	(.316)	6.0	(.557)
126/7 C.16044	3.4	(.316)	6.0	(.557)
F-70-17	4.0	(.372)	7.1	(.660)
30(a) (ii)	1.8	(.167)	3.4	(.316)
रेशर १५	2.4	(.223)	4.4	(.409)
Graph 1	2.8	(.260)	5.0	(.465)
r to	3.0	(.279)	5.4	(.502)

JUN 20 2008

21 June 2008

O: GOVIE BOURQUE

GONE - PER YOUR REQUEST.

() UPON CONSULT W/SHAWN WASON OF

QUALITY INSULATION ME STATES.

"YOU CAN EASILY BET R-38 IN A

7X6 CAUTTY SPALED 16 O.C. I WOULD

USE K-WOOL REFERETORY INSULATION

HOD IN W/A NYLON NETTING.

(2) DRAWINGS ATTACHED.

(1) ZAD PESUR BORM FIRE SEP. DETAL (#17)

FLOOR BADAIN UNIT 17.

SSF COCHTHOG CUTS FOR GRAY ST 2-8WX3-6HI

6 ABLE END EGRESS WINDOW,


1 CHAROS CUTS FOR EXISTING 3RD FLOWR

SKYLIGHT W/MECHANISMS. SIZED 30"WX 36"H

NORMS A FULL 25" OR 90"

GAZIANE IRANIA MOILLIEN INDOCALE I.O.D.

JUN 20 2000




4

A SO GRAY ST.

Fire Rated
Exterior wall
Exterior wall MEE WALL C Rayon 6-6 FUNG < CATE CONGRESSA LURTAN CENTUR Ht-8-GATE Beam Be

KNEE WAIT - AND 61

HUDON ANDPOP



Frong UIEW OF BUILT UP BEAM

