CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400



NOTICE OF VIOLATION AND ORDER TO CORRECT

	April 21, 2017	EMITIL TO I padans 10 maine
Responsible Party 1: Doering Ralph 18 MT VERNON ST #1 BOSTON, MA 02108	MATL	Responsible Party 1: PETER ADAMS 215 STATES 1 75 7 Congress ST PORTLAND, ME 0410 P
Location III STATE ST	CBL 045 B029001	Inspection Date 4/3/2017
Inspector Dean Berry	Inspection Type FP Routine Inspection	Status Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 5/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101-31.3.4.1.1 FIRE ALARM SYSTEM<11 UNITS OR ><3 STORIES>; Apartment buildings four or more stories in height or with more than 11 dwelling units, other than those meeting the requirements of 31.3.4.1.2, shall be provided with a fire alarm system in accordance with Section 9.6, except as modified by 31.3.4.2 through 31.3.4.6. Building Rep said the owners are aware and working on it.	11/15/17
NFPA 101- 31.2.9 EMERGENCY LIGHTS REQUIRED; Emergency lighting in accordance with section 7.9 shall be provided in all buildings four or more stories in height or with more than 12 dwelling units, unless every dwelling unit has a direct exit to the outside of the building at grade level.	
NFPA 101- 7.2.1.8.1 DOORS SHALL BE SELF-CLOSING & SELF-LATCHING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise specified by 7.2.1.8.3. Several of the old style fire doors do not close fully and none latch. Include the rear staircase and Boiler room doors.	11/15/17
NFPA 101- 7.2.1.8.1 FIRE DOORS BLOCKED OPEN; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise permitted by 7.2.1.8.3. Laundry room. This door is also an older style that does not close properly and non latchling.	11/15/17
NFPA 70 LABEL ALL ELECTRICAL PANELS; Refer to NFPA 70 for requirements regarding labeling of all electrical panels.	

Violation	
	Proposed Date of Completion
NFPA 70- 4.10.8 DEFECTIVE LIGHT FIXTURE; Luminaries shall be installed such that the connections between the luminaire conductors and the circuit conductors can be inspected without requiring the disconnection of any part of the wiring unless the luminaries are connected by attachment plugs and receptacles. Basement lighing in electric panel room has been installed improperly and wiring is exposed.	1/15/17
operating condition shall be repaired or replaced without delay. Basement Laundry Rear stairs	11/15/17
NFPA 101-31.3.4.1.1 FIRE ALARM SYSTEM REQUIRED; Apartment buildings four or more stories in height or with more than 11 dwelling units, other than those meeting the requirements of 31.3.4.1.2, shall be provided with a fire alarm system in accordance with Section 9.6, except as modified by 31.3.4.2 through 31.3.4.5.	10/15/17
NFPA 101-7.9.3 EMERGENCY LIGHTS REQUIRE MAINTENANCE: 7.9.3 Periodic Testing of Emergency Equipment 7.9.3.1 Required emergency lighting systems shall be tested in accordance with one of the three options offered by 7.9.3.1.1, 7.9.3.1.2, or 7.9.3.1.3. 7.9.3.1.1 Functional testing shall be conducted monthly with a minimum of 3 weeks and a maximum of 5 weeks between tests, for not less than 30 seconds, except as otherwise permitted by 7.9.3.1.1(2). (2) The test interval shall be permitted to be extended beyond 30 days with the approval of the authority having jurisdiction. (3) Functional testing shall be conducted annually or a minimum 1-1/2 hours if the emergency lighting system is battery powered. (4) The emergency lighting equipment shall be fully operational for the duration of the test required by 1.9.3.1.1(1) and (3). (5) Written records of visual inspections and tests shall be kept by the winer for inspection by the authority having jurisdiction.	
IFPA 101-7.10.9 TESTING AND MAINTENANCE EXIT SIGNS REQUIRE MAINTENANCE; .10.9.1 Inspections. Exit signs shall be visually inspected for operation of the illumination ources at intervals not to exceed 30 days. 7.10.9.2 Testing. Exit signs connected to, or owered with, a battery-operated emergency illumination source shall be tested and haintained in accordance with 7.9.3. 7.9.3 Periodic Testing of Emergency Equipment 7.9.3.1 required emergency lighting systems shall be tested in accordance with one of the three ptions offered by 7.9.3.1.1, 7.9.3.1.2, or 7.9.3.1.3. 7.9.3.1.1 Testing of required emergency ghting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted monthly with a minimum of 3 weeks and a maximum of 5 weeks between tests, for ot less than 30 seconds, except as otherwise permitted by 7.9.3.1.1(2). (2) The test interval hall be permitted to be extended beyond 30 days with the approval of the authority having misdiction. (3) Functional testing shall be conducted annually for a minimum 1-1/2 hours if the emergency lighting system is battery powered. (4) The emergency lighting equipment mall be folly operational for the duration of the test required by 7.9.3.1.1(1) and (3). (5) — Interval priority having jurisdiction.	11 13/17
INAL DATE OF COMPLETED VIOLATION(S)	11/15/17
IRE PREVENTION BUREAU RE-INSPECTION OF COMPLETED VIOLATION(S)	11/15/17

The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any

VIOLATOR CERTIFICATION

I agree to remedy the violations listed within the timeframes provided. If I require additional time to comply, I understand that I must contact the Fire Prevention Bureau prior to the deadline to request an extension, which is entirely within the Bureau's discretion to grant or deny.

I further understand that it is my responsibility to schedule a reinspection of my property once the violations have been remedied to do so. My failure to schedule a reinspection shall be deemed an admission that the violations have not been remedied.

If I fail to comply with this agreement, Portland Code of Ordinances §§ 1-15 action.	I understand that I am liable for penalties pursuant to the City of and 10-25, and 30-A M.R.S. § 4452 and may be subject to further legal
Date 5/5/12	Responsible Party
Date	Responsible Party

SEEN AND AGREED

Date

		·	
			•
1			
			•