### Portland, Maine



### Yes, Life's good here.

August 17, 2015

**BALDWIN MARTINA M** 

1231 FOREST AVE

PORTLAND, ME 04103

CBL: 052 H008001

Located at 168 WASHBURN AVE

#### NOTICE OF INTENT TO PROSECUTE

Dear Owner/Manager/Occupant,

An inspection of the property located at the address referenced above revealed that the structure and premises fail to comply with NFPA 2009 Fire Code and/or NFPA Life Safety Codes. Attached is a list of those violations.

The above-referenced property is in violation of the Chapter 10, Fire Prevention and Protection, Article 1 of the Portland City Code (the "Code") and National Fire Protection Association (NFPA) 101 Life Safety Code. Please note that the Code is available online at www.portlandmaine.gov.

This is a notice of intent to prosecute. As such, the matter is being referred to the City of Portland Corporation Council for legal action and possible civil penalties as provided for in Chapter 10, Fire Prevention and Protection, 10-25 of the Code and in Title 30- A.M.R.S.A. 4452.

Please be advised that you will need to contact the Fire Prevention Bureau at 207-874-8400 before the court date on the attached Reference to Court letter to either schedule a re-inspection or to submit a plan of action to correct these violations.

Sincerely,

Portland Fire Department

AC Wich Santisan

Fire Prevention Bureau

# CITY OF PORTLAND PORTLAND FIRE DEPARTMENT

380 Congress Street Portland, Maine 04101

## **Inspection Violations**

Owner/Manager BALDWIN MARTINA M			Inspector Christopher Goodall Status		Inspection Date 8/14/2015			
Location CBL 168 WASHBURN AVE 052 H008001		Inspection Type						
				Yellow 5-9 Violations		Fire Company-FP Routine Inspec		
Code		Int/Ext	Floor	Unit No. 🛭	\rea	Compliance Date		
1) 2.125								
Violation:			.3.3.2 HOL	E IN CEILING N	NEEDS REPA	AIR; InteriorWall and		
	Ceiling Finish Interior walls and ceiling finish materials complying with 10.2 shall be permitted as follows:  1) Exit encloures Class A or class B  2) Lobbies and corridorsClass A or Class B							
	3) other spa	aces Clas	s A, orClas	ss B, or Class C				
Notes:	STAIRWELL OF 168 SIDE SECOND FLOOR LANDING							
2) 9.002								
	door assemblies that are installed in fire-rated floor-ceiling or roof-ceiling assemblies that have been tested in accordance with the methods described in NFPA 288. The listing indicates the fire-rated assembly and the hourly rating (3 hours, 2 hours, 1.5 hours, 1 hour, 75 hours) for which the door can be permitted to be used so that access to the space above the ceiling or to the floor above can be provided without adversely affecting the fire resistance rating of the entire assembly. The listing provides limitations on the maximum size of an individual door opening and the total area of all door openings permitted for each 100 square feet of floor or ceiling.							
Notes:	FRONT AND REAR STAIRWELLS SECOND FLOOR, FIRST FLOOR REAR STAIRWELL							
3) 3.011								
Violation:	NFPA 101- 31.3.2.1.1 BOILER PROTECTION REQUIRED; THE AREAS DESCRIBED IN TABLE 31.3.2.1.1 SHALL BE PROTECTED AS INDICATED: BOILER AND FUEL-FIRED HEATER ROOMS SERVING MORE THAN A SINGLE DWELLING UNIT (MINIMUM SEPARATION/PROTECTION IS 1 HOUR OR SPRINKLERS)							
Notes:	NO BOILER PROTECTION FOR FURNACE IN BASEMENT							
4) 55.229								
Violation:	NFPA 101- 31.3.3.2 INTERIOR FINISH FOR EXITS AND ENCLOSURES; INTERIOR WALL AND CEILING FINISH MATERIALS COMPLYING WITH 10.2 SHALL BE PERMITTED AS FOLLOWS: EXIT ENCLOSURES- CLASS A OR CLASS B							
Notes:	PANELING IN STAIRWELLS AND LANDINGS IN FRONT STARIWELL FOR #168							

# CITY OF PORTLAND PORTLAND FIRE DEPARTMENT

380 Congress Street Portland, Maine 04101

## **Inspection Violations**

Owner/Manager		Inspector	Inspection Date
BALDWIN MARTINA M		Christopher Goodall 8/14/2015	
Location	CBL	Status	Inspection Type
168 WASHBURN AVE	052 H008001	Yellow 5-9 Violations	Fire Company-FP Routine Inspec

5) 1.120

Violation:

NFPA 101- 7.5.1.1 AND 7.5.1.1.1 OBSTRUCTED EGRESS; Exits shall be located and exit access

shall be arranged so that exits are readily accesible at all times (7.5.1.1).

Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in

7.5.1.1.3 and 7.5.1.1.4 (7.5.1.1.1).

Notes:

STORAGE OF ITEMS IN FIRST FLOOR REAR HALLWAY

Comments:

DISTRICT COURT Location: Portland Docket No.

CITY OF PORTLAND and body politic and Corporate, located in the County of Cumberland and State of Maine,

Plantiff,

FIRE PREVENTION AND PROTECTION CODE VIOLATION

(M.R. CIV. P. 80H AND 80k)

v.

Martina M. Baldwin Defendant

SUMMONS NUMBER:

354881

This matter has been referred to the Corporation Counsel's Office for immediate legal action with respect to the code violations detailed in the attached letter. It has been assigned the above summons number and will be filed with the Portland District Court and will be assigned for an initial appearance at the Portland District Court 205 Newbury Street Portland, Maine 04101 at 8:30 A.M. on 09/14/2015. I strongly urge you to contact Victoria Meserve at Fire Prevention at (207)-874-8400 or via e-mail at <a href="mailto:meservev@portlandmaine.gov">meservev@portlandmaine.gov</a> to set up an inperson meeting to resolve these issues or make alternative arrangements to relieve you of the requirement to appear in Court on 09/14/2015.

Dated: 8/19/15

Adam R. Lee, Esq. Bar No. 4143

Associate Corporation Council

City of Portland 389 Congress St

Portland, ME 04101

207-874-8480