

Helen Donaldson <hcd@portlandmaine.gov>

## **D** Street

Tom Errico <thomas.errico@tylin.com>

Tue, Feb 26, 2019 at 2:41 PM

To: Michael Tremblay <mtremblay@portlandmaine.gov>

Cc: Bruce Hyman <a href="https://example.com/shiften-bonaldson">https://example.com/shiften-bonaldson</a> <a href="https://example.com/shiften-bonaldson">ht

Nell – the following is a summary of traffic signal design comments.

- The mast arm located on the southeast corner is labeled as a "Proposed 12' Pedestal Pole". This shall be corrected.
- I do not support the location of the utility pole in the flare of the sidewalk ramp located on the southeast corner.
- Although the MUTCD does not specifically note standards for cone of vision for pedestrian signal heads, it is suggested that they be located as close as practicable to a pedestrian looking directly in line with the crosswalk.
- The Applicant shall confirm that all equipment will be located within the public right-of-way. A summary of construction impacts to private property should be noted.
- The mast arm on the northwest corner should be depicted.
- A pedestrian signal head for crossing St. John Street should be depicted on the northeast corner mast arm.
- The Applicant should document that the push buttons meet MUTCD requirements for accessibility and separation.

If you have any questions, please contact me.

Best regards,

Thomas A. Errico, PE
Senior Associate
Traffic Engineering Director
TYLININTERNATIONAL

12 Northbrook Drive

Falmouth, ME 04105

- +1.207.781.4721 main
- +1.207.347.4354 direct
- +1.207.400.0719 mobile
- +1.207.781.4753 fax

thomas.errico@tylin.com

Visit us online at www.tylin.com

Twitter | Facebook | LinkedIn | Google+