



Helen Donaldson <hcd@portlandmaine.gov>

---

## MMC Drawings

---

**Jeremiah Bartlett** <jbartlett@portlandmaine.gov>

Tue, Dec 11, 2018 at 1:31 PM

To: "Donaldson, Helen" <hcd@portlandmaine.gov>

Cc: Bruce Hyman <bhyman@portlandmaine.gov>, Keith Gray <kgray@portlandmaine.gov>, "Thomas.Errico@tylin.com" <thomas.errico@tylin.com>

The earliest I can likely be there is 11:45, unfortunately.

I have looked at the memo, and offer the following:

Comment 5: I do recommend monitoring of Congress at Gilman post occupancy to see what the crash situation is.

Comment 6: I do recommend monitoring of A St. at St. John post occupancy to see what the crash situation is.

I remain concerned and focused on examinations of the street network near the access points to the campus in the Bramhall area, but am of the understanding that this is to be addressed as part of other plan and permitting requirements.

Thank you,  
Jeremiah

Jeremiah J. Bartlett, PE, PTOE, IMSA II  
Transportation Systems Engineer  
Department of Public Works  
212 Canco Road, Suite B  
Portland, Maine 04103  
[jbartlett@portlandmaine.gov](mailto:jbartlett@portlandmaine.gov)  
(207) 874-8891

[Quoted text hidden]