## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

March 16, 2018

HARRIS PROPERTIES PO BOX 1216 PORTLAND ME 04104

Location	CBL	<b>Inspection Date</b>
16 WEYMOUTH ST	053 1010001	2/14/2018
Inspector	Inspection Type	Status
Alan Bouchard	FP Routine Inspection	Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 4/15/2018.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
<b>NFPA 101- 7.2.1.15.8 FIRE DOOR ASSEMBLY REQ REPAIR</b> ; Door openings not in proper operating condition shall be repaired or replaced without delay. closer not operational for apartment #1,2,4	//
<b>NFPA 101-7.2.4.3.1 FIRE BARRIER REQUIRES MAINTENANCE</b> ; Fire barriers separating buildings or areas between which there are horizontal exits shall have a minimum 2-hour fire resistance rating, unless otherwise provided in 7.2.4.4.1, and shall provide a separation that is continuous to the finished grounded level. second floor rear hallway	//
<b>NFPA 101- 31.3.1.1.1 VERTICAL OPENINGS NOT FIRE RATED</b> ; Vertical openings shall be enclosed or protected in accordance with Section 8.6. rear stair attic access not fire rated	//
NFPA 101- 31.3.7 FLOOR/ CEILINGS ASSEMBLY NOT SMOKE-TIGHT; In buildings other than those meeting the requirements of 31.3.7.1, 31.3.7.2, 31.3.7.3, 31.3.7.4, or 31.3.7.5, in addition to the following criteria to be met. apartment 1 and 2 bathroom ceiling needs repair	//
<b>NFPA 101- 7.1.8 STAIR GAURDS MUST BE REPAIRED</b> ; Guards in accordance with 7.2.2.4 shall be provided at the open sides of means of egress that exceed 30 inches above the floor or the finished ground level below. rear stair guard loose, between floor 2 &3, also front stairs loose	//
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.  APT. #2 INOP outside sleeping area	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.

Violation		Proposed Date of Completion
NFPA 1 EXCESSIVE/DISORDERLY S	STORAGE; Reference NFPA 1 for excessive fuel-load.	
basement and outside		//
NFPA 70- 590.6 EXTENSION CORDS; Ground-fault protection for personnel for all temporary wiring installations shall be provided to comply with 590.6(A) and (B). This section shall apply only to temporary wiring installations used to supply temporary power to equipment used by personnel during construction, remodeling, maintenance, repair, or demolition of buildings, structures, equipment, or similar activities.		//
apt. 2 has extesion from hall to front sl	eeping area, apt. 3 has cord powering light fixture	
	DOOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 tical shafts (including stairways, exits, and refuse our.	//
FINAL DATE OF COMPLETED VIOL	ATION(S)	//
FIRE PREVENTION BUREAU RE-INS	SPECTION OF COMPLETED VIOLATION(S)	//
is entirely within the Bureau's discr I further understand that it is my re have been remedied to do so. My for violations have not been remedied.	Fire Prevention Bureau <u>prior to the deadline</u> to requeretion to grant or deny.  Esponsibility to schedule a reinspection of my properation to schedule a reinspection shall be deemed an entiry of the schedule a reinspection of the deemed and that I am liable for penalties pursua	ty once the violations admission that the
	15 and 10-25, and 30-A M.R.S. § 4452 and may be si	• •
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	