

77 CARLETON ST.
2ND FLOOR FLOOR JOISTS
LAYOUT

NOT WORKING ON THIS SIDE OF
HOUSE



☒ = STRUOBO POSTS
= 2x12 LVL - DOUBLE END UNDER 20MM YK6

SCALE
H
1/4" = 1'