CITY OF PORTLAND

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
DUBOIS REAL ESTATE MANAGEMENT		Jon Rioux	1/30/2007
Locatation	CBL	Status	Inspection Type
6 WALKER ST	055 D003001	Passed	Complaint-Inspection

	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1)	6-113.4 Violation: Notes:	Interior Extension cords. Remove all zip cords from unit 3		3		03/01/2007
2)	6-108.4 Violation: Notes:	Interior Stairways, stairwells, stairs, porches. Maintain the first and second floor main s	1-3 tairwell hand	drails for stab	Stairways	03/06/2007
3)	6-116.2 Violation: Notes:	Interior Egress Remove the bookcase and material from	14 03/01/2007 rom restricting the front door ingress/ egress in unit fourteen (14.			
4)	6-109.1 Violation: Notes:	Interior Sanitiation/Maintenance of assigned area Maintain unit fifteen (15) in a clean and sa				
5)	6-113.5 Violation: Notes:	Interior Maintenance of lighting fixtures Install a hard-wire smoke detector in unit	fifteen (15)	15		03/01/2007
6)	6-111.4 Violation: Notes:	Interior Maintenance of plumbing fixtures. Maintaine all sink fixtures free from defect	ts and leaks	9 , and in acco	rdance with the	03/01/2007 e state plumbing code
7)	6-113.5 Violation: Notes:	Interior Maintenance of lighting fixtures Install a hard-wire smoke detector in unit	fifteen (15)	9		03/01/2007
8)	6-113.5 Violation: Notes:	Interior Maintenance of lighting fixtures Repair the bathroom exhaust fan to safe of the city	working cond	4 ditions, and ir	n accordance v	03/01/2007 vith the electrical code
9)	6-120.1 thru Violation: Notes:	5 Interior Posted against occupancy. Illegal unit; posted against occupancy		18		03/01/2007

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date	
DUBOIS REAL ESTATE MANAGEMENT		Jon Rioux	1/30/2007	
Locatation	CBL	Status	Inspection Type	
6 WALKER ST	055 D003001	Passed	Complaint-Inspection	

10) 6-108.2 Interior 1 03/01/2007

Violation: Interior floors, walls, ceilings and doors

Notes: Repair the first floor ceiling above the main stairwell

Comments: