## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

August 18, 2017

| Responsible Party 1:   |                           |                              |  |  |
|------------------------|---------------------------|------------------------------|--|--|
| Keezer Terry           |                           |                              |  |  |
| 29 Pine St             |                           |                              |  |  |
| Portland, ME 04102     |                           |                              |  |  |
|                        |                           |                              |  |  |
| Location               | CBL                       | Inspection Date              |  |  |
| Location<br>29 PINE ST | <b>CBL</b><br>055 E012001 | Inspection Date<br>7/28/2017 |  |  |
|                        |                           | _ •                          |  |  |

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 9/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

| Violation   | Proposed Date of Completion  |
|---|--|
| <b>NFPA 101- 7.5.1.1 EXIT OBSTRUCTED</b> ; Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4. storage 2nd floor front stairway  | IMMEDIATELY remove all obstructions from the exits. Your signature below indicates that all obstructions have been removed and will not be replaced. |
| <b>NFPA 70 MISSING BOX COVERS</b> ; Refer to NFPA 70, National Electrical Code, on standards for missing box covers.  2nd floor rear apartment  | //   |
| NFPA 101- 8.3.4.2 60 MINUTE FIRE DOOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 that states fire door assemblies for vertical shafts (including stairways, exits, and refuse chutes) are rated and required for 1 hour. basment Door, and Front hallway apt Door   | //   |
| NFPA 80- ANNEX D.4 1-HOUR FIRE DOORS ASSEMBLIES REQ; Listings are provided for floor fire door assemblies that are installed in fire-rated floor-ceiling or roof-ceiling assemblies that have been tested in accordance with the methods described in NFPA 288. The listing indicates the fire-rated assembly and the hourly rating (3 hours, 2 hours, 1.5 hours, 1 hour, .75 hours) for which the door can be permitted to be used so that access to the space above the ceiling or to the floor above can be provided without adversely affecting the fire resistance rating of the entire assembly. The listing provides limitations on the maximum size of an individual door opening and the total area of all door openings permitted for each 100 square feet of floor or ceiling.  Fire Doors required between common area and basement | //   |

| Violation                    |   | Proposed Date of Completion |
|------------------------------|---|-----------------------------|
| FINAL DATE OF COMPLETE       | D VIOLATION(S)  | · / / /                     |
| FIRE PREVENTION BUREAU       | RE-INSPECTION OF COMPLETED VIOLATION(S)   | //                          |
|                              | t to reject or modify any proposed plan of action, and may nical capacity to complete the proposed plan. Please contact TION                                      | <del>-</del>                |
| understand that I must conta | ons listed within the timeframes provided. If I require add<br>act the Fire Prevention Bureau <u>prior to the deadline</u> to requ's discretion to grant or deny. |                             |
| v                            | is my responsibility to schedule a reinspection of my prope<br>. My failure to schedule a reinspection shall be deemed an<br>nedied.                              | •                           |
|                              | greement, I understand that I am liable for penalties pursurs $\{s, s, s, 1-15\}$ and 10-25, and 30-A M.R.S. $\{s, s, s$         |                             |
| Date                         | Responsible Party   |                             |
| Date                         | Responsible Party   |                             |
| SEEN AND AGREED              |   |                             |

Fire Prevention Bureau

Date