



Portland Fire Department

3/26/2019

KEVIN ROCQUE
31 NEW ISLAND AVE
PEAKS ISLAND, ME 04108
krocque@yahoo.com

KEVIN ROCQUE
31 NEW ISLAND AVE
PEAKS ISLAND, ME 04108
krocque@yahoo.com

CERTIFIED MAIL

RE: 73 EMERY ST
PORTLAND, ME

057 A001001

Page 1 of 2

**NOTICE OF VIOLATION
AND ORDER TO CORRECT**

To Whom it May Concern,

The City of Portland inspected the above-referenced property on 10/17/2017 and found violations of the City of Portland Code of Ordinances, which are listed on the attached page(s). You are hereby ordered to correct these violations by the dates given on the attached.

A reinspection of your property will take place on 4/25/2019 10:00:00AM .

Please contact the Fire Prevention Bureau at 874-8400 if you have any question about your reinspection. If the violations are not corrected at the time of reinspection, you will be charged a \$150 failed reinspection fee.

If you do not correct the attached violations, then this matter may be referred to the City of Portland Corporation Counsel for legal action, including civil penalties and other legal remedies.

Thank you for keeping the City of Portland safe.

Sincerely,

Captain John Brennan
Fire Prevention Bureau
City of Portland

NON-COMPLIANCE VIOLATION LIST

NAME	CODE DESCRIPTION	COMMENTS	Deadline
NFPA 101-8.6	Vertical openings shall be enclosed or protected in accordance with Section 8.6.	3rd floor transom over door needs to be removed.	10/24/2017
NFPA 101-8.6	Vertical openings shall be enclosed or protected in accordance with Section 8.6.	2nd floor extra room off the stairway must be removed or add a 1-hour rated door and detection.	10/24/2017
NFPA 101-8.3.3.3	Fire doors must be self- or auto-closing.		11/16/2017
NFPA 101-9.1.2; NFPA 70	All electrical equipment must comply with the National Electric Code.	Unused electrical boxes in basement should be removed.	11/16/2017
NFPA 101-31.3.4.5; City Code 10-3(i)	Photoelectric, hardwired with battery backup smoke alarms must be provided in every sleeping room, outside every sleeping area, and on every level, including the basement.	IMMEDIATELY install temporary alarms where required. Fully compliant, permanent alarms must be installed by the date given. Additional Detection required in basement and first floor apartment dining/hallway area.	11/16/2017
Portland Code Ch. 10	Buildings must comply with Ch. 10 of the Portland Code of Ordinances.	Excessive storage in the basement	11/27/2017
NFPA 101-31.2.2.1	1-hour fire rated doors and assemblies required, including self-closing and self-latching mechanisms.	Fire doors are required in common areas. Landlord was advised to sheetrock over additional doors will probably require total of 7 doors.	10/17/2018